
		4.1			•
SUNDRY Do not use th	UNITED STATES EPARTMENT OF THE IN UREAU OF LAND MANA NOTICES AND REPO Is form for proposals to II. Use form 3160-3 (API	TERIOR SDEED FIG GENERAL SDEED FIG RTS ON WELLS DE HI drill or to re-enter and HI	eid u obbs	OMB NO	APPROVED D. 1004-0137 nuary 31, 2018 Tribe Name
SUBMIT IN	7. If Unit or CA/Agree	ment, Name and/or No.			
1. Type of Well  Oil Well Gas Well  Otl  2. Name of Operator CIMAREX ENERGY COMPA	Contact:	DAVID A EYLER JUN 1 3	2018	8. Well Name and No. MOBERLY RHOD 9. API Well No. 30-025-12023-0	ES WATERFLOOD PRO
3a. Address 202 S CHEYENNE AVE. SUITE 1000 TULSA, OK 74103  3b. Phone No. (include Cub) V ED Ph: 432-687-3083				10. Field and Pool or Exploratory Area RHODES	
4. Location of Well (Footage, Sec., 7	11. County or Parish, State				
Sec 21 T26S R37E NESW 19	LEA COUNTY, NM				
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF	NOTICE,	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
☑ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☑ Temporarily Abandon ☐ Water Disposal		☐ Water Shut-Off ☐ Well Integrity ☐ Other
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for for SPECIAL ENERGY CORP. REPOLLOWING PROCEDURE PROJECT.  1) POOH LAYING DOWN 2-3	erration: Clearly state all pertiner ally or recomplete horizontally, rk will be performed or provide loperations. If the operation resondonment Notices must be file inal inspection.  ESPECTFULLY REQUES WHILE SEC EVALUATES	nt details, including estimated starting give subsurface locations and measur the Bond No. on file with BLM/BIA. sults in a multiple completion or record only after all requirements, including To TEMPORARILY ABANI	date of any pred and true ve Required sub- npletion in a r ng reclamation	roposed work and approx rtical depths of all pertine sequent reports must be new interval, a Form 3160 n, have been completed a	ent markers and zones. filed within 30 days 0-4 must be filed once and the operator has
2) SET 7" CIBP @ 2,900'; DU	MP BAIL 6 SXS.CMT. @	2,900'-2,865'.			


2,3E1 / CIBP @ 2,900'; DUMP BAIL 6 SXS.CMT. @ 2,900'-2,865'.
3) CIRC. WELL W/ CORROSION INHIBITED FLUID.
4) RIH W/ 1 JT. 2-3/8" TBG. AS KILL STRING X PRES. TEST 7" CSG. X CIBP + CMT. TO 500# AND HOLD 30 MINS.


DURNING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM WITH A STEEL TANK AND HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.

14. I hereby certify that the foregoing is true and correct.  Electronic Submission #422409 verified by the BLM Well Information System  For CIMAREX ENERGY COMPANY OF CO, sent to the Hobbs  Committed to AFMSS for processing by PRISCILLA PEREZ on 06/05/2018 (18PP1162SE)							
Name (Printed/Typed)	DAVID A EYLER	Title	AGENT				
Signature	(Electronic Submission)	Date	06/04/2018				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
/s/ Jonathon Shepard		Title	PE	Lef left 8			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Go				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.







## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.