State of New Mexico Form C-103 Submit 1 Copy To Appropriate District Office Revised July 18, 2013 District I - (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 WELL API NO. District II - (575) 748-1283 30-025-33979 OIL CONSERV 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 STATE 🖂 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe District IV - (505) 476-3460 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELL 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPH DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 1 Hoover 28 PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number ARMSTRONG ENERGY CORPORATION 1092 3. Address of Operator 10. Pool name or Wildcat P.O. BOX 1973, ROSWELL, NM 88202-1973 Vacuum; Drinkard, East 4. Well Location : 1650___ feet from the _ Unit Letter I 330 _ feet from the __ South line and Section 28 Township 17S Range 35E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: \Box PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING | COMMENCE DRILLING OPNS. **TEMPORARILY ABANDON** P AND A \boxtimes INT TO PA **PULL OR ALTER CASING** CASING/CEMENT JOB P&A NR DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 7/2/2018 Move in equipment, rig up and install BOP. Caught circulation and tested casing to 600#. Lost 20# in 10 minutes. Small leak at 331' was isolated by Armstrong before we arrived. Circulated MLF and spotted 25 sx cement on top of existing CIBP at 4758'. POOH to 3004' and spot 25 sx cement. POOH to 1617' and spot 25 sx cement. POOH and SION. Perforate casing at 400'. Establish circulation. Remove BOP and install top flange. Pump cement down 5 ½" casing to perfs at 400' and up 5 ½" X 8 5/8" annulus to surface with 105 sx cement. Rigged down. dug out cellar and cut off wellhead. Cement was to surface in both strings of casing. Installed marker, cut off anchors, cleaned pit and cleared location. Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on Spud Date: Rig Release the OCD web page under forms. Restoration Due By <u>07-03-2019</u> I hereby certify that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** VP – Operations TITLE DATE 7/13/2018 _ PHONE: Kyle Alpers E-mail address: <u>kalpers@aecnm.com</u> Type or print name APPROVED BY: Conditions of Approval (if any):