Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
District 1 - (575) 393-6161 Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OII CONSEDVA NO	368 O	30-025-37122
DISTRICTII - (5/3) 746-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV (505) 476-3460 Santa Fe, NM 87505		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8	7505	STATE FEE 6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Junta 1 0, 1 11/1 0	RECEIVED	o. State on & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name South Vacuum
PROPOSALS.) 1. Type of Well: Oil Well ☐ Gas Well ☒ Other - SWD			8. Well Number 274
2. Name of Operator			9. OGRID Number
Clearwater SWD, LLC			371101
3. Address of Operator P.O. Box 1476, Lovington, NM 88260		10. Pool name or Wildcat SWD; MISS-DEVONIAN 96319	
4. Well Location		SWD, MISS-DEVOITARY 70317	
Unit Letter P: 960 feet from the South line and 693 feet from the East line			
Section 27 Township 18-S Range 35-E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3,887' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM OTHER: Replace suspected dama	aged tubing joint	OTHER:	_
OTHER: Replace suspected damaged tubing joint OTHER: Under the of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
1. R/U pulling unit, nipple down tree. Release packer and pull 4-1/2" duoline plastic lined tubing. Inspect tubing coming out of the hole and replace any damage joints.			
2. GBIH with 4-1/2" duoline plastic lined tubing & coated packer. Set packer at 10,786' (+,-), above Mississippian perforations from 10,858-78', 10.890-900', 10,920-30' and Devonian perfs from 11,760-820', 11,840-900' and 12,300-400'			
3. N/D pulling unit & N/U tree, test annulus to 500 psi for 30 minutes (notify Hobbs OCD office of test). If test holds OK, place well back on SWD operations as per Order SWD-1444.			
[······			
Spud Date:	Rig Release Da	ite:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Lay Contract TITLE President DATE 7/18/2018			
Type or print name <u>Larry Gandy</u> E-mail address: <u>lgandy@gandycorporation.com</u> PHONE: <u>575-394-0555</u> For State Use Only			
Petroleum Engineer			
APPROVED BY: TITLE Petroleum Engineer DATE 07/19/18 Conditions of Approval (if any):			
		•	

