

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
HOPES OCD
OIL CONSERVATION DIVISION
1220 South Santa Fe
Santa Fe, NM 87505
RECEIVED

Form C-103
Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-43695
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator XTO ENERGY, INC		6. State Oil & Gas Lease No. STATE
3. Address of Operator 6401 HOLIDAY HILL RD, BLDG 5, MIDLAND TX 79705		7. Lease Name or Unit Agreement Name CHISTERA 32 STATE
4. Well Location Unit Letter <u>B</u> : <u>217'</u> feet from the <u>NORTH</u> line and <u>1726'</u> feet from the <u>EAST</u> line Section <u>32</u> Township <u>20S</u> Range <u>33E</u> NMPM County <u>LEA</u>		8. Well Number 2H
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3619' GL		9. OGRID Number 5380
		10. Pool name or Wildcat HAT MESA; BONE SPRING

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

XTO Energy, Inc requests permission to revise the casing and cement design as follows:

Casing Type	Fluid Type	Mud Weight	Hole Size	Casing Size	Casing Grade	Casing Weight	Top MD	Setting Depth	Lead Cement	Tail Cement	Total Sks Cement	TOC
Surf	FW/Native	8.3 - 9.5	20	16	H40 STC	64	0	1455	1082	275	1357	0
1st Interm	Brine	9.0-10.3	14.75	11.75	H-40 STC	42	0	3267	911	168	1079	0
2nd Interm	FW/Native	8.3-9.5	10.875	8.625	J-55 LTC	32	0	5032	617	84	702	0
Prod	FW/Cut Brine OBM	8.5 - 10 9.7	7.875 7.875	5.5	P110 BTC	17	0	16035	538	652	1190	4532

Contingencies

1. OBM may be used in production hole if production hole becomes unstable while drilling with WBM

2. DV tool may be set in 1st intermediate between 1500-2200'.

3. DV tool may be set in 2nd intermediate between 3300-3800'

4. If Capitan formation does not have losses, 10-5/8" hole may be drilled as deep as 10,400' w/ FW and 8-5/8" csg w/ be set at said depth. This will not change DV tool depth for 8-5/8" csg. The point of this plan is to drill deeper than the Capitan (if possible) to seal off as many possible lost circulation zones before drilling production hole.

> DVT SET MINIMUM 50' below shoe.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Kardos TITLE Regulatory Coordinator DATE 07/30/2018

Type or print name Kelly Kardos E-mail address: kelly_kardos@xtoenergy.com PHONE: 432-620-4374

For State Use Only

APPROVED BY: Mary Brown TITLE AO/I DATE 8/6/2018
Conditions of Approval (if any)