Submit 1 Copy To Appropriate District Office	State of New Me	rol Docourooc	Form C-103 Revised August 1, 2011	
District I – (575) 393-6161 Energy, Minerals and Natural Resources		WELL API NO.		
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88210 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 0IL CONSERVATION DIVISION District III – (505) 334-6178		30-025-28307		
$\frac{\text{District III}}{\text{District III}} - (505) 334-6178$		5. Indicate Type of Lease STATE FEE		
$\frac{\text{District III} - (505) 334-6178}{\text{District IV} - (505) 476-3460}$ AUG 27 2018 20 South St. Francis Dr. $\frac{1000 \text{ Rio Brazos Rd.}}{\text{Santa Fe, NM 87505}}$		STATE FEE 6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM			o. Blate on te Gas Deuse No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit COOP	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: Injector – CO2/Water		8. Well Number 4		
2. Name of Operator			9. OGRID Number: 157984	
Occidental Permian Ltd.			9. OOKID Number, 197984	
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323			10. Pool name or Wildcat: Hobbs (G/SA)	
4. Well Location (Surface)				
. ,	494feet from the _North line a	and 1025	feet from the East line	
Section 4 Township 19S Range 38E NMPM Lea County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	3626.2' (GL)			
12. Check	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR				
PULL OR ALTER CASING		CASING/CEMEN	т јов	
	er and Recomplete	OTHER:		
	ork). SEE RULE 19.15.7.14 NMAC		d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of	
1) MIRU PU. ND Wellhead.	NU BOP.			
2) POOH with injection equi				
3) Cleanout well to TD (± 440			During this procedure we plan to use	
4) Set CICR at 4000' w/ 350' 2-3/8" fiberglass tailpipe and sqz well w/ \pm 800 sx the closed-loop system w			the closed-loop system with a steel	
 5) Drill out squeeze to TD and prepare for liner run 6) Run 650' 4" Flushjoint L80 casing w/ Duplex shoe and Cement in place w/ 			tank and haul contents to the required	
± 50 sx			disposal per ODC Rule 19.15.17	
7) Clean out and test liner for	leaks			
 8) Log well (CBL/CNL/GR) 9) Perforate/Stimulate based off of log 10) BH w/ injection maker and set marker at +30' from ten perf 				
11) Circulate packer fluid, RIH with duoline tubing, and perform MIT			D Hobbs office 24 hours	
12) ND BOP. NU Wellhead. F	lace well on injection.	prior of	running MIT Test & Chart	
Saud Data	Dia Balanza Da			
Spud Date:	Rig Release Da			
I hereby certify that the information	above is true and complete to the be	est of my knowledg	e and belief.	
	•			
SIGNATURE		ction Engineer	DATE 08/27/2018	
Turne or print name Isaah S. Cov. E. mail address: Isaah Cov.@ev. som DUONE: 712.407.2052				
Type or print name <u>Jacob S. Cox</u> E-mail address: <u>Jacob Cox@oxy.com</u> PHONE: <u>713-497-2053</u> For State Use Only				
APPROVED BY: I Conditions of Approvel (if a ki):	ALICUN TITLE	TU/L	DATE 8/27/2018	
Conditions of Approval (if any):			•	

M	,
---	---



