

CONDITIONS OF APPROVAL

API #	Operator	Well name & Number
30-025-43908	SOLARIS WATER MIDSTREAM	BRININSTOOL SWD # 001

Applicable conditions of approval marked with XXXXXX

Administrative Orders Required

XXXXXXX	Reveiw administrative order when approved for additional conditions of approval

Other wells

Drilling

XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string

Casing

XXXXXXX	SURFACE, INTERNEMIAE(1) & PRODUCTION CASING - Cement must circulate to surface -- Liner(1) Cement come to top of liner
XXXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water

Lost Circulation

XXXXXXX	Must notify OCD Hobbs Office if lost circulation is encountered at 575-370-3186

Water flows

XXXXXXX	Must notify OCD Hobbs Office of any water flow in the Salado formation at 575-370-3186. Report depth and flow rate.

Stage Tool

XXXXXXX	Must notify OCD Hobbs Office prior to running Stage Tool at 575-370-3186
XXXXXXX	If using Stage Tool on Surface casing, Stage Tool must be greater than 350' and a minimum 200 feet above surface shoe.
XXXXXXX	When using a Stage Tool on Intermediate or Production Casing Stage must be a minimum of 50 feet below previous casing shoe.

Completion & Production

XXXXXXX	Will require a deviational survey with the C-105
XXXXXXX	Must notify Hobbs OCD office prior to conducting MIT (575) 393-6161 ext. 114
XXXXXXX	May not inject prior to SWD order approval
XXXXXXX	Must conduct & pass MIT prior to any injection