Office	State of New Mexico	Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Reson	urces Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISI	ON 30-015-01193
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE X FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK T	
	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Artesia Metex Unit
PROPOSALS.) 1. Type of Well: Oil Well \[\bar{X} \]	Gas Well Other	8. Well Number 30
	-	
State of New Mexico for	merly Canyon E&P Company 29 2018	269864
3. Address of Operator	merly Canyon E&P Company 29 2018	10. Pool name or Wildcat
	Hobbs, NM 88240 RECEIVED	
	110005, 19101 00270	Altesia QU-OD-SA
4. Well Location	000 - N-4h	220
Unit Letter A		e and 330 feet from the East line
Section 25	Township 18S Range 27	E NMPM County Eddy
	11. Elevation (Show whether DR, RKB, RT	G, GR, etc.)
12 Check	Appropriate Box to Indicate Nature of	Notice, Report or Other Data
12. Check	rippropriate Box to material retails of	Tronger, Report of Other Data
NOTICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		IAL WORK
TEMPORARILY ABANDON	· · · · · · · · · · · · · · · · · · ·	ENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING	\equiv	G/CEMENT JOB
DOWNHOLE COMMINGLE		_
	· ·	
CLOSED-LOOP SYSTEM	1	
CLOSED-LOOP SYSTEM OTHER:		: 🗆
OTHER:	□ OTHER	
OTHER: 13. Describe proposed or com	pleted operations. (Clearly state all pertinent of	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	OTHER pleted operations. (Clearly state all pertinent coords). SEE RULE 19.15.7.14 NMAC. For Mu	
OTHER: 13. Describe proposed or com	OTHER pleted operations. (Clearly state all pertinent coords). SEE RULE 19.15.7.14 NMAC. For Mu	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	OTHER pleted operations. (Clearly state all pertinent coords). SEE RULE 19.15.7.14 NMAC. For Mu	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	OTHER pleted operations. (Clearly state all pertinent coords). SEE RULE 19.15.7.14 NMAC. For Mu	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	OTHER pleted operations. (Clearly state all pertinent coords). SEE RULE 19.15.7.14 NMAC. For Mu	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	OTHER pleted operations. (Clearly state all pertinent coords). SEE RULE 19.15.7.14 NMAC. For Mu	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent cork). SEE RULE 19.15.7.14 NMAC. For Muccompletion.	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	OTHER pleted operations. (Clearly state all pertinent coords). SEE RULE 19.15.7.14 NMAC. For Mu	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent cork). SEE RULE 19.15.7.14 NMAC. For Muccompletion.	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent cork). SEE RULE 19.15.7.14 NMAC. For Muccompletion.	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent cork). SEE RULE 19.15.7.14 NMAC. For Muccompletion.	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent cork). SEE RULE 19.15.7.14 NMAC. For Muccompletion.	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent cork). SEE RULE 19.15.7.14 NMAC. For Muccompletion.	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent cork). SEE RULE 19.15.7.14 NMAC. For Muccompletion.	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	pleted operations. (Clearly state all pertinent overly). SEE RULE 19.15.7.14 NMAC. For Muscompletion. SEE ATTACHMEN	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent cork). SEE RULE 19.15.7.14 NMAC. For Muccompletion.	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	pleted operations. (Clearly state all pertinent overly). SEE RULE 19.15.7.14 NMAC. For Muscompletion. SEE ATTACHMEN	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	pleted operations. (Clearly state all pertinent overly). SEE RULE 19.15.7.14 NMAC. For Muscompletion. SEE ATTACHMEN	letails, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re Spud Date:	pleted operations. (Clearly state all pertinent overly). SEE RULE 19.15.7.14 NMAC. For Muscompletion. SEE ATTACHMEN Rig Release Date:	letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re Spud Date:	pleted operations. (Clearly state all pertinent overly). SEE RULE 19.15.7.14 NMAC. For Muscompletion. SEE ATTACHMEN	letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re Spud Date:	pleted operations. (Clearly state all pertinent overk). SEE RULE 19.15.7.14 NMAC. For Moreompletion. SEE ATTACHMEN Rig Release Date:	letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re Spud Date:	pleted operations. (Clearly state all pertinent overly). SEE RULE 19.15.7.14 NMAC. For Muscompletion. SEE ATTACHMEN Rig Release Date:	letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re Spud Date:	pleted operations. (Clearly state all pertinent overk). SEE RULE 19.15.7.14 NMAC. For Moreompletion. SEE ATTACHMEN Rig Release Date:	letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re Spud Date: I hereby certify that the information SIGNATURE	Pleted operations. (Clearly state all pertinent of york). SEE RULE 19.15.7.14 NMAC. For Musicompletion. SEE ATTACHMEN Rig Release Date: TITLE Petroleum Er	letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or com of starting any proposed we proposed completion or responsed completion or responsed completion. Spud Date: I hereby certify that the information SIGNATURE Type or print name Mark Whita	Pleted operations. (Clearly state all pertinent of york). SEE RULE 19.15.7.14 NMAC. For Musicompletion. SEE ATTACHMEN Rig Release Date: TITLE Petroleum Er	letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of NTS knowledge and belief. DATE 8/29/2018
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re Spud Date: I hereby certify that the information SIGNATURE	Pleted operations. (Clearly state all pertinent overk). SEE RULE 19.15.7.14 NMAC. For Moreompletion. SEE ATTACHMEN Rig Release Date: TITLE Petroleum Er Lease Date: E-mail address:	knowledge and belief. DATE 8/29/2018 PHONE: 575-393-6161
OTHER: 13. Describe proposed or com of starting any proposed we proposed completion or responsed completion or responsed completion. Spud Date: I hereby certify that the information SIGNATURE Type or print name Mark Whita	Pleted operations. (Clearly state all pertinent of york). SEE RULE 19.15.7.14 NMAC. For Musicompletion. SEE ATTACHMEN Rig Release Date: TITLE Petroleum Er	knowledge and belief. DATE 8/29/2018 PHONE: 575-393-6161
OTHER: 13. Describe proposed or com of starting any proposed we proposed completion or responsed completion or responsed completion or responsed completion or responsed completion or response completion completion or response completion completi	Pleted operations. (Clearly state all pertinent overk). SEE RULE 19.15.7.14 NMAC. For Moreompletion. SEE ATTACHMEN Rig Release Date: TITLE Petroleum Er Lease Date: E-mail address:	letails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of NTS knowledge and belief. DATE 8/29/2018

Canyon E&P Company Artesia Metex Unit No. 30 30-015-01193 990' FNL & 330' FEL UL – A, Sec. 25, T18S, R27E

8 5/8" 24# csg at 493' w/ 50 sx cmt. 4 1/2" 9.5# csg at 2126' w/ 300 sx cmt. Perfs 1910' – 1947' TD 2129'

- 1. MIRU plugging equipment. POOH w/ production equipment.
- 2. Run gauge ring. Set CIBP at 1810'. Circulate hole w/ mud laden fluid and pressure test casing to 500 psi.
- 3. Spot 35 sx cement.
- 4. Perforate at 543'. Pump sufficient cement to circulate to surface inside/outside of 4 ½" casing.
- 5. Cut off wellhead 3 feet below ground level.
- 6. Verify cement to surface on all strings.
- 7. Install upright P&A marker and cut off anchors.

NOTES: Mud laden fluid consists of 9.5 ppg with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to proceeding with P&A.

Canyon E P Company Artesia Metex Unit No. 30

CURRENT 30-015-01193

8 5/8" 24# @ 493' w/ 50 sx

Perfs 1910' - 1947' 4 1/2" 9.5# @ 2126' w/ 300 sx TD 2129'

Canyon E P Company Artesia Metex Unit No. 30





INSTALL P&A MARKER
VERIFY CMT TO SURFACE
CUT OFF WELLHEAD 3' BELOW GL

8 5/8" 24# @ 493' w/ 50 sx PERF AT 543'.

CIRCULATE CEMENT TO SURFACE.

SPOT 35 SX CMT*
CIRC MLF. PRESSURE TEST CSG.
SET CIBP AT 1810'.

Perfs 1910' - 1947' 4 1/2" 9.5# @ 2126' w/ 300 sx TD 2129'

* NO TAG NECESSARY IF CSG TESTS GOOD