Submit 1 Copy To Appropriate District	State of New Me	vico		Form C-103
Office	Finise State of New Westers  State of New Westers  Energy, Minerals and Natural Resources  Strict II – (575) 393-6161  Energy, Minerals and Natural Resources  Strict III – (575) 748-1283  OIL CONSERVATION DIVISION  Strict III – (505) 334-6178  1220 Sout III BR35 OCD		Revised August 1, 2011	
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> - (575) 748-1283				
			30-025-06219	
1000 Rio Brazos Rd., Aztec, NM 87410			5. Indicate Type of Lease	
Santa Fe, NM 87505 220 S. St. Francis Dr., Santa Fe, NM SEP 1 0 2018			STATE XX FEE  6. State Oil & Gas Lease No.	
87505	SEF, I	U 2010	6. State Oil & Ga	as Lease No.
SUNDRY NO	TICES AND REPORTS ON 的社会	en/en	7. Lease Name o	r Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN UR PLUG BACK TO A			Eumont Hardy U	
	ICATION FOR PERMIT" (FORM C-101) FO	R SUCH	n n	<b>→</b>
PROPOSALS.)  1. Type of Well: Oil Well X	Gas Well Other		8. Well Number	
2. Name of Operator			9. OGRID Numb	per
Marr Oil & Gas Corporation	,		151228	
3. Address of Operator			10. Pool name or	Wildcat
PO Box 5155 Santa Fe, NM 8	7502		Eumont; Yates, 7	Rivers, Queen
4. Well Location		· · · · · · · · · · · · · · · · · · ·		
Unit LetterN:	660feet from theSouth_	line and1	980feet from	n theWestline
Section 36	Township 20S	Range 378E	NMPM	Lea County
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)		
	251		V-52 mm/hh	THE RESERVE OF THE PROPERTY OF THE PARTY OF
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INT				
NOTICE OF INT SUBS			·	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRIL		P AND A XX
PULL OR ALTER CASING	(1)	CASING/CEMENT		TANDA AX
DOWNHOLE COMMINGLE		O, tollto, ozmzivi		
	POAR			
OTHER:		OTHER:		
	pleted operations. (Clearly state all p			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
SEE ATTACHED				
JEE AT TACHED				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE BULY ?- Ruhan TITLE FIELD SUPER DATE 9/5/18				
Type or print name Billy E. Prichard-mail address: billy@pwllc.netphone: 4329347680				
For State Use Only				
h Vila Dec				
APPROVED BY: Washington TITLE P.E.S., DATE 01/10/18				
Conditions of Approval (if any):				

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Restoration Due By 07-19-2018

## Plugging Report Eumont Hardy Unit #21 30-025-06219

7/16/2018 Move equipment and rig up. Unset pump and lay down 142 ¾" rods. Install BOP and POOH with 116 joints 2 3/8" tubing.

7/17/2018 Made gauge ring run to 3500'. Set 5 ½" CIBP at 3475'. Circulate MLF and test casing. Casing showed leak. Spot 25 sx cement on top of CIBP. POOH with tubing and pick up packer. Isolated small hole 1137' to 1200'. Has another larger hole between 60' and surface. Perforated at 2610'. Set packer and pressured up on perforations. Held 500#. POOH with packer and spot 25 sx cement across perfs from 2663'. SION

7/18/2018 Tagged cement at 2469'. Perforated casing at 1200' as per OCD. Set packer at 884'. Could not pump into perfs. Showed same bleed off as before from the casing leak. POOH with packer and spot cement across perfs and casing leak from 1263' with 25 sx cement with CaCl. WOC and tagged at 1020'. Perforated casing at 350'. Set packer at 60' and squeezed perfs with 35 sx cement. Shut in with 1400# on the tubing after squeezing. Left packer set and SION

Tagged cement at 202'. Circulated cement to surface from 202' with 20 sx. Closed casing valve and squeezed hole in casing between 60' and surface with 15 sx. No communication with surface. Rigged down and cut off wellhead. Filled up 5 ½" casing with 5 sx. Cement remained at surface. Installed marker.