

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

HOBBS OCD

SUBMIT IN TRIPLICATE - Other instructions on page 2

SEP 13 2018

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMNM01135
2. Name of Operator CROSS BORDER RESOURCES INC E-Mail: alan@redmountainresources.com		6. If Indian, Allottee or Tribe Name
3a. Address 14282 GILLIS ROAD FARMERS BRANCH, TX 75244	3b. Phone No. (include area code) Ph: 501-412-4097 Fx: 214-871-0406	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 33 T19S R32E NENE 700FNL 330FEL 32.622181 N Lat, 103.763642 W Lon		8. Well Name and No. LUSK 33 FEDERAL 06
		9. API Well No. 30-025-39027-00-S1
		10. Field and Pool or Exploratory Area LUSK
		11. County or Parish, State LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Star
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily At
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal

INT TO PA
P&A NR
P&A R/PM

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

See Attachment

RECLAMATION PROCEDURE
ATTACHEDRECLAMATION
DUE 1-10-19

14. I hereby certify that the foregoing is true and correct. Electronic Submission #431436 verified by the BLM Well Information System For CROSS BORDER RESOURCES INC, sent to the Hobbs Committed to AFMSS for processing by DEBORAH MCKINNEY on 08/16/2018 (18DLM0399SE)	
Name (Printed/Typed) ROSS PEARSON	Title VP OPERATION
Signature (Electronic Submission)	Date 08/15/2018
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved By _____	Title _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office _____
ACCEPTED FOR RECORD AUG 16 2018 Date DMCKinney LIE BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

FOR RECORD ONLY
NMOC 09/13/2018

LUSK 33 FEDERAL #6 (LEA COUNTY, NEW MEXICO)

07/06/18	RODE EQUIP TO LOC – HELD TAILGATE SAFETY MEETING & JSA. RU RIG & RD PUMP JACK HEAD. UNLOADED 20 JTS RENTED TBG. LOADED PIPE FROM PREVIOUS LOC. SDFN.
07/07/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA. OPEN WELL – BG PRESS @ 0# PSI, CSG PRESS @ 180# PSI & SURF PRESS @ 0# PSI; BLED DOWN CSG. RU FLOOR & ROD TONGS. POOH W/ (110) 7/8" RODS & (65) 3/4" RODS TOTAL OF 174 RODS, 1 POLISH ROD & 1 PUMP. RD ROD TONGS & FLOOR. DUG OUT CELLAR, ND WH & NU BOP. RU FLOOR & TONGS. RELEASED TBG ANCHOR & <u>POOH W/ 136 JTS 2-3/8" TBG & TAC, SLOTTED SUB, & SN. RIH W/ TBG TO TAG RBP @ 4,833' & TAGGED HIGH @ 4,486'.</u> CALLED <u>PAUL W/ BLM</u> – INFORMED US THAT WE NEEDED TO REACH THAT RBP. CALLED JEFF INSTRUCTED US TO GET SWIVEL, BIT & COLLARS. CALLED JACK W/ RMR & GAVE HIM UPDATE. SPOKE W/ ROSS W/ RMR – INSTRUCTED US TO HAVE TOOLS ON STANDBY ON LOC TOMORROW, PUMP 100 BBLs TOMORROW AM & CALL HIM BACK W/ DETAILS. PUMPED 50 BBLs BRINE – WELL WENT ON VAC & DID NOT LOAD. POOH. CWI. SDFN.
07/08/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA. OPEN WELL – NO PRESS. PUMPED 100 BBLs BRINE WATER. CALLED ROSS W/ RMR; HE CALLED BLM – INSTRUCTED US TO RIH W/ TBG & ATTEMPT TO BREAK THROUGH TAG POINT. BROKE THROUGH TAG SPOT W/ TBG & CON'T TO RIH. TAGGED @ 4,526' & BROKE THROUGH. TAGGED UP @ 4,692'. SPOKE W/ ROSS W/ RMR – INSTRUCTED US TO PUMP 50 BBLs & ATTEMPT TO GET DEEPER. PUMPED 50 BBLs – STILL TAGGED @ 4,692'. WORKED PIPE – STILL UNABLE TO GET ANY DEEPER. SPOKE W/ ROSS – INFORMED US THAT HE WOULD CALL ZOTA STEVENS W/ BLM FOR FURTHER INSTRUCTIONS. POOH & WOC. ROSS CALLED BACK @ 2:00 PM – INSTRUCTED US TO POOH & <u>SET CIBP @ 4,384' & SPOT 35 SXS CMT, WOC & TAG.</u> PUSHER CALLED ZOTA STEVENS & VERIFIED PROCEDURE. ALSO CALLED PAUL FLOWERS & INFORMED HIM OF CHANGES. POOH W/ TBG. PU CIBP, RIH & SET @ 4,384'. @ 5:00 PM POOH & PUMPED 20 BBLs BRINE WATER. <u>SPOTTED 25 SXS CMT ON TOP OF CIBP.</u> POOH W/ 45 STANDS. CWI. SDFN.
07/09/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA. OPEN WELL – NO PRESS. RIH & TAGGED TOC @ 3,996'. POOH & CIRC MUD. PRESS TESTED TO 500# PSI – HELD GOOD. LD 52 JTS TO 2,712' & <u>SPOTTED A 52 SXS CMT PLUG.</u> POOH & WOC. RIH W/ SLICKLINE & TAGGED TOC @ 2,270'. POOH W/ SLICKLINE. RIH W/ TBG TO 1,190' & <u>SPOTTED A 25 SXS CMT PLUG.</u> LD 37 JTS TBG. CWI. SDFN.
07/09/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA. OPEN WELL – NO PRESS. RIH & TAGGED TOC @ 962'. POOH TO 935' & <u>SPOTTED A 25 SXS CMT PLUG.</u> POOH & WOC. RIH W/ SLICKLINE & <u>TAGGED TOC @ 700'.</u> POOH W/

LUSK 33 FEDERAL #6 (LEA COUNTY, NEW MEXICO)

	SLICKLINE. ND BOP & RD PULLING UNIT. LOADED BEAM TRAILER, <u>DUG OUT</u> <u>CELLAR & CUT OFF WH.</u> PUMPED THP. CAPPED WELL & COVERED CELLAR. <u>INSTALLED MARKER & PLATE.</u> WASHED PIT & PREP TO MO. WELL COMPLETE.
--	---



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos
Supervisory Petroleum Engineering Tech
575-234-5909, 575-361-2648 (Cell)

Arthur Arias
Environmental Protection Specialist
575-234-6230

Henryetta Price
Environmental Protection Specialist
575-234-5951

Shelly Tucker
Environmental Protection Specialist
575-234-5979

Trishia Bad Bear, Hobbs Field Station
Natural Resource Specialist
575-393-3612