
Submit I Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 R11 S. First St. Artesia NM 88210 OIL CONSERVATION DIVISION			Revised July 18, 2013 WELL API NO.	
			30-025-06288	
<u>District III</u> – (505) 334-6178	511 5, 1 Hat 5t., 7 Head, 144 05210		5. Indicate Type of I	,
1000 Río Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		STATE X 6. State Oil & Gas I	
1220 S. St, Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTI	7. Lease Name or U	nit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FÖRM C-101) FOR SUCH			EUNICE MONUMENT SOUTH UNIT	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Y Other INJECTION			8. Well Number 126	
2. Name of Operator XTO ENERGY INC.			9. OGRID Number 005380	
3. Address of Operator			10. Pool name or Wildcat	
6401 HOLIDAY HILL ROAD BLDG #5 MIDLAND TEXAS 79707			EUNICE MONUMENT	F; GRAYBURG SA /
4. Well Location				
Unit Letter M:	660'_feet from the SOUTH	line and <u>660</u>		/
Section 30		inge 37E		County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.				AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB				
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM OTHER:	П	OTHER:		П
	leted operations. (Clearly state all		d give pertinent dates, i	ncluding estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or reco	ompletion.			
XTO ENERGY INC., RESPI	ECTFULLY SUBMITS THIS SUNDE	Y TO PERMANEN	TLY ABANDON REFER	RENCED WELL:
1. TAG TA' CIBP, WOC. CIRCULATE MUD LADEN FLUID			(D	HOBBS OCD
2. Spot 35 sks cement from 3356 to 3006'.				HODDS OCD
3. P/S 40 sks from 2684 to 2544′ WOC, Tag. 4. P/S 40 sks from 1 106 to 966′ WOC. Tag //ZZ′·				OCT 172018
				001 172010
5. Spot 20 sks balanced plug across csg leak from 400 to 600'. WOC. Tag.6. P/S 100 sks from 391 to surface or spot 40 sks balanced plug inside Production casing.				RECEIVED
7. ND BOP and cut off wellhead 5' below surface. Verify CMT set P&A marker.				**FOFIAFE
, , , , , , , , , , , , , , , , , , ,				
		<u></u>		}
Spud Date:	Rig Release Da	ıte:	Se	e Attached
		L	Condit	ions of Approva
				TO 13 OI APPIO
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
12/2 / La 10/1				
SIGNATURE DATE 10/17/2018				
		RICIA_DONALD@X		us. 432-571-8220
Type or print name PATRICIA DON For State Use Only	E-mail address	j:	PHON	E:
A ,	VII Dr			10/1-6-
APPROVED BY: Value Conditions of Approval (if any):	Whiteham TITLE P.E	. 3.	DATE	10/17/2018

See Attached Conditions of Approval

W



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.