Submit 3 Copies To Appropria Office	M 88240	State of New Me	exico		Form C-103 June 19, 2008
District I 1625 N. French Dr., Hobbs, N.	M 88240	· · ·	iai Resources	WELL API NO.	June 19, 2000
District II 1301 W. Grand Ave., Artesia, NM 88210  District III 1000 Rio Brazos Rd., Aztec, NM 8741  District IV 1220 S. St. Francis Dr., Santa Fe, NM				30-025-22811	
				5. Indicate Type of Lea	FEE
1000 Rio Brazos Rd., Aztec, NM 8741 TECEN Santa Fe, NM 87505				6. State Oil & Gas Lea	
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				G S State	
1. Type of Well: Oil Well  Gas Well  Other				8. Well Number 1	
2. Name of Operator JAY MANAGEMENT COMPANY, LLC				9. OGRID Number 247692	
3. Address of Operator				10. Pool name or Wildcat	
1001 WEST LOOP SOUTH, SUITE 750 HOUSTON,TX 77027				BAGLEY PERMO	PENN NORTH
4. Well Location Unit Letter G: 2086 feet from the NORTH line and 1874 feet from the EAST line					
Unit Letter Section		nship 11S Ra			
Section			RKB, RT, GR, etc.,		inty LEA
4301' GL					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTIC	E OF INTENTION T	O:	SUB	SEQUENT REPOR	T OF:
PERFORM REMEDIAL V			REMEDIAL WOR		RING CASING
TEMPORARILY ABANDO PULL OR ALTER CASIN		<del></del>	COMMENCE DRI		DA 📙
DOWNHOLE COMMING		DIMITE []	CASING/CEIVIEN	1 306	
•	nvert to SWD				_
<b>O17141</b> (1		(Clearly state all a	OTHER:	d give pertinent dates inc	luding estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
1. TIH with PKR and 2-7/8" work string tubing. Set PKR @ 9092'.					
2. Pressure test casing to 500 psi.					
3. Acidize Perf with 15% NEFE.					
3. Acidize Perf with 15% NEFE.  4. POOH with PKR and 2-7/8" work string.  5. TIH with PKR and 2-7/8" plastic-lined tubing. Set PKR @ 9092'  SUID DRDER IS					
5. TIH with PKR and 2-7/8" plastic-lined tubing. Set PKR @ 9092' SIN DRDER IS					
5. THE With PRR and 2-7/8" plastic-lined tubing. Set PRR @ 9092"  6. Pressure test casing for MIT.  7. Put well Online.					
6. Pressure test casing for MIT.  7. Put well Online.					
7. Put well Onl	ine.			YVX	thrown -
Spud Date:		Rig Release Da	ite:		
<u> </u>					
I hereby certify that the in	formation above is true and	Momplete to the be	est of my knowledge	e and belief.	
Alf	100	//o :	, ,		
SIGNATURE /	with Short	TITLE Open	ntions Manager	DATE	10/05/0010
	1 W N	The Open	ations Manager	DAIE_	10/25/2018
Type or print name Clay	Griffin ( )	E-mail address	s: <u>cgriffin@jayn</u>	ngt.com PHONE:	574-707-5691
For State Use Only					
APPROVED BY:				DATE	
Conditions of Approval (i	fany):				