Office District I – (575)	Γο Appropriate District ) 393-6161 <b>ΗΟ</b> Dr., Hobbs, NM 88240	S BBCERREANN	state of New Me finerals and Natu	exico Iral Resources	. <u> </u>	Form C- Revised July 18, 2	
1625 N. French	Dr., Hobbs, NM 88240	003 060			WELL API N	<sup>O.</sup> 30-025-23777	
					5. Indicate Type of Lease   STATE   X   FEE   6. State Oil & Gas Lease No.		
							1220 S. St. Fran 87505
		TICES AND REPO			7. Lease Nan	ne or Unit Agreement Nan	ne
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					NORTH VAC. ABO UNIT		
1. Type of Well: Oil Well Gas Well Other INJ					8. Well Number 209		
2. Name of Operator CROSS TIMBERS ENERGY, LLC					9. OGRID Number 298299		
3. Address of Operator					10. Pool name or Wildcat		
		TH STREET, FO	ORT WORTH,	TX 76102	NORTH	VAC ABO	
4. Well Loca	_		_		1700		
Unit Sect	Letter J ion 22		rom the <u>S</u> nship 17-S Ra	line and ange 34-E	1780 feet NMPM	from the <u>E</u> li County LEA	ne
Sect			Show whether DR			County LEA	
			4050.2 G				
TEMPORARI	REMEDIAL WORK 🕅	CHANGE PLA	BANDON	REMEDIAL WO	· · · ·	REPORT OF: ALTERING CASING P AND A	
PULL OR AL			OMPL 🗌	CASING/CEME	ит јов 🛛 🗌	]	
DOWNHOLE		]	MPL	CASING/CEME	NT JOB [	]	
		]		CASING/CEME	NT JOB [	]	
DOWNHOLE CLOSED-LO OTHER: 13. Descr	COMMINGLE COP SYSTEM	] ] npleted operations.	(Clearly state all	OTHER: pertinent details, and	nd give pertinent	dates, including estimated	□ I date
DOWNHOLE CLOSED-LOO OTHER: 13. Descr of sta	COMMINGLE COP SYSTEM	] ] npleted operations. work). SEE RULE	(Clearly state all	OTHER: pertinent details, and	nd give pertinent		□ I date
DOWNHOLE CLOSED-LOO OTHER: 13. Descr of sta propo	COMMINGLE COP SYSTEM Correction of the proposed or compressed or completion or rection o	] ] mpleted operations. work). SEE RULE ecompletion.	Clearly state all 19.15.7.14 NMA	OTHER: pertinent details, and	nd give pertinent	dates, including estimated	□ I date
DOWNHOLE CLOSED-LOO OTHER: 13. Descr of sta propo 1.	COMMINGLE OP SYSTEM	] ] npleted operations. work). SEE RULE ecompletion. H w/ tubing and	Clearly state all j 19.15.7.14 NMA	OTHER: pertinent details, a C. For Multiple Co	nd give pertinent ompletions: Atta	dates, including estimated ch wellbore diagram of	☐ I date
DOWNHOLE CLOSED-LOO OTHER: 13. Descr of sta propo	COMMINGLE OP SYSTEM	] ppleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand	Clearly state all (Clearly state all) 19.15.7.14 NMAG I seal assembly. I. Perforate squ	OTHER: pertinent details, au C. For Multiple Co eeze holes @ 1,7	nd give pertinent ompletions: Atta 725'. RIH w/ (	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'.	
DOWNHOLE CLOSED-LOO OTHER: 13. Descr of sta propo 1. 2. 3.	COMMINGLE OP SYSTEM	] ppleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand	Clearly state all (Clearly state all) 19.15.7.14 NMAG I seal assembly. I. Perforate squ	OTHER: pertinent details, au C. For Multiple Co eeze holes @ 1,7	nd give pertinent ompletions: Atta 725'. RIH w/ (	dates, including estimated ch wellbore diagram of	
DOWNHOLE CLOSED-LOO OTHER: 13. Descr of sta propo 1. 2. 3.	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC.	] ppleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand	Clearly state all j (Clearly state all j 19.15.7.14 NMAC I seal assembly. I. Perforate squ 5 sx Class C cmt	OTHER: pertinent details, an C. For Multiple Co eeze holes @ 1,7 t to attempt to b	nd give pertinent ompletions: Atta 725'. RIH w/ ( oring cmt to su	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'.	
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for re	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICE	] ppleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275	Clearly state all j (Clearly state all j 19.15.7.14 NMAC I seal assembly. I. Perforate squ 5 sx Class C cmt ure test casing -	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade	nd give pertinent ompletions: Atta 725'. RIH w/ ( oring cmt to su enhead.	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'.	
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for re 4.	COMMINGLE OP SYSTEM ribe proposed or com- rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICI Cleanout to to	npleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press	Clearly state all (Clearly state all ) 19.15.7.14 NMA I seal assembly. I. Perforate squ 5 sx Class C cmt ure test casing - culate sand clear	OTHER: pertinent details, a C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade n and retrieve R	nd give pertinent ompletions: Atta 725'. RIH w/ G oring cmt to su enhead. BP.	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'.	
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7.	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICH Cleanout to to RIH w/ 2-3/8" Pressure test t	pleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press op of sand. Circ ' tubing and retu- bg/csg annulus.	Clearly state all (Clearly state all 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmt ure test casing - culate sand clear rievable injectio Release from G	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade n and retrieve R on packer. Set p on/off tool, circu	nd give pertinent ompletions: Atta 725'. RIH w/ G oring cmt to su enhead. BP. okr @ 8,505'. ulate backside	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'.	nhead
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICH Cleanout to to RIH w/ 2-3/8" Pressure test t kr. Notify NMOC	pleted operations. work). SEE RULE completion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press op of sand. Circ ' tubing and retu- bg/csg annulus. CD of intent to p	Clearly state all (Clearly state all 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmt ure test casing - culate sand clear rievable injectio Release from G	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade n and retrieve R on packer. Set p on/off tool, circu	nd give pertinent ompletions: Atta 725'. RIH w/ ( oring cmt to su enhead. BP. okr @ 8,505'. ulate backside	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac	nheae :k on
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7.	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICH Cleanout to to RIH w/ 2-3/8" Pressure test t	pleted operations. work). SEE RULE completion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press op of sand. Circ ' tubing and retu- bg/csg annulus. CD of intent to p	Clearly state all (Clearly state all 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmt ure test casing - culate sand clear rievable injectio Release from G	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade n and retrieve R on packer. Set p on/off tool, circu	nd give pertinent ompletions: Atta 725'. RIH w/ C oring cmt to su enhead. BP. okr @ 8,505'. ulate backside cd. Co	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac <b>ndition of Approval:</b>	nhead ck on <b>noti</b>
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk 8.	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICH Cleanout to to RIH w/ 2-3/8" Pressure test t cr. Notify NMOC Return well to	pleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press op of sand. Circ ' tubing and retu- bg/csg annulus. CD of intent to r o injection.	(Clearly state all ) (Clearly state all ) 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmf ure test casing - culate sand clear rievable injectio Release from G run MIT and pr	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade n and retrieve R on packer. Set p pon/off tool, circu roceed as advise	nd give pertinent ompletions: Atta 725'. RIH w/ G oring cmt to su enhead. BP. okr @ 8,505'. ulate backside ed. Co	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac <b>ndition of Approval:</b> CD Hobbs office 24	nhead ck on <b>noti</b> <b>hours</b>
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICH Cleanout to to RIH w/ 2-3/8" Pressure test t kr. Notify NMOC	pleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press op of sand. Circ ' tubing and retu- bg/csg annulus. CD of intent to r o injection.	Clearly state all (Clearly state all 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmt ure test casing - culate sand clear rievable injectio Release from G	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade on and retrieve R on packer. Set p pon/off tool, circu roceed as advise	nd give pertinent ompletions: Atta 725'. RIH w/ G oring cmt to su enhead. BP. okr @ 8,505'. ulate backside ed. Co	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac <b>ndition of Approval:</b>	nhead ck on <b>noti</b> <b>hours</b>
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk 8.	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICH Cleanout to to RIH w/ 2-3/8" Pressure test t cr. Notify NMOC Return well to	pleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press op of sand. Circ ' tubing and retu- bg/csg annulus. CD of intent to r o injection.	(Clearly state all ) (Clearly state all ) 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmf ure test casing - culate sand clear rievable injectio Release from G run MIT and pr	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade n and retrieve R on packer. Set p pon/off tool, circu roceed as advise	nd give pertinent ompletions: Atta 725'. RIH w/ G oring cmt to su enhead. BP. okr @ 8,505'. ulate backside ed. Co	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac <b>ndition of Approval:</b> CD Hobbs office 24	nhead ck on <b>noti</b> <b>hour</b>
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk 8. Spud Date:	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICF Cleanout to to RIH w/ 2-3/8" Pressure test t cr. Notify NMOC Return well to 05/25/197	pleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press op of sand. Circ ' tubing and retr bg/csg annulus. CD of intent to r o injection.	(Clearly state all ) (Clearly state all ) 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmf ure test casing - culate sand clear rievable injection Release from G run MIT and pr Rig Release Da	OTHER: pertinent details, and C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade on and retrieve R on packer. Set p pon/off tool, circu roceed as advise ate: 06/21	nd give pertinent ompletions: Atta 725'. RIH w/ ( oring cmt to su enhead. BP. okr @ 8,505'. ulate backside ed. <b>Co</b> /1971 prior	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac <b>ndition of Approval:</b> CD Hobbs office 24	nhead ck on <b>noti</b> <b>hour</b>
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk 8. Spud Date:	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICH Cleanout to to RIH w/ 2-3/8" Pressure test t cr. Notify NMOC Return well to	pleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Press op of sand. Circ ' tubing and retr bg/csg annulus. CD of intent to r o injection.	(Clearly state all ) (Clearly state all ) 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmf ure test casing - culate sand clear rievable injection Release from G run MIT and pr Rig Release Da	OTHER: pertinent details, and C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade on and retrieve R on packer. Set p pon/off tool, circu roceed as advise ate: 06/21	nd give pertinent ompletions: Atta 725'. RIH w/ ( oring cmt to su enhead. BP. okr @ 8,505'. ulate backside ed. <b>Co</b> /1971 prior	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac <b>ndition of Approval:</b> CD Hobbs office 24	nhead ck on <b>noti</b> <b>hour</b>
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk 8. Spud Date:	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICF Cleanout to to RIH w/ 2-3/8" Pressure test t cr. Notify NMOC Return well to 05/25/197	pleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Presse op of sand. Circe ' tubing and retu- bg/csg annulus. CD of intent to r o injection.	(Clearly state all ) (Clearly state all ) 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmf ure test casing - culate sand clear rievable injection Release from G run MIT and pr Rig Release Da	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade on and retrieve R on packer. Set p pon/off tool, circu roceed as advise ate: 06/21 est of my knowled	nd give pertinent ompletions: Atta 725'. RIH w/ ( oring cmt to su enhead. BP. okr @ 8,505'. ulate backside ed. <b>Co</b> /1971 prior	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac <b>ndition of Approval:</b> CD Hobbs office 24	nhead ck on <b>noti</b> <b>hour</b>
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk 8. Spud Date:	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICF Cleanout to to RIH w/ 2-3/8" Pressure test t tr. Notify NMOC Return well to 05/25/197	ppleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Presse op of sand. Circ ' tubing and retu- bg/csg annulus. CD of intent to p o injection. 1 n above is true and Mageleo	(Clearly state all j (Clearly state all j 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmf ure test casing - culate sand clear rievable injectio Release from G run MIT and pr Rig Release Da l complete to the b	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade n and retrieve R on packer. Set p pon/off tool, circu coceed as advise ate: 06/21 est of my knowled latory Tech	nd give pertinent ompletions: Atta 725'. RIH w/ G oring cmt to su enhead. .BP. okr @ 8,505'. ulate backside ed. Co /1971 prior	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac ndition of Approval: CD Hobbs office 24 of running MIT Tes	nhead k on <b>noti</b> <b>hours</b> t & C
DOWNHOLE CLOSED-LO OTHER: 13. Descr of sta propo 1. 2. 3. for ro 4. 5. 6. 7. to pk 8. Spud Date:	COMMINGLE OP SYSTEM ribe proposed or com rting any proposed v osed completion or re MIRU. POOF Set RBP @ 3,8 Cement under eturns. WOC. Drill out CICH Cleanout to to RIH w/ 2-3/8" Pressure test t cr. Notify NMOC Return well to 05/25/197	ppleted operations. work). SEE RULE ecompletion. H w/ tubing and 00' w/ 2 sx sand r CICR with 275 R & Cmt. Presse op of sand. Circ ' tubing and retu- bg/csg annulus. CD of intent to p o injection. 1 n above is true and Mageleo	(Clearly state all j (Clearly state all j 19.15.7.14 NMAG I seal assembly. I. Perforate squ 5 sx Class C cmf ure test casing - culate sand clear rievable injectio Release from G run MIT and pr Rig Release Da l complete to the b	OTHER: pertinent details, at C. For Multiple Co eeze holes @ 1,7 t to attempt to b - monitor brade n and retrieve R on packer. Set p pon/off tool, circu coceed as advise ate: 06/21 est of my knowled latory Tech	nd give pertinent ompletions: Atta 725'. RIH w/ G oring cmt to su enhead. .BP. okr @ 8,505'. ulate backside ed. Co /1971 prior	dates, including estimated ch wellbore diagram of CICR & set @ 1,700'. urface. Monitor brade w/ pkr fluid, latch bac <b>ndition of Approval:</b> <del>CD H</del> obbs office 24 <u>of running MIT Tes</u> DATE 10/25/2018	nhead k on <b>notii</b> hours t & C



