
Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District 1</u> – (575) 393-6161 Ene 1625 N. French Dr., Hobbs, NM 88240	rgy, Minerals and Natural Res	well A	PI NO.
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION		0655
District III – (505) 334-6178	1220 South St. Francis Dr	5. Indica	te Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505	31	TATE S FEE DILL DILL GAS Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	·		
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO D		i i	Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FO		88**	Number 1
PROPOSALS.) 1. Type of Well: Oil Well Gas Well	Other	o. Wen i	vanior 1
2. Name of Operator		9. OGRI	D Number
Mack Energy Corporation		013837	nome or Wildon
3. Address of Operator P.O. Box 960 Artesia, NM 88210			name or Wildcat G-06 S183515A; Bone Spring
4. Well Location			
Unit Letter B: 330	feet from theN line ar	nd <u>1650</u> feet fro	om the <u>E</u> line
	nship 18S Range 34E	NMPM	County Lea
	vation (Show whether DR, RKB, F	RT, GR, etc.)	
3982' (SR		
12. Check Appropri	ate Box to Indicate Nature of	of Notice, Report or	Other Data
	_ / . ~ '	_	
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG A		SUBSEQUEI EDIAL WORK	NT REPORT OF: ☐ ALTERING CASING ☐
		MENCE DRILLING OP	_
PULL OR ALTER CASING MULTIF	PLE COMPL CASIN	NG/CEMENT JOB	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM OTHER:	☐ OTHE	R:	П
13. Describe proposed or completed oper	ations. (Clearly state all pertinen	t details, and give perti	
of starting any proposed work). SEE proposed completion or recompletion		Multiple Completions:	Attach wellbore diagram of
proposed completion of recompletion			
1. Set 5 1/2" CIBP @ 8200'. Circulate		Spot 25 sx cmt @ 820	0-8100'.
2. Spot 25 sx cmt @ 7040-6940'. WOO			•
3. Spot 25 sx cmt @ 6630-6530'. WOO 4. Perf & Sqz 45 sx cmt @ 5330-5230'			
5. Perf & Sqz 45 sx cmt @ 4875-4775	. WOC & Tag		
6. Perf & Sqz 45 sx cmt @ 4380-4280			_
7. Perf & Sqz 75 sx cmt @ 3230-3100 8. Cut & POH 5 ½" csg @ 1800'. Spo		OC & Tag (T/Sa/t), 5 1	/2" Stub. 8 5/8" Shoe)
9. Spot 45 sx cmt @ 100'-Surface.	_		,,
10. Cut off well head, verify cement to	surface, weld on Dry Hole Mar	ker.	×
			Con Attack
CI D-4	Die Deleses Dete	_	See Attached
Spud Date:	Rig Release Date:	Col	nditions of Approval
I hereby certify that the information above is t	rue and complete to the best of m	y knowledge and belief	f.
1			
SIGNATURE Moragor	nexy TITLE Agent		DATE 11/7/2018
Type or print name Abigo I Montro	mery E-mail address:	@bcmandas600	iates.com PHONE: 432-580-716
For State Use Only			
APPROVED BY: Malluti	TITLE P.E.S.		DATE 11/08/2018
Conditions of Approval (if any):			


Mack Ene	ergy Corporation			
Author:	Abigail Montgomery			
Well Name	Trigger State	Well No.	#1	
Field		API#:		30-025-40655
County	Lea	Prop #:		
State	New Mexico	Zone:		
Spud Date				
GL	3982 GR			

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	8 5/8	J55	#24	1,760	12 1/4	880	SURF
Prod Csg	5 1/2	L80	#17	9,825	7 7/8	450	6140'



Mack Ene	rgy Corporation		
Author:	Abigail Montgomery		
Well Name	Trigger State	Well No.	#1
Field		API #:	30-025-40655
County	Lea	Prop #:	
State	New Mexico	Zone:	
Spud Date			
GL	3982 GR		

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	8 5/8	J55	#24	1,760	12 1/4	880	SURF
Prod Csg	5 1/2	L80	#17	9,825	7 7/8	450	6140'



TOC @ 6140' (Calc)

DVT @ 6991'

9. Spot 45 sx cmt @ 100'-Surface.

8 5/8 J55 #24 CSG @ 1,760 Hole Size: 12 1/4

8. Cut & POH 5 1/2" csg @ 1800'. Spot 125 sx cmt @ 1900-1710'. WOC & Tag. (T/Salt, 5 1/2" Stub, 8 5/8" Shoe)

- 7. Perf & Sqz 75 sx cmt @ 3230-3100'. WOC & Tag (Bsalt)
- 6. Perf & Sqz 45 sx cmt @ 4380-4280'. WOC & Tag
- 5. Perf & Sqz 45 sx cmt @ 4875-4775'. WOC & Tag
- 4. Perf & Sqz 45 sx cmt @ 5330-5230'. WOC & Tag
- 3. Spot 25 sx cmt @ 6630-6530'. WOC & Tag
- 2. Spot 25 scx cmt @ 7040-6940'. WOC & Tag (DV Tool)
- 1. Set 5 1/2" CIBP @ 8200'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 8200-8100'.

Perfs @ 8223-8325'

Perfs @ 8894-8923'

Perfs @ 9325-9141

5 1/2 L80 #17 (Hole Size: 6140

CSG @ 9,825

TD @ 9825'

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.