Submit 1 Copy To Appropriate District Office <u>L</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	State of New Energy, Minerals and OIL CONSERVAT 1220 South St. Santa Fe, NI	Natural Resou ION DIVISIO Francis Dr.		WELL API N 30-015-2715 5. Indicate T STAT 6. State Oil a	7 ype of Leas E X	<u> Augus</u> se FEE	C-103 tt 1, 2011
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	ATION FOR PERMIT" (FORM C-1 as Well Other	R PLUG BACK TO	<u>)</u>	 Lease Nar Artesia Mete Well Num OGRID N 269864 Pool nam 	ex Unit iber 062 iumber		Name
1625 N. French Drive Hobbs, N	M 88240	RECEIV	'ED	Artesia QU-C		al	-
Section 30	2310feet from the Township 18S 11. Elevation (Show whether	Range	28E	NMPM		_West County	_line
12. Check Ap	opropriate Box to Indica		Notice, I	Report or Ot	her Data		

NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL		SUBSEQUENT REPORT OF: REMEDIAL WORK		
OTHER:			OTHER:		
12 Describe many and an example of example of the state of an extinent details and share mathematicated at the state of the					

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED


I hereby certify that the information above is true and complete to the best of my knowledge and belief.


SIGNATURE	_ TITLE	_DATE
Type or print name	E-mail address:	PHONE:
APPROVED BY Mark Whitehr	TITLE P.E.S.	DATE 12/05/2018
Conditions of Approval (if any):		

Canyon E&P Company Artesia Metex Unit #62 30-015-27157 2310 FNL & 990 FWL UL-E, Sec 30, T18S, R28E

8 5/8" 24 # casing set at 361'. Cemented with 300 sx cement. Cement circulated. 5 ½" 15.5# casing set at 2200'. Cemented with 500 sx cement. Cement circulated. Perforations: 1859'-1971'

- 1. MIRU and POOH with production equipment.
- 2. Make gauge ring run and set 5 ½" CIBP at 1759'. Circulate MLF and test casing to 500#.
- 3. Spot 50 sx cement on top of CIBP.
- 4. Spot cement from 411' to surface.
- 5. Cut off wellhead 3' below ground level.
- 6. Install upright marker and cut off anchors.





•