Submit One Copy To Appropriate District Office District I 1625 N. French Dr. Hobbs NM 88240 A District I	
	Form C-103
Office District I Energy, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
DELOIL CONSERVATION DIVISION DELOIL CONSERVATION DIVISION	30-025-00960
District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV DECOIL CONSERVATION DIVISION Santa Fe, NM 87505	5. Indicate Type of Lease STATE FEE □
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
220 S. St. Francis Dr., Santa Fe, NM	E-9062
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	LITTLE EDDY UNIT
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number
1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other	1
2. Name of Operator	9. OGRID Number
Chevron USA Inc.	4323
3. Address of Operator 6301 Deauville Blvd., Midland, TX 79705	10. Pool name or Wildcat SALT LAKE, MORROW, SO.
	SALI LAKE, MORROW, SU.
4. Well Location:	E A CITE LL
Unit Letter P: 660 feet from the SOUTH line and 660 feet from the	
Section 25 Township 20-S Range 32-E NMPM County LI 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	<u>2A</u>
3634'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Da	ata
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRILL	-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	
FOLL OR ALTER CASING MIDETIFEE COMPL CASING/CLIMENT	308 U
OTHER:	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Oper	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been particles.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in	concrete. It shows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU	ARTER/OUARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	TI III KO DELIT WEEDED OIL
	THE DEET WEEDED ON
_ , , , , , , , , , , , , , , , , , , ,	
ther production equipment.	peen cleared of all junk, trash, flow lines and
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grounds.	neen cleared of all junk, trash, flow lines and
other production equipment. ☐ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s)	neen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location.	nd level. have been remediated in compliance with action equipment and junk have been removed.
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s) CD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.	nd level. have been remediated in compliance with action equipment and junk have been removed.
wither production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.)	nd level. have been remediated in compliance with action equipment and junk have been removed.
wither production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules.	nd level. have been remediated in compliance with action equipment and junk have been removed. Yed. (Poured onsite concrete bases do not have
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s) CDD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC.	nd level. have been remediated in compliance with action equipment and junk have been removed. Yed. (Poured onsite concrete bases do not have
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group If this is a one-well lease or last remaining well on lease, the battery and pit location(s) CDD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines.	peen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have All fluids have been removed from non-
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC, etrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and	peen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have All fluids have been removed from non-
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC, etrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and occation, except for utility's distribution infrastructure.	been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC, etrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and occation, except for utility's distribution infrastructure.	been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC, etrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and ocation, except for utility's distribution infrastructure.	been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well actual an inspection.
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC, etrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and occation, except for utility's distribution infrastructure.	been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well an inspection.
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC, retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and ocation, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schools of the service poles. FIGNATURE Katherine Papageorge TITLE Decommissioning Formation of the service poles and the	been cleared of all junk, trash, flow lines and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well actual an inspection.
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC, etrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and ocation, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to scheme all work has been completed, return this form to the appropriate District office to scheme lease. EIGNATURE Katherine Papageorge TITLE Decommissioning Forms of the papageorge and the lease of the	been cleared of all junk, trash, flow lines and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection.
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and ocation, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to school of the location of the locat	been cleared of all junk, trash, flow lines and level. have been remediated in compliance with action equipment and junk have been removed red. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection. Project ManagerDATE12/18/2018evron.comPHONE:832-854-5291
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and ocation, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to school of the location of the locat	been cleared of all junk, trash, flow lines and level. have been remediated in compliance with action equipment and junk have been removed red. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection. Project ManagerDATE12/18/2018evron.comPHONE:832-854-5291
Anchors, dead men, tie downs and risers have been cut off at least two feet below group. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) DCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. etrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and occation, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to school of the complete lease of the c	been cleared of all junk, trash, flow lines and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have All fluids have been removed from non- llines have been removed from lease and well edule an inspection.