Office	Appropriate District	219	ate of New Me	kico		Form C-103	
District 1 1625 N. French Dr., Hobbs, NM BBS OCD Energy, Minerals and Natural Resources					WELL ADINO	June 19, 2008	
Dietmot II					WELL API NO. 30-025-2241	,	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION					5. Indicate Type of		
District III FEB 01 2019 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aziec, NM 87410					STATE [☐ FEE ☑	
District IV 1220 S. St. Francis Dr., Santa Fe, RECEIVED 87505					6. State Oil & Ga	s Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Name or	Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					EVA COM		
PROPOSALS.)					8. Well Number 1		
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator					9. OGRID Number		
JAY MANAGEMENT COMPANY, LLC					9. OGRID Number 247692		
3. Address of Operator					10. Pool name or Wildcat		
1001 WEST LOOP SOUTH, SUITE 750 HOUSTON,TX 77027					North Bagley		
4. Well Location Unit Letter J: 1980 feet from the SOUTH line and 1980 feet from the EAST line							
Section	20	icct in					
Section	20	Towns		nge 33E RKB, RT, GR, etc.	NMPM	County LEA	
	Company of the second		4308 KB	mio, m, on, cic.,	,		
	12. Check A	ppropriate Box	x to Indicate Na	ature of Notice,	Report or Other	Data +	
N	OTICE OF INT	TENTION TO	:	SUB	SEQUENT RE	PORT OF:	
PERFORM REMI		PLUG AND ABA		REMEDIAL WOR	·	ALTERING CASING	
TEMPORARILY /		CHANGE PLAN		COMMENCE DR		P AND A	
PULL OR ALTER DOWNHOLE CO		MULTIPLE CON	MPL 🗌	CASING/CEMEN	I JOB 🗍	PNR	
DOWNHOLE CO	WIMINGLE L						
OTHER:				OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date							
of starting	g any proposed wor					es, including estimated date am of proposed completion	
of starting or recomp	g any proposed wor	k). SEE RULE 1	103. For Multipl				
of starting or recomp 01/12/2019	g any proposed wor pletion. : Tag "fish" at 7453'. Ca	rk). SEE RULE 1	1103. For Multipl	e Completions: At			
of starting or recomp 01/12/2019 01/13/2019	g any proposed wor pletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3	rk). SEE RULE 1 Ill OCD for instruction. 30 sx class C cmt at 72	103. For Multipl	e Completions: At			
of starting or recomp 01/12/2019 01/13/2019	g any proposed wor pletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri	rk). SEE RULE I III OCD for instruction. 30 sx class C cmt at 72 forate at 6000' attem	103. For Multipl . 299' (Per Kerry w/OCD) pted to squeeze. Call (e Completions: At). WOC. DCD for instruction.	tach wellbore diagra	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019	g any proposed wor pletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri Pump balance plug at	rk). SEE RULE 1 Ill OCD for instruction. 30 sx class C cmt at 72 forate at 6000' attem. 6050' with 25 sx class	For Multipl . 299' (Per Kerry w/OCD pted to squeeze. Call C	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora	tach wellbore diagra		
of starting or recomp 01/12/2019 01/13/2019	g any proposed wor pletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri Pump balance plug at	rk). SEE RULE I all OCD for instruction. 30 sx class C cmt at 72 forate at 6000' attem. 6050' with 25 sx class 3825' with 25 sx class	Por Multipl	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora	tach wellbore diagra	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019	g any proposed wor bletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri Pump balance plug at Pump balance plug at Perforate at 2400'. Sq	rk). SEE RULE I all OCD for instruction. 30 sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class jueeze 70 sx class C cr	Per Multiple. Per Kerry w/OCD pted to squeeze. Call Cost Comt. No WOC (Per st. Comt. No WOC (Per mt. WOC.	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora kerry w/OCD).	tach wellbore diagra	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019	g any proposed word pletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump : : Tag plug at 6867'. Peri Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in	rk). SEE RULE I all OCD for instruction. 30 sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class queeze 70 sx class C cr instruction. Squeeze 2	Por Multiple. Per Kerry w/OCD pted to squeeze. Call Cont. No WOC (Per S C cmt. No WOC (Per mt. WOC.) S x class C cmt displa	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora kerry w/OCD).	tach wellbore diagra te at 3774' attempted to v/OCD). WOC.	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019	g any proposed word pletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump : : Tag plug at 6867'. Peri Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in	rk). SEE RULE I all OCD for instruction. 30 sx class C cmt at 72 forate at 6000' attem. 6050' with 25 sx class 3825' with 25 sx class jueeze 70 sx class C cr instruction. Squeeze 2 5 500 psi - Held. Perfo	Per Multiple Per Kerry w/OCD pted to squeeze. Call (s C cmt. No WOC (Per s C cmt. No WOC (Per mt. WOC.) s x class C cmt displarate at 1700'. Squeeze	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora kerry w/OCD).	tach wellbore diagra te at 3774' attempted to v/OCD). WOC.	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019	g any proposed wor bletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for it	rk). SEE RULE I III OCD for instruction. 30 sx class C cmt at 72 forate at 6000' attem, 6050' with 25 sx class 3825' with 25 sx class jueeze 70 sx class C cr instruction. Squeeze 2 50500 psi - Held. Perfoulate 120 sx class C cr	Por Multiple. Per Kerry w/OCD pted to squeeze. Call of s C cmt. No WOC (Per s C cmt. No WOC (Per mt. WOC.) S ex class C cmt displarate at 1700'. Squeeze mt to surface.	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora kerry w/OCD). ce to 2300' (Per Kerry v 70 sx class C cmt. WO	tach wellbore diagra te at 3774' attempted to v/OCD). WOC.	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019 01/15/2019	g any proposed wor bletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circulate of the control of the contr	ck). SEE RULE I III OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class ueeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo- ulate 120 sx class C cr slow ground level and	Por Multiple. Per Kerry w/OCD pted to squeeze. Call of s C cmt. No WOC (Per s C cmt. No WOC (Per mt. WOC.) S ex class C cmt displarate at 1700'. Squeeze mt to surface. Install dry hole marke	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora kerry w/OCD). ce to 2300' (Per Kerry v 70 sx class C cmt. WOC r.	te at 3774' attempted to v/OCD). WOC. C. Tag at 1595'	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019	g any proposed wor bletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circu	ck). SEE RULE I III OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class ueeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo- ulate 120 sx class C cr slow ground level and	Por Multiple. Per Kerry w/OCD pted to squeeze. Call of s C cmt. No WOC (Per s C cmt. No WOC (Per mt. WOC.) S ex class C cmt displarate at 1700'. Squeeze mt to surface.	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora kerry w/OCD). ce to 2300' (Per Kerry v 70 sx class C cmt. WOC r.	tach wellbore diagra te at 3774' attempted to v/OCD). WOC.	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019 01/15/2019	g any proposed wor bletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circulate of the control of the contr	ck). SEE RULE I III OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class ueeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo- ulate 120 sx class C cr slow ground level and	Por Multiple. Per Kerry w/OCD pted to squeeze. Call of s C cmt. No WOC (Per s C cmt. No WOC (Per mt. WOC.) S ex class C cmt displarate at 1700'. Squeeze mt to surface. Install dry hole marke	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora kerry w/OCD). ce to 2300' (Per Kerry v 70 sx class C cmt. WOC r.	te at 3774' attempted to v/OCD). WOC. C. Tag at 1595'	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019 01/15/2019 01/16/2019 Spud Date:	g any proposed wor bletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Peri Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circulate of the control of the contr	rk). SEE RULE I all OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class queeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo ulate 120 sx class C cr elow ground level and	103. For Multiple. 299' (Per Kerry w/OCD) pted to squeeze. Call of the second of the squeeze. Call of the second	e Completions: At). WOC. OCD for instruction. Kerry w/OCD). Perfora kerry w/OCD). ce to 2300' (Per Kerry v 70 sx class C cmt. WOC r.	te at 3774' attempted to v/OCD). WOC. C. Tag at 1595'	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019 01/15/2019 01/16/2019 Spud Date:	g any proposed wordletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Perform pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circus Cut off wellhead 3' be 01/11/201	rk). SEE RULE I all OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class queeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo ulate 120 sx class C cr elow ground level and	103. For Multiple. 299' (Per Kerry w/OCD) pted to squeeze. Call of the second of the squeeze. Call of the second	e Completions: At). WOC. OCD for instruction. Kerry w/OCD). Perfora kerry w/OCD). ce to 2300' (Per Kerry v 70 sx class C cmt. WOC r.	te at 3774' attempted to v/OCD). WOC. C. Tag at 1595'	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019 01/15/2019 01/16/2019 Spud Date:	g any proposed wordletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Perform pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circus Cut off wellhead 3' be 01/11/201	rk). SEE RULE I all OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class queeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo ulate 120 sx class C cr elow ground level and	103. For Multiple. 299' (Per Kerry w/OCD) pted to squeeze. Call of the complete to squeeze. Call of the complete to the between the complete to t	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perforaterry w/OCD). ce to 2300' (Per Kerry word). 70 sx class C cmt. WOOd. r. te: C	te at 3774' attempted to w/OCD). WOC. C. Tag at 1595' 11/16/2019 e and belief.	am of proposed completion squeeze. Call OCD for instruction.	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019 01/15/2019 01/16/2019 Spud Date:	g any proposed wordletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3 : Tag plug at 6867'. Perform pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circus Cut off wellhead 3' be 01/11/201	rk). SEE RULE I all OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class queeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo ulate 120 sx class C cr elow ground level and	103. For Multiple. 299' (Per Kerry w/OCD) pted to squeeze. Call of the second of the squeeze. Call of the second	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perforaterry w/OCD). ce to 2300' (Per Kerry word). 70 sx class C cmt. WOOd. r. te: C	te at 3774' attempted to w/OCD). WOC. C. Tag at 1595' 11/16/2019 e and belief.	am of proposed completion	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019 01/15/2019 01/16/2019 Spud Date:	g any proposed word pletion. : Tag "fish" at 7453'. Call: Circulate MLF. Pump 3: Tag plug at 6867'. Perform pump balance plug at Pump balance plug at Perforate at 2400'. Squit No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circulate Cut off wellhead 3' be 01/11/201	rk). SEE RULE I all OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class queeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo ulate 120 sx class C cr elow ground level and	Per Multiple Per Marry W/OCD pted to squeeze. Call of s C cmt. No WOC (Per mt. WOC.) S x class C cmt displarate at 1700'. Squeeze mt to surface. Install dry hole marke Rig Release Da Complete to the be	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perforaterry w/OCD). ce to 2300' (Per Kerry word). 70 sx class C cmt. WOOd. r. te: C	te at 3774' attempted to v/OCD). WOC. C. Tag at 1595' 11/16/2019 e and belief. DA	am of proposed completion squeeze. Call OCD for instruction.	
of starting or recomp 01/12/2019 01/13/2019 01/14/2019 01/15/2019 01/16/2019 Spud Date: I hereby certify that SIGNATURE	g any proposed word pletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3: : Tag plug at 6867'. Perion Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circus: Cut off wellhead 3' be 01/11/201	rk). SEE RULE I all OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class queeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo ulate 120 sx class C cr elow ground level and	Per Multiple Per Marry W/OCD pted to squeeze. Call of s C cmt. No WOC (Per mt. WOC.) S x class C cmt displarate at 1700'. Squeeze mt to surface. Install dry hole marke Rig Release Da Complete to the be	e Completions: At). WOC. DCD for instruction. Kerry w/OCD). Perfora kerry w/OCD). te to 2300' (Per Kerry v 70 sx class C cmt. WOC r. st of my knowledg	te at 3774' attempted to v/OCD). WOC. C. Tag at 1595' 11/16/2019 e and belief. DA	am of proposed completion squeeze. Call OCD for instruction.	
of starting or recomp o1/12/2019 o1/13/2019 o1/14/2019 o1/15/2019 o1/16/2019 Spud Date: I hereby certify the SIGNATURE	g any proposed word pletion. : Tag "fish" at 7453'. Ca : Circulate MLF. Pump 3: : Tag plug at 6867'. Perion Pump balance plug at Pump balance plug at Perforate at 2400'. Sq : No Tag. Call OCD for in Pressure test casing to Perforate at 400'. Circus: Cut off wellhead 3' be 01/11/201	rk). SEE RULE I all OCD for instruction. So sx class C cmt at 72 forate at 6000' attem 6050' with 25 sx class 3825' with 25 sx class queeze 70 sx class C cr nstruction. Squeeze 2 50500 psi - Held. Perfo ulate 120 sx class C cr elow ground level and	103. For Multiple 299' (Per Kerry w/OCD) pted to squeeze. Call of the squeeze. Call of the squeeze. Call of the squeeze. Call of the squeeze. The squeeze of the squeeze o	e Completions: At b. WOC. CDD for instruction. Kerry w/OCD). Perforaterry w/OCD). te to 2300' (Per Kerry v. 70 sx class C cmt. WOC. r. te: Cd the completions: At car instruction. Co	te at 3774' attempted to v/OCD). WOC. C. Tag at 1595' 11/16/2019 e and belief. DA	am of proposed completion squeeze. Call OCD for instruction. ATE 01/31/2019 ONE: 574-707-5691	