Form 3160-5 (June 2015)	
	SUN Do not u

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED

OMD	NO.	100	4-V	13/	ľ
Expires:	Janı	ıary	31,	20	1
on Carriel Ma					

NDRY NOTICES AND REPORTS ON WELLS
use this form for proposals to drill or to re-enter an Report of the control of the control

NMLC067968

6.	If Indian,	Allottee	or Tribe	Name	

SUBMIT IN	TRIPLICATE - Other instr	2019	7. If Unit or CA/Agree 8910084910	ement, Name and/or No.			
1. Type of Well ☐ Gas Well ☐ Other		RECEI	VED	8. Well Name and No. WDQSU 73			
2. Name of Operator CHAPARRAL ENERGY LLC	Contact: (E-Mail: CSWAN@S	CONNIE SW WANDERLAN	AN		9. API Well No. 30-025-29970-0	i0-S1	
3a. Address 701 CEDAR LAKE BOULEVA OKLAHOMA CITY, OK 73114		3b. Phone No Ph: 918-62	(include area code 1-6533	e)	10. Field and Pool or F DOLLARHIDE	Exploratory Area	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)				11. County or Parish, State		
P Sec 30 T24S R38E SESE 105	50FSL 1250FEL				LEA COUNTY,	NM	
12. CHECK THE AI	PPROPRIATE BOX(ES)	O INDICA	ΓE NATURE C	F NOTICE	, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION			
■ Notice of Intent	☐ Acidize	Dee	pen	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	New	Construction	□ Recom	plete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	N Plug	and Abandon	☐ Tempo	rarily Abandon	•	
	☐ Convert to Injection	☐ Plug	Back	□ Water 1	Disposal		
1. NOTIFY BLM 24HRS BEF 2. MIRU. 3. SET CIBP @ 3525' AND S 4. SPOT 40SX OF CLASS "C 5. SPOT 25SX OF CLASS "C 6. SPOT 50SX OF CLASS "C (SHOW/FR.WTR./SURFACE) 7. CUT OFF WELLHEAD. IN CLOSED LOOP CONTAINME	POT 205X ON TOP. (PEF "CEMENT FROM 2755-2" CEMENT FROM 1256-1 "CEMENT FROM 453'-S STALL MARKER AND TU	1425', WOC 8 056', WOC 8 URFACE, VE IRNOVER F	& TAG. (YATES & TAG. (T. SAL' ERIFY CEMEN ^T OR RECLAMAT	T) ΓAT SURFA		S OF APPROVAL	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #4 For CHAPAR itted to AFMSS for processi	50862 verifie RAL ENERG ng by DEBO	d by the BLM We Y LLC, sent to the RAH MCKINNEY	ell Informatio ne Hobbs on 01/28/201	n System 9 (19DLM0218SE)		
	V PATTERSON			ATIONS MA	-		
Signature (Electronic S	<u></u>		Date 01/16/2				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		
Approved By	, Q. am	_	Title S	ET		2-6-19 Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the		Office Cf	- 0			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s					ake to any department or	agency of the United	
(Instructions on page 2) ** BLM REV	SED ** BLM REVISED	** BLM RE	VISED ** BLI	M REVISEI	D ** BLM REVISEI	 D **	

7 NMOCD 2-8-19

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #73

Created: Updated: Lease: Field: Surf. Loc.: Bot. Loc.:	QU	By: LEE R. By: E QUEEN SAND UNI EEN & 1250' FEL	Well #: API T Unit Ltr.: TSHP/Rng Pool Code:	
County: Status:	LEA	St.: NM	Directions:	
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8-5/8" 24# 403 250 yes surface 12-1/4" p		MLF S	SPOT 50SX OF CMT FROM 453'-SURFACE. /ERIFY. (FW/SHOE/SURFACE) SPOT 25SX OF CMT FROM 1256'-1056'. NOC&TAG. (T.SALT)
	1206' 2525' 2 7 0 5' 3 6 0 0		MLF N	SPOT 40SX OF CMT FROM 2755'-2425'. VOC&TAG. (YATES/B.SALT) SET CIBP@3525' AND SPOT 20SX ON TOP FROM 3525'-3325'.(PERFS)
Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	5-1/2" 17# 3854' 1350 YES SURFACE 7-7/8"			Queen: 3619'-3769'(OA) <i>3</i> 7/ タ 〜 <i>3 7 6 8</i>

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #73

Created: Updated: Lease: Field: Surf. Loc.; Bot. Loc.:	01/15/19 By: LEE R. By: WEST DOOLARHIDE QUEEN SAND UNIT QUEEN 1050' FSL & 1250' FEL			Well #: API Unit Ltr. TSHP/F Pool Co	Rng:	30-025-29970		
County: Status:	LEA	St.: NM		Direction	ns:			
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8-5/8" 24# 403 250 yes surface 12-1/4"			ALF	VERIFY. (FW	OF CMT FROM 453'-SU /SHOE/SURFACE) OF CMT FROM 1256	Philip	
	1206' 2525'			ALF	WOC&TAG. SET CIBP@ FROM 3525	(T.SALT) OF CMT FROM 2755 (YATES/B.SALT) 3525' AND SPOT 203 '-3325'.(PERFS) 19'-3769'(OA)		

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.