

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM69377

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

OXY USA INC

Contact: DAVID STEWART

E-Mail: david_stewart@oxy.com

3a. Address

P.O. BOX 50250
MIDLAND, TX 79710

3b. Phone No. (include area code)

Ph: 432-685-5717

8. Well Name and No.

RED TANK 28 FEDERAL 4

9. API Well No.

30-025-36009

10. Field and Pool or Exploratory Area

RED TANK DELAWARE, WEST

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

D Sec 28 T22S R32E SWSE 330FSL 2310FEL
32.356201 N Lat, 103.678619 W Lon

11. County or Parish, State

LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

12/7/18 - MIRU PU

12/10/18 - POOH & LD rods & pump

12/11/18 - NDWH, NU BOP, rel TAC, POOH & LD tbg. RIH w/ GR/junk basket to 8430', POOH. Notified Paul Flowers-BLM.

12/12/18 - RIH & set CIBP @ 8430', POOH. RIH w/ tbg & tag CIBP @ 8430', notified BLM & appr using CI C, circ hole w/ 10# MLF, M&P 25sx CL C cmt, calc TOC 8177'. PUH to 7946', M&P 25sx CL C cmt, PUH, WOC.

12/13/18 - RIH & tag cmt @ 7723', BLM witnessed, PUH to 6835', M&P 25sx CL C cmt, PUH, WOC.

**RECLAMATION
DUE 6-30-19****RECLAMATION PROCEDURE
ATTACHED**

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #449227 verified by the BLM Well Information System
For OXY USA INC, sent to the Hobbs
Committed to AFMSS for processing by JIM AMOS on 01/09/2019 ()**

Name (Printed/Typed) DAVID STEWART

Title SR. REGULATORY ADVISOR

Signature (Electronic Submission)

Date 01/07/2019

*Accepted for Record***THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By

James R. Amos

Title

SAET

Date

1-18-19

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CKD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED *****KJ**NMOC**2-8-19*

Additional data for EC transaction #449227 that would not fit on the form

32. Additional remarks, continued

12/14/18 - RIH & tag cmt @ 6727', tagged low, notified BLM, spot additional plug. RIH to 6727', M&P 25sx CL C cmt w/ 3% CaCl₂, PUH, WOC. RIH & tag cmt @ 6388', notified BLM. PUH to 5566', M&P 25sx CL C cmt, PUH, WOC.

12/17/18 - RIH & tag cmt @ 5290', BLM witnessed, PUH to 4708', M&P 35sx CL C cmt w/ 3% CaCl₂, PUH, WOC.

12/18/18 - RIH & tag cmt @ 4283', BLM witnessed. RIH w/ pkr & isolated holes @ 551-477', notified BLM. RIH & set pkr @ 2362', RIH & perf @ 2710', Attempt to EIR, pressure to 2000#, no rate or loss, notified BLM.

12/19/18 - POOH w/ pkr, RIH to 2765', M&P 25sx CL C cmt w/ 3% CaCl₂, PUH, WOC. RIH & tag cmt @ 2494'. PUH & set pkr @ 551', RIH & perf @ 1114', EIR @ w/ full circulation between 5-1/2" X 8-5/8" @ 2BPM @ 0#. Per BLM, close 5-1/2" & 8-5/8" valves, attempt to EIR into 8-5/8" by open hole annulus, pressure to 500#, no leak off. M&P 100sx CL C cmt w/ 3% CaCl₂, WOC.

12/20/18 - POOH w/ pkr, RIH & tag cmt @ 669', BLM witnessed. RIH & set pkr @ 75', RIH & perf @ 475', EIR @ w/ full circulation between 5-1/2" X 8-5/8" @ 2BPM @ 0#. Per BLM, close 5-1/2" & 8-5/8" valves, attempt to EIR into 8-5/8" X 13-3/8" annulus, pressure to 500#, no leak off. M&P 130sx CL C cmt, circ cmt to surf. all casing full of cmt. ND BOP, top off csg, NUWH, RDPU.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (**Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure**). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos
Supervisory Petroleum Engineering Tech
575-234-5909, 575-361-2648 (Cell)

Arthur Arias
Environmental Protection Specialist
575-234-6230

Crystal Weaver
Environmental Protection Specialist
575-234-5943

Trishia Bad Bear, Hobbs Field Station
Natural Resource Specialist
575-393-3612