

Submit I Copy To Appropriate District	State of New Mexico		E.m. (* 102
Office	Energy, Minerals and Natural Res	MIRAS	Form C-103 Revised July 18, 2013
<u>District I</u> ~ (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, winterns and Autora res	WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVIS		25-20819
<u>District III</u> - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of STATE	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas I	
1220 S. St. Francis Dr., Santa Fe, NM 87505		B-2	2354-2
SUNDRY NOT		Init Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Tacuum Chorn	eta East Unit 037
PROPOSALS.)		8. Well Number	01
1. Type of Well: Oil Well 2. Name of Operator	Gas Well Other		
Co	nocoPhillips Company		7817
3. Address of Operator 925 N. Eldridge Pkwy, Houston, TX 77079 Vacuum: Glorieta			
925 N. Eldridge Pkwy Houston, TX 77079 4. Well Location Vacuum; Glorieta			
-4 . Well Location Unit Letter B $=:\approx^{5}$	660 feet from the North line ar	nd 2180 feet from the	East line
Section	Township 17-S Range	35-E NMPM	County Lea
	11. Elevation (Show whether DR, RKB, R		eouny Exa
3990' GL			
JAN ZO			
12. Cheek Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:			
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🛛 💼 REMEDIAL WORK 🔅 🔲 ALTERING CASING 🗌			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASINGMULTIPLE COMPLCASING/CEMENT JOB			
CLOSED-LOOP SYSTEM			
OTHER: OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
MIRU. ND WH, NU BOP. POOH Prod Equipment Set CIBP @ 5902' – Circ hole w/ MLF. Pressure test casing. Spot 50sx cmt @ 5902' – 5702'.			
Spot 30sx cmt @ 4360' - 3956'. WOC-Tag			
Spot 25sx cmt @ 3698' - 3498'			
Perf & Sqz 80sx cmt @ 3130' - 2733'. WOC-Tag Perf & Sqz 75sx cmt @ 1715' - 1472' Perf & Sqz 25sx cmt @ 60' - 3' POOH. Fill wellbore. Verify cmt @ surface in all annuli Cut off WH & anchors. Install DH marker 4"dio 4" obove groubd marker			
Perf & Sqz 25sx cmt @ 60' - 3'			
POOH. Fill wellbore. Verify cmt @ surface in all annuli			
Cut off WH & anchors. Install DH marker			
4"dia 4" above grouded marker ""PProval			
** A closed-loop system	will be used for all fluids from this wellbore an	d disposed of required by OCD Ru	de 19.15.17**
•••		• •	
Spud Date:	Rig Release Date:		
spid bac.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Agent – Basic Energy Services DATE 1/25/19			
SIGNATURE TITLE Agent – Basic Energy Services DATE 1/25/19			
Type or print name Greg Br	yant E-mail address:	PHONE:	432-563-3355
For State Use Only			
APPROVED BY: Kenny Former TITLE Compliance Officer A DATE 2-14-19			
Conditions of Approval (if any):	,		

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit



WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.