# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT	HODBA	_
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS		$\mathbb{C}$

BS OC DNMLC031621B

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

	•	, , ,	1 3 2019		
SUBMIT IN	TRIPLICATE - Other inst	ructions on page 2	CEMER	7. If Unit or CA/Agre	ement, Name and/or No.
1. Type of Well  Oil Well Gas Well Oth				8. Well Name and No. BRITT B 25	•
Name of Operator     CONOCOPHILLIPS COMPAN		GREG BRYANT YANT@BASICENERGYSERV	ICES.COM	9. API Well No. 30-025-24956-0	00-S1
3a. Address MIDLAND, TX 79710	······································	3b. Phone No. (include area co Ph: 432-563-3355 Fx: 432-563-3364	de)	10. Field and Pool or EUMONT	Exploratory Area
4. Location of Well (Footage, Sec., 7	T., R., M., or Survey Description,			11. County or Parish,	State
Sec 15 T20S R37E NENW 66	•			LEA COUNTY,	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE,	REPORT, OR OT	HER DATA
TYPE OF SUBMISSION		ТҮРЕ	OF ACTION		
Notice of Intent  ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturin ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	g Reclam	olete arily Abandon	☐ Water Shut-Off ☐ Well Integrity ☐ Other
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Al determined that the site is ready for f.  1) MIRU, ND WH, NU BOP. P. 2) Set 5-1/2 CIBP @ 3428'. C. 3) Spot 25sx cmt @ 3428' - 3. 4) Spot 25sx cmt @ 2910' - 2. 5) Spot 30sx cmt @ 2652' - 2. 6) Perf & Sqz 40sx cmt @ 13. 7) Perf & Sqz 45sx cmt @ 55. 8) Perf & Circ 25sx cmt @ 60' 9) RDMO. Cut off WH & anchor	d operations. If the operation respondonment Notices must be file inal inspection.  POOH w/ Prod Tbg irc hole w/ MLF. Pressure 308' 790' 400'. WOC-Tag 00' - 1200'. WOC-Tag 7' - 457'. WOC-Tag - 3'	sults in a multiple completion or red only after all requirements, inc	ecompletion in a	new interval, a Form 310 n, have been completed SEE ATTAC	60-4 must be filed and the operator has
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #4 For CONOCO	SOLE WAS KEY 450254 verified by the BLM V PHILLIPS COMPANY, sent to ing by DEBORAH MCKINNE	o the Hobbs	n System	
Name (Printed/Typed) GREG BR	•	Title AGE		9 (19DLW02145E)	
Signature (Electronic S	Submission)	Date 01/11	/2010		
Signature (Electronic S	<del></del>	OR FEDERAL OR STAT	/2019 E OFFICE U	SE	
_Approved By	x a amo	Title	SPET	<u> </u>	2-6-19 Date
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	uitable title to those rights in the		40		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				ake to any department of	r agency of the United
(Instructions on page 2)  ** BLM REV	ISED ** BLM REVISED	) ** BLM REVISED ** BI	LM REVISED	** BLM REVISE	D **

NMOCD 2-14-19

### WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date 9/11/18

RKB @ 3570 DF @ 3570 GL @ 3560 Subarea Hobbs (Entl) Lease & Well No Britt B 121/4" hole Sec. 15C, T-20S, R-37-E 1980 FWL 660 FNL Legal Description County . State New Mexico EUMONT Surface Field : Date Spudded B-5/81, 24#/ft, 507 2/28/75 30-025-24956 Crnt'd w/ 260 SX API Number TOC @ Surface \_\_\_ Operator Number Lonso ID. Field Number 5-1/2", 14#/ft, to 3772" Cmt'd w: 275 SX \_\_ TOC @ 1800' Method unknown --Pustler 1200 That 1280 1280 72 2910 72 3417 Penrose 3522 3710 GB UINKED ZONE

EUMONT Yates/7Rivers/Queen
Perfd 3528' - 3556' Perfd 3603: - 3660:

PB1D @ 3728

## WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

RKB @ 3570' DF @ 3570' GL @ 3560'

P&S 256x cmt @ 60'-3' Surface 8-\$;6", 24#rft, 507' Cmt'd w/ 260 SX TOC @ Surface P&S 45ax cmt @ 557'-457' - Tag
 Production 5-1/2" 14#/h, to 3772" Cmt'd w/ 275 SX TOC @ 1800" Method unknown P&S 40sx cmt @ 1300"-1200" - Tag
 Spot 30ox cmt @ 2652'-2400' - Tag
Spot 25sx cmt @ 2910'-2790'
Spot 255x cmt @ 3428'-3308' Sot CIBP @ 3428' LINKED ZONE EUMONT Yates/7Rivers/Queen Perfy 3528' - 3586'
Perfq 3503' - 5560' FBTD @ 3728' TD @ 3775'

Jata.	9/11/1	n

Subarea	Hobbs (E	ast)		
Lease & Well No	Britt B		No. 25	
Legal Description	Sec. 150	C. T-205, R-37-E	1980' FWL	660' FNL
County	Lea	State	New	Mexico
Field	EUMON	T		
Date Spudged .	2/28/75			
API Number	30-025-24956			

Operator Number, Lease ID Field Number

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/Condition of Approval for Lesser Prairie-Chicken:

From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted