UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS 2018

Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS 2018

SUNDRY NOTICES AND REPORTS ON

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN T	TRIPLICATE - Other instru	ctions on page 2		BBS (Donit or CA/Agre	ement, Name and/or No.
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. 19 SHOOT 12 FED (01
2. Name of Operator HARVEY E YATES COMPAN		DE LABOLT natadorresources.com	m	7,	9. API Well No.	
3a. Address		b. Phone No. (include th: 972-629-2158			10. Field and Pool or W CORBIN	
ROSWELL, NM 88202 4. Location of Well (Footage, Sec., T			 	11. County or Parish,	State	
Sec 12 T18S R32E NWSE 2310FSL 1980FEL				LEA COUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE NAT	URE O	F NOTICE,	REPORT, OR OTH	HER DATA
TYPE OF SUBMISSION	N TYPE OF ACTION					
Notice of Intent	☐ Acidize	☐ Deepen		☐ Product	ion (Start/Resume)	☐ Water Shut-Off
Notice of Intent	☐ Alter Casing	☐ Hydraulic Fra	cturing Reclamation		ation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	■ New Constru	struction		olete	□ Other
☐ Final Abandonment Notice	Change Plans	Plug and Aba	ndon 🛌	don 🛌 🛭 Temporarily Abandon		
	☐ Convert to Injection	n Plug Back Wat		☐ Water I	er Disposal	
determined that the site is ready for fill Intent to TA: Previously approto TA well for future use in open Provide 24 hour notice to distrain MIRU. Kill well. ND Wellhead. RIH w/WL and set CIBP at 50 WL dump bail 35? Class C ce Perform MIT to 500 psi. Subm RDMO.	ved to P&A well on 5/10/18, erator?s plans. ict office. NU BOP's. Pull rods and tul 00' (62' above perfs). ment on top of CIBP.	bing.			e	
	Electronic Submission #449 For HARVEY E \ nmitted to AFMSS for process	(ATES COMPÁNY, ing by PRISCILLA F	sent to the EREZ or	ne Hobbs n 01/28/2019	(19PP0737SE)	
Name(Printed/Typed) CHRIS VILLARREAL			Title OPERATIONS ENGINEER			
Signature (Electronic S	Submission)	Date	01/07/20	119		
organization (Environment	THIS SPACE FOR				SE	
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		·	PPh 1 0 0010
Approved By /s/ Jonatho	n Shepard	Direct	oleu	m En	ringer	FEB 1 3 2019
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of t	d. Approval of this notice does not itable title to those rights in the su				gineer Office	•
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to ma	ake to any department or	agency of the United

(Instructions on page 2)
*** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

X7 NMUCD 3-22-19

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Note: TA status "will be effective for a period up to 1 year from the date of NOI approval and can be renewed annually thereafter" per IM NM-2016-017.

- A bridge plug (CIBP) or packer must be installed 50 to 100 feet above any open perforations or open hole. A CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 2. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 3. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 4. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 5. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 6. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.