Submit One Copy To Appropriate District State of New Mexico	Form C-103
District I Piergy, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
BILS First St. Artesia NM 88214 GONSERVATION DIVISION	30-025-31600
Submit One Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Office Conservation Division 1270 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 PK Santa Fe. NM 87505	STATE X FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe. NM	6. State Off & Gas Lease No.
0,000	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	KIWI AKX STATE
1. Type of Well: Oil Well Gas Well Other	8. Well Number #4
2. Name of Operator	9. OGRID Number
EOG RESOURCES, INC	7377
3. Address of Operator	10. Pool name or Wildcat
PO BOX 2267 MIDLAND, TEXAS 79702	LIVINGSTON RIDGE; DELAWARE, E
4. Well Location	
Unit Letter O: 330 feet from the SOUTH_line and 1650 feet from the EAS	T line
Section 16 Township 22S Range 32E NMPM County LEA	<u></u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3705' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check represents Box to indicate reactive of reciper, respect of Other Bath	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF!
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRIL	LING OPNS.□ P AND A □
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB 🗆
	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in	concrete. It snows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU	ADTED/OUADTED I OCATION OD
UNIT LETTED SECTION TOWNSHIP AND DANCE ALLINEODMATIC	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	N HAS BEEN WELDED OR
	N HAS BEEN WELDED OR
BUTTO DE LA CONTRACTOR	SENT PICS INFO GOOD
The location has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as the possible to original ground contour and the	SENT PICS INFO GOOD
The location has been leveled as nearly as possible to original ground contour and has bother production equipment.	Sent Pics INFO good peen cleared of all junk, trash, flow lines and
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground the second second	Sent Pics Ent o good been cleared of all junk, trash, flow lines and and level.
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below groun ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) 	Sent Pics INF o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below grounded in the second of the second of	Sent Pics INF o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
The location has been leveled as nearly as possible to original ground contour and has bother production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location.	Sent Pics Info good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below groung of this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed. 	Sent Pics Info good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) ○ OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) 	Sent Pics Info good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below grounded in the lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. 	Sent Pics Ent o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. 	Sent Pics Ent o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. 	Sent Pics Ent o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have all fluids have been removed from non-
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. 	Sent Pics Ent o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have all fluids have been removed from non-
 ☑ The location has been leveled as nearly as possible to original ground contour and has be other production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. ☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and 	Sent Pics Info good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well
 ☑ The location has been leveled as nearly as possible to original ground contour and has be other production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. ☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. 	Sent Pics Info good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s). ○ OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. ☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule. 	Sent Pics Ent o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection.
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s). ○ OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. ☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule. 	Sent Pics Inf o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed yed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well
 ☑ The location has been leveled as nearly as possible to original ground contour and has been the production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. ☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule. 	Sent Pics Inf o good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection. CIALIST DATE 04/01/2019
 ☑ The location has been leveled as nearly as possible to original ground contour and has been the production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s). ○ CD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. ☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule. SIGNATURE	Sent Pics Info good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection. CIALIST DATE 04/01/2019
 ☑ The location has been leveled as nearly as possible to original ground contour and has bother production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s). ☑ OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. ☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedular to the appropriate District office to schedular the complete completed in the propriate District office to schedular the complete completed in the propriate District office to schedular the complete completed in the complete complete complete completed in the complete completed in the complete complete completed in the complete completed in the complete complete complete complete complete completed in the complete complete complete completed in the complete complete complete complete complete complete complete complete comp	Sent Pics Info good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed and (Poured onsite concrete bases do not have All fluids have been removed from non- lines have been removed from lease and well adule an inspection. CIALIST DATE 04/01/2019 OM PHONE: _432-686-3658
 ☑ The location has been leveled as nearly as possible to original ground contour and has been the production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground. ☑ If this is a one-well lease or last remaining well on lease, the battery and pit location(s). ○ CD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. ☑ All metal bolts and other materials have been removed. Portable bases have been removed be removed.) ☑ All other environmental concerns have been addressed as per OCD rules. ☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. ☑ If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule. SIGNATURE	Sent Pics Info good been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed and (Poured onsite concrete bases do not have All fluids have been removed from non- lines have been removed from lease and well adule an inspection. CIALIST DATE 04/01/2019 OM PHONE: _432-686-3658