
Submit 1 Copy To Appropriate District Office	State of New Mexi		Form C-103	
District I - (575) 393-6161	Energy, Minerals and Natural		rised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 3002507008		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION D	5 Indicate Type of Lease		
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Franci	STATE STATE	EE 🗌	
<u>District IV</u> - (505) 476-3460	Santa Fe, NM 8750	6. State Oil & Gas Lease N	lo.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	HOB	BS OCD 6. State Oil & Gas Lease N		
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SSALS TO DRILL OR TO DEEPEN OR PILIO	F F HARDISON B	reement Name	
PROPOSALS.)	CATION FOR FERMIT (FORM C-101) YOR	30011		
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other Injection RECEIVED  3. Name of Operators		CEIVED 8. Well Number 1		
2. Name of Operator XTO ENERGY, INC.		9. OGRID Nulliber	9. OGRID Number   005380	
3. Address of Operator		10. Pool name or Wildcat		
6401 HOLIDAY HILL RD, BLDG 5, MIDLAND TX 79707		BLINEBRY		
4. Well Location				
Unit LetterH	:1980feet from theNORTI	H_ line and440 feet from theE	ASTline	
Section 34 Township 21S Range 37E NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12 Charle	Annronriata Roy to Indicate Nat	ure of Notice, Report or Other Data		
12. Cleck	Appropriate Box to indicate Nati	re of Notice, Report of Other Data		
	NTENTION TO:	SUBSEQUENT REPORT		
PERFORM REMEDIAL WORK			NG CASING	
TEMPORARILY ABANDON DULL OR ALTER CASING	= 1	COMMENCE DRILLING OPNS.☐ P AND A CASING/CEMENT JOB ☐	· 🗆	
DOWNHOLE COMMINGLE	MOLTIFLE COMPL	CASHING/CEIVIEIN JOB		
CLOSED-LOOP SYSTEM				
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion				
XTO respectfully submits the following plug and abandon summary.				
XTO respectfully submits the following plug and abandon summary.  Set a CIBP at 5400'. Spot a 35 sxs cement plug on CIBP. WOC Tag TOC. C:CC MLF				
Set a CIBP at 5400'. Spot a 35 sxs cement plug on CIBP. WOC Tag TOC. CIC MLF				
Spot a 35 sxs balanced plug from 3935 to 3585'. WOC. Tag TOC.				
Spot a 35 sxs balanced plug from 3375 to 3025'. WOC. Tag TOC.				
Set a CIBP at 5400'. Spot a 35 sxs cement plug on CIBP. WOC Tag TOC. C:rc MLF Spot a 35 sxs balanced plug from 3935 to 3585'. WOC. Tag TOC. Spot a 35 sxs balanced plug from 3375 to 3025'. WOC. Tag TOC. Perforate at 2856'. (50' below csg shoe.) Spot a 50 sxs balanced plug from 2905 to 2406'. WOC. Tag TOC. Perforate at 419'. (50' below the surface csg shoe) Set Pkr at 100' from surface. Mix and pump ~95 sxs cement and displace to depth of 300' with 5.3 bbls water. WOC. POH LD Pkr. Tag TOC inside 5.5" csg.				
Spot a 50 sxs balanced plug from 2905 to 2406'. WOC. Tag TOC.				
Perforate at 419'. (50' below the surface csg shoe)				
Set Pkr at 100° from surface. What and pump ~95 sxs cement and displace to depth of 500° with 5.5 bols water.				
WOC. POH LD Pkr. Tag TOC inside 5.5" csg.  Ru cementers and fill casing to surface with ~30 sxs cement.				
	marker 4"d:a 4' A Bou	wa agai at mila		
Cut and cap well. Instan FA	marker 7 a.a. 4 Ppol	re ground rack		
Spud Date:	Rig Release Date	:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
0.	0			
way was (head	Kowell TITLE Regu		06/04/2019	
Type or print name E-mail address: cheryl_rowell@xtoenergy.com PHONE: 432-571-8205				
For State Use Only				
APPROVED BY: Key Fate TITLE Compliance Office A DATE 6-18-19				
Conditions of Approval (if any)				
- Silamono or repproved (it unity)	•	•		

F. F. Hardison B-1 API 30-025-07008



## **GENERAL CONDITIONS OF APPROVAL:**

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.