Submit 1 Copy To Appropriate District Office District I – (575) 393-6161  State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240  District II - (575) 748-1283  811 S. First St., Artesia, NM 87410  District III - (505) 334-6  District III - (505) 334-6  District IV - (505) 476-3460  District IV - (505) 476-34		WELL API NO. 30-025-22451  5. Indicate Type of Lease	
		STATE FEE  6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Pe, NM 87505 SUNDA FOR EAST AND REPORTS ON WELLS			B-1113-1
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name: Central Vacuum Unit  8. Well Number:
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other:			118
2. Name of Operator: Chevron U.S.A. Inc.		9. OGRID Number: 4323	
3. Address of Operator: 6301 Deauville Blvd, Midland, TX. 79706		10. Pool name or Wildcat: Vacuum Grayburg San Andres	
4. Well Location			
Unit Letter N: 990 feet from the South line and 1650 feet from the West line  Section 6 Township 18-S Range 35-E NMPM County Lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3,977' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ COMMENCE DR			
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN			
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM  OTHER:	П	OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Charges has determined the subject well is unaconomic to approte so the plan is to TA the well for fitting use nor the			
following procedure:			
1. MIRU, NDWH, NU BOPE.			
<ol> <li>POOH with all producing equipment.</li> <li>Set CIBP @ ~4,400' MD and cap with 35' or 25 sxs of CMT. Circulate PKR fluid.</li> </ol>			
4. Notify NMOCD to witness pressure test of casing and chart.			
5. File subsequent report with MIT chart to NMOCD.			
Chevron is requesting a 5-year TA status.			
following procedure:  1. MIRU, NDWH, NU BOPE.  2. POOH with all producing equipment.  3. Set CIBP @ ~4,400' MD and cap with 35' or 25 sxs of CMT. Circulate PKR fluid.  4. Notify NMOCD to witness pressure test of casing and chart.  5. File subsequent report with MIT chart to NMOCD.  Chevron is requesting a 5-year TA status.  Rig Release Date:			
Spud Date:	Rig Release Date	e:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Sara Maynard TITLE Production Engineer DATE 11 June 2019			
Type or print name Sara Maynard E-mail address: sara.deeney@chevron.com PHONE: (432) 687-7255  For State Use Only			
APPROVED BY: Xery first TITLE Conglisions of Approval (if app):			
Conditions of Approval (if apy):			
			<

Men De L'autoffice Wild Leit & Charle OCO STATE ONCE STATE OF THE STA Considerate of soprovale nobile