	State of New Me		Form C-10	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natur	ral Resources	Revised July 18, 201	.3
1625 N. French Dr., Hobbs, NM 88240		_	WELL API NO.	
District II - (575) 748-1283	OIL CONSERVATION	DIVISION	30-025-23777	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Fran	cic D	5. Indicate Type of Lease	- 1
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Flan	cos DITO	STATE X FEE	_
	Santa Fe, NM 8/	10/2	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87  CES AND REPORTS ON WENG SALS TO DRULL OR TO DEEPEN OR PLU CATION FOR PERMIT" (FORM C-101) FO  Gas Well  Other INJ  TIMBERS ENERGY, LLC	GBAN TO A-EN	212470	
SUNIDRY NOT	ICES AND DEPORTS ON WEATH	70, 7	7. Lease Name or Unit Agreement Name	$\dashv$
COO NOT USE THIS FORM FOR PROPO	SALS TO DEST OF TO DEEPEN OF PLUS	IC BANK TO A-	7. Lease Name of Onli Agreement Name	
DIFFERENT RESERVOIR USE "APPLIA	CATION FOR PERMIT" (FORM C-101) FO	R SUCH	NORTHINACAROUR	
PROPOSALS.)	, at the second	~	NORTH VAC ABO UNIT	
1. Type of Well: Oil Well	Gas Well  Other INI	~	8. Well Number 209	
2. Name of Operator			9. OGRID Number	$\neg$
CROSS	TIMBERS ENERGY, LLC		298299	
3. Address of Operator	AMADEM DATEM AT HER		10. Pool name or Wildcat	_
<u>-</u>		FIX 54100		
400 W Z	<u>TH STREET, FORT WORTH</u>	.TX 76102	NORTH VAC ABO	
4. Well Location	•			
Unit Letter:	1980feet from theS	line and	1780 feet from theE line	:
Section 22	Township 17-S Ra	nge 34-E	NMPM County LEA	
7,4	11. Elevation (Show whether DR,			
	4050 GR	IGD, KI, GK, CIC.)		
	4030 GR			
12. Check A	Appropriate Box to Indicate Na	ature of Notice,	Report or Other Data	
NOTICE OF IN			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUĞ AND ABANDON 🔲	REMEDIAL WORL	K ☐ ALTERING CASING ☐	]
TEMPORARILY ABANDÓN 🔛	CHANGE PLANS	COMMENCE DRI	LLING OPNS. ☐ P AND A ☐	j
PULL OR ALTER CASING 🗀	MULTIPLE COMPL	CASING/CEMENT	r JOB 🔲	
DOWNHOLE COMMINGLE	<del>-</del>		<del>-</del>	
CLOSED-LOOP SYSTEM	P.C.			
OTHER:REVISION - ORIGINAL	ĽŃOI APVD 6/14/19	OTHER:		1
			give pertinent dates, including estimated da	<u></u>
13. Describe proposed of comp				ate
of starting any proposed we	NELL SEE RILLE 10 15 7 14 NIMAC	HOT MINITIMIA I OF	nnietions. Attach wellhore diagram of	ate
of starting any proposed wo		. For Multiple Con	npletions: Attach wellbore diagram of	ate
proposed completion or rec	ompletion.	. For Multiple Con	npletions: Attach wellbore diagram of	ate
proposed completion or rec REVISED PKR DEPT	ompletion. 'H TO 8480'	. For Multiple Con	npletions: Attach wellbore diagram of	ate
proposed completion or rec	ompletion. 'H TO 8480'	. For Multiple Con	npletions: Attach wellbore diagram of	ate
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1	ompletion. H TO 8480' 9	. For Multiple Con	npletions: Attach wellbore diagram of	ate
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a	ompletion. H TO 8480' 9 and packer and scan tbg.	. For Multiple Con	npletions: Attach wellbore diagram of	ate
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is	ompletion. H TO 8480' 9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC		npletions: Attach wellbore diagram of	ate
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB	ompletion. H TO 8480' 9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or	better		ate
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB	ompletion. H TO 8480' 9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or	better		ate
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S	ompletion. H TO 8480' 9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or	better new packer, if r	needed). Test in the hole.	ate
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr	ompletion. H TO 8480' 9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu	better new packer, if r	needed). Test in the hole. to 350 psi.	ate
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pro-	ompletion.  H TO 8480'  nd packer and scan tbg.  s 2-3/8", 4.6#, J-55 IPC  tbg. Replace w/ 2-3/8" YB or  tring and redressed packer (or  revious depth of 8480'. Pressu	better new packer, if re re test backside to with packer fluid	needed). Test in the hole. to 350 psi. l. Latch back in to packer. Contact	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pro-	ompletion. H TO 8480' 9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu	better new packer, if re re test backside to with packer fluid	needed). Test in the hole. to 350 psi. l. Latch back in to packer. Contact	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pro-	ompletion.  H TO 8480'  nd packer and scan tbg.  s 2-3/8", 4.6#, J-55 IPC  tbg. Replace w/ 2-3/8" YB or  tring and redressed packer (or  revious depth of 8480'. Pressu	better new packer, if re re test backside to with packer fluid	needed). Test in the hole. to 350 psi. l. Latch back in to packer. Contact	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pro-	ompletion.  H TO 8480'  nd packer and scan tbg.  s 2-3/8", 4.6#, J-55 IPC  tbg. Replace w/ 2-3/8" YB or  tring and redressed packer (or  revious depth of 8480'. Pressu	better new packer, if re re test backside to with packer fluid	needed). Test in the hole. to 350 psi.	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480' 9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu n/off tool. Circulate backside vest per OCD representative's designated	better new packer, if re re test backside to with packer fluic directive.	needed). Test in the hole. to 350 psi. l. Latch back in to packer. Contact	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480'  9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu n/off tool. Circulate backside west per OCD representative's design Rig Release Day	better new packer, if re re test backside s with packer fluid lirective.	needed). Test in the hole. to 350 psi. I. Latch back in to packer. Contact	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480'  9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu n/off tool. Circulate backside west per OCD representative's design Rig Release Day	better new packer, if re re test backside s with packer fluid lirective.	needed). Test in the hole. to 350 psi. l. Latch back in to packer. Contact	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480'  9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu n/off tool. Circulate backside west per OCD representative's design Rig Release Day	better new packer, if re re test backside s with packer fluid lirective.	needed). Test in the hole. to 350 psi. I. Latch back in to packer. Contact	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480'  Ind packer and scan tbg. S 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressun/off tool. Circulate backside west per OCD representative's depth of Rig Release Date 2	better new packer, if re test backside swith packer fluid lirective.	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  8556  Perfo 9438	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480'  Ind packer and scan tbg. S 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressun/off tool. Circulate backside west per OCD representative's depth of Rig Release Date 2	better new packer, if re test backside swith packer fluid lirective.	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  8556  Perfo 9438	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480'  Ind packer and scan tbg. S 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressun/off tool. Circulate backside west per OCD representative's depth of Rig Release Date 2	better new packer, if re test backside swith packer fluid lirective.	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  8556  Perfo 9438	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480'  9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu n/off tool. Circulate backside west per OCD representative's depth of Rig Release Date  Rig Release Date  2	better new packer, if nee test backside to with packer fluid lirective.  te:	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  Performance of the second of the secon	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/1  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to	ompletion. H TO 8480'  9 and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu n/off tool. Circulate backside west per OCD representative's depth of Rig Release Date  Rig Release Date  2	better new packer, if re test backside swith packer fluid lirective.	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  8556  9435-1	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/16 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to  Spud Date:  05/25/197	ompletion.  H TO 8480'  and packer and scan tbg.  s 2-3/8", 4.6#, J-55 IPC  tbg. Replace w/ 2-3/8" YB or  tring and redressed packer (or  revious depth of 8480'. Pressu  n/off tool. Circulate backside vest per OCD representative's destruction.  Rig Release Date  above is true and complete to the beside of the second of the	better new packer, if retest backside to the test backer fluid directive.  Tee:  St of my knowledge to the test backer fluid to the test backer fl	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  8556  9436-1  06/21/1971  e and belief.  DATE 06/25/2019	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/16 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to  Spud Date:  05/25/197  Thereby certify that the information  SIGNATURE  Type or print name Samanntha A	ompletion.  H TO 8480'  and packer and scan tbg.  s 2-3/8", 4.6#, J-55 IPC  tbg. Replace w/ 2-3/8" YB or  tring and redressed packer (or  revious depth of 8480'. Pressu  n/off tool. Circulate backside vest per OCD representative's destruction.  Rig Release Date  above is true and complete to the beside of the second of the	better new packer, if retest backside to the test backer fluid directive.  Tee:  St of my knowledge to the test backer fluid to the test backer fl	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  Performance of the second of the secon	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/16 1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to  Spud Date:  05/25/197	ompletion.  H TO 8480'  and packer and scan tbg.  s 2-3/8", 4.6#, J-55 IPC  tbg. Replace w/ 2-3/8" YB or  tring and redressed packer (or  revious depth of 8480'. Pressu  n/off tool. Circulate backside vest per OCD representative's destruction.  Rig Release Date  above is true and complete to the beside of the second of the	better new packer, if retest backside to the test backer fluid directive.  Tee:  St of my knowledge to the test backer fluid to the test backer fl	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  8556  9436-1  06/21/1971  e and belief.  DATE 06/25/2019	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/16  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to  Spud Date:  05/25/197  Thereby certify that the information  SIGNATURE  Type or print name Samanntha A For State Use Only	ompletion. H TO 8480'  9  and packer and scan tbg. s 2-3/8", 4.6#, J-55 IPC tbg. Replace w/ 2-3/8" YB or tring and redressed packer (or revious depth of 8480'. Pressu n/off tool. Circulate backside v est per OCD representative's d  Rig Release Date  Above is true and complete to the been serviced and complete to the se	better new packer, if new packer, if new packer fluid with packer fluid lirective.  The stof my knowledge atory Technician savarello@msp	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  8556  9435-1  06/21/1971  e and belief.  DATE 06/25/2019  eartners.com PHONE: 817-334-7747	
proposed completion or rec REVISED PKR DEPT Plan to MIRU 07/08/16  1) POOH w/ tbg a a. Tubing string is b. LD BB, GB, RB 2) RBIH w/ Tbg S 3) Set packer at pr 4) Release from or NMOCD & run MIT to  Spud Date:  05/25/197  Thereby certify that the information  SIGNATURE  Type or print name Samanntha A For State Use Only	ompletion.  H TO 8480'  and packer and scan tbg.  s 2-3/8", 4.6#, J-55 IPC  tbg. Replace w/ 2-3/8" YB or  tring and redressed packer (or  revious depth of 8480'. Pressu  n/off tool. Circulate backside vest per OCD representative's destruction.  Rig Release Date  above is true and complete to the beside of the second of the	better new packer, if new packer, if new packer fluid with packer fluid lirective.  The stof my knowledge atory Technician savarello@msp	needed). Test in the hole. to 350 psi. d. Latch back in to packer. Contact  8556  9436-1  06/21/1971  e and belief.  DATE 06/25/2019	

## CROSS TIMBERS ENERGY, LLC

