Submit 1 Copy To Appropriate District	State of New Me	exico	Form	n C-103
Office <u>District I</u> (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised Jul	y 18, 2013
1625 N French Dr. Hobbs NM 88240		WELL API NO.		
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 D		30-025-34167		
District III = (505) 334-61781 10 BBS 1220 South St. Francis Dr		5. Indicate Type of Lease	ı	
1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE 🛛 FEE	1	
District IV – (505) 476-3460	2019 Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.	
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NJUL 0, 87505				
87505	EPORTS ON WELLS		7. Lease Name or Unit Agreemen	t Nome
(DO NOT USE THIS FORM FOR CONSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		MONUMENT 1 STATE	it Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		MONUMENTISTATE	1	
PROPOSALS.)		8. Well Number #15H		
1. Type of Well: Oil Well				
2. Name of Operator		9. OGRID Number 4323		
CHEVRON USA INC				
3. Address of Operator		10. Pool name or Wildcat		
6301 DEAUVILLE BLVD, MIDLAND, TEXAS 79706		MONUMENT;ABO, NORTH		
4. Well Location				
	feet from the SOUTH line	e and 2310	feet from the WEST line	
	······································			7
	11. Elevation (Show whether DR) 3739' KB	, KKB, KI, GK, etc.)		
	3/39 KB			
12. Check Ap	propriate Box to Indicate N	ature of Notice,	Report or Other Data	
			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WOR			SING 🗌	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.□ P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	「JOB □	
DOWNHOLE COMMINGLE		l .		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				
 .	TION 🗆	OTHER:		
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC			d give pertinent dates, including esti	 mated date
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet	ed operations. (Clearly state all	pertinent details, and	I give pertinent dates, including esti	
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMAG	pertinent details, and		
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMAG	pertinent details, and		
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMAOnpletion.	pertinent details, and C. For Multiple Con	npletions: Attach wellbore diagram	of
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recompleted.	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMAOnpletion. HUT IN SINCE JUNE 14, 2019	pertinent details, and C. For Multiple Con	npletions: Attach wellbore diagram	of
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or reconstant THE SUBJECT WELL HAS BEEN SI	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMAOnpletion. HUT IN SINCE JUNE 14, 2019	pertinent details, and C. For Multiple Con	npletions: Attach wellbore diagram	of
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or reconstant THE SUBJECT WELL HAS BEEN SI	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMA on a pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION.	Dertinent details, and C. For Multiple Conduction DUE TO DOWNHO	npletions: Attach wellbore diagram	of ANS TO
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recommendation. THE SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS.	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMAGO PROPERTY. SEE RULE 19.15.7.14 NMAGO PROPERTY. SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION OF THE PULLING UNIT, LOAD AND TABLE TO PROPERTY.	pertinent details, and C. For Multiple Conduction DUE TO DOWNHO ON. TEST THE TUBINO	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recommendation. THE SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE START THE SUBJECT WELL AS FOLLOWS.	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMAGO PROPERTY. SEE RULE 19.15.7.14 NMAGO PROPERTY. SEE RULE 19.15.7.14 NMAGO PROPERTY. SEE RODUCTION TO THE PART, FISH RODS AT TO THE PART, FISH RODS AT	Dertinent details, and C. For Multiple Conduction DUE TO DOWNHO ON. TEST THE TUBINO ND PUMP. REPLACE	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recommendation. THE SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE SWITH RODS, INSPECTING DOWN.	ed operations. (Clearly state all).) SEE RULE 19.15.7.14 NMA on pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO I	Dertinent details, and C. For Multiple Conduction TO DOWNHO TO DOWNHO TO THE TUBING TO PUMP. REPLACE TO PIMP SHOP SHOP TO PIMP SHOP SHOP TO PIMP SHOP SHOP SHOP SHOP SHOP SHOP SHOP SHO	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recommendated that the SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED U	ed operations. (Clearly state all).) SEE RULE 19.15.7.14 NMA on pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO I	Dertinent details, and C. For Multiple Conduction TO DOWNHO TO DOWNHO TO THE TUBING TO PUMP. REPLACE TO PIMP SHOP SHOP TO PIMP SHOP SHOP TO PIMP SHOP SHOP SHOP SHOP SHOP SHOP SHOP SHO	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recommendated that the SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED U	ed operations. (Clearly state all).) SEE RULE 19.15.7.14 NMA on pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO I	Dertinent details, and C. For Multiple Conduction TO DOWNHO TO DOWNHO TO THE TUBING TO PUMP. REPLACE TO PIMP SHOP SHOP TO PIMP SHOP SHOP TO PIMP SHOP SHOP SHOP SHOP SHOP SHOP SHOP SHO	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recommendated that the SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED U	ed operations. (Clearly state all).) SEE RULE 19.15.7.14 NMA on pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO I	Dertinent details, and C. For Multiple Conduction TO DOWNHO TO DOWNHO TO THE TUBING TO PUMP. REPLACE TO PIMP SHOP SHOP TO PIMP SHOP SHOP TO PIMP SHOP SHOP SHOP SHOP SHOP SHOP SHOP SHO	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recommendated that the SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED U	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMA on pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION TO THE PART, FISH RODS AND SED RODS. SEND PUMP TO BENT AND RIG DOWN ONCE IT.	Dertinent details, and C. For Multiple Conduction CON. TEST THE TUBING ND PUMP. REPLACE PUMP SHOP TO PER PUMP ACTION IS	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recommendated that the SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED U	ed operations. (Clearly state all).) SEE RULE 19.15.7.14 NMA on pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO I	Dertinent details, and C. For Multiple Conduction CON. TEST THE TUBING ND PUMP. REPLACE PUMP SHOP TO PER PUMP ACTION IS	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or reconstance. THE SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM.	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMA on pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION TO THE PART, FISH RODS AND SED RODS. SEND PUMP TO BENT AND RIG DOWN ONCE IT.	Dertinent details, and C. For Multiple Conduction CON. TEST THE TUBING ND PUMP. REPLACE PUMP SHOP TO PER PUMP ACTION IS	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or reconstance. THE SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM.	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMA on pletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION TO THE PART, FISH RODS AND SED RODS. SEND PUMP TO BENT AND RIG DOWN ONCE IT.	Dertinent details, and C. For Multiple Conduction CON. TEST THE TUBING ND PUMP. REPLACE PUMP SHOP TO PER PUMP ACTION IS	npletions: Attach wellbore diagram OLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or recompleted. The SUBJECT WELL HAS BEEN STREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date:	ed operations. (Clearly state all j.). SEE RULE 19.15.7.14 NMAGINPLETION. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION TO THE PART, FISH RODS AND TO THE PART AND RIG DOWN ONCE TO THE PART AND RIG PROWN ONCE TO THE PART AND RIGHT PROWN ONCE T	pertinent details, and C. For Multiple Conduction CON. TEST THE TUBING ND PUMP. REPLACE PUMP SHOP TO PER PUMP ACTION IS nate:	DLE PROBLEMS. CHEVRON PLA TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND RE VERIFIED.	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or reconstance. THE SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM.	ed operations. (Clearly state all j.). SEE RULE 19.15.7.14 NMAGINPLETION. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION TO THE PART, FISH RODS AND TO THE PART AND RIG DOWN ONCE TO THE PART AND RIG PROWN ONCE TO THE PART AND RIGHT PROWN ONCE T	pertinent details, and C. For Multiple Conduction CON. TEST THE TUBING ND PUMP. REPLACE PUMP SHOP TO PER PUMP ACTION IS nate:	DLE PROBLEMS. CHEVRON PLA TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND RE VERIFIED.	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUCT 13. Describe proposed or complet of starting any proposed work proposed completion or reconstruction. THE SUBJECT WELL HAS BEEN STREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date:	ed operations. (Clearly state all plants). SEE RULE 19.15.7.14 NMAGINPLETON. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO BENT AND RIG DOWN ONCE BENT AND RIG RELEASE DESCRIPTION OF THE	pertinent details, and C. For Multiple Conduction DUE TO DOWNHO ON. TEST THE TUBINO ND PUMP. REPLACE PUMP SHOP TO PERFUMP ACTION IS pump action.	DLE PROBLEMS. CHEVRON PLAGE TO CONFIRM TUBING IS GOODE SOON AND BELOW ERFORM A TEARDOWN AND REVERIFIED.	of ANS TO D. POOH
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUCT 13. Describe proposed or complet of starting any proposed work proposed completion or reconstruction. THE SUBJECT WELL HAS BEEN STREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date:	ed operations. (Clearly state all plants). SEE RULE 19.15.7.14 NMAGINPLETON. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO BENT AND RIG DOWN ONCE BENT AND RIG RELEASE DESCRIPTION OF THE	pertinent details, and C. For Multiple Conduction DUE TO DOWNHO ON. TEST THE TUBINO ND PUMP. REPLACE PUMP SHOP TO PERFUMP ACTION IS pump action.	DLE PROBLEMS. CHEVRON PLAGE TO CONFIRM TUBING IS GOODE SOON AND BELOW ERFORM A TEARDOWN AND REVERIFIED.	ANS TO D. POOH V &R.
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUCT 13. Describe proposed or complet of starting any proposed work proposed completion or reconstruction. THE SUBJECT WELL HAS BEEN STREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date:	ed operations. (Clearly state all j.). SEE RULE 19.15.7.14 NMAGINPLETION. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCTION TO THE PART, FISH RODS AND TO THE PART AND RIG DOWN ONCE TO THE PART AND RIG PROWN ONCE TO THE PART AND RIGHT PROWN ONCE T	pertinent details, and C. For Multiple Conduction DUE TO DOWNHO ON. TEST THE TUBINO ND PUMP. REPLACE PUMP SHOP TO PERFUMP ACTION IS pump action.	DLE PROBLEMS. CHEVRON PLAGE TO CONFIRM TUBING IS GOODE SOON AND BELOW ERFORM A TEARDOWN AND REVERIFIED.	ANS TO D. POOH V &R.
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUC 13. Describe proposed or complet of starting any proposed work proposed completion or reconstruction. THE SUBJECT WELL HAS BEEN SIREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date:	ed operations. (Clearly state all plane). SEE RULE 19.15.7.14 NMAC appletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO BENT AND RIG DOWN ONCE IT COVER IS true and complete to the beautiful power of the part of	pertinent details, and C. For Multiple Condition of Condi	DLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND REVERIFIED. e and belief. DATE 07/02/201	ANS TO D. POOH V &R.
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUCT 13. Describe proposed or complet of starting any proposed work proposed completion or recompleted. The SUBJECT WELL HAS BEEN STREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date: I hereby certify that the information about the subject of the subject	ed operations. (Clearly state all plane). SEE RULE 19.15.7.14 NMAC appletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO BENT AND RIG DOWN ONCE IT COVER IS true and complete to the beautiful power of the part of	pertinent details, and C. For Multiple Condition of Condi	DLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND REVERIFIED. e and belief. DATE 07/02/201	ANS TO D. POOH V &R.
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUCT 13. Describe proposed or complet of starting any proposed work proposed completion or reconstruction. THE SUBJECT WELL HAS BEEN STREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date: I hereby certify that the information about the start of the start	ed operations. (Clearly state all plane). SEE RULE 19.15.7.14 NMAC appletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO 1 ENT AND RIG DOWN ONCE IT AND RIG DOWN ONCE IT TITLE PER CA-MURILLO E-mail address:	pertinent details, and c. For Multiple Condition of Condi	DLE PROBLEMS. CHEVRON PLA TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R. VERIFIED. The and belief. The property of the confidence of the confi	of ANS TO D. POOH V &R.
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUCT 13. Describe proposed or complet of starting any proposed work proposed completion or reconstruction. THE SUBJECT WELL HAS BEEN STREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date: I hereby certify that the information about the start of the start	ed operations. (Clearly state all plane). SEE RULE 19.15.7.14 NMAC appletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO 1 ENT AND RIG DOWN ONCE IT AND RIG DOWN ONCE IT TITLE PER CA-MURILLO E-mail address:	pertinent details, and c. For Multiple Condition of Condi	DLE PROBLEMS. CHEVRON PLA TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND R. VERIFIED. The and belief. The property of the confidence of the confi	of ANS TO D. POOH V &R.
CLOSED-LOOP SYSTEM OTHER: RETURN TO PRODUCT 13. Describe proposed or complet of starting any proposed work proposed completion or recompleted. The SUBJECT WELL HAS BEEN STREPAIR THE WELL AS FOLLOWS. THE JOB PLAN IS TO RIG UP THE WITH RODS, INSPECTING DOWN PARTED ROD WITH INSPECTED URUN BACK IN WITH ALL EQUIPM. Spud Date: I hereby certify that the information about the subject of the subject	ed operations. (Clearly state all plane). SEE RULE 19.15.7.14 NMAC appletion. HUT IN SINCE JUNE 14, 2019 AND RETURN TO PRODUCT! PULLING UNIT, LOAD AND TO THE PART, FISH RODS AND SEED RODS. SEND PUMP TO 1 ENT AND RIG DOWN ONCE IT AND RIG DOWN ONCE IT TITLE PER CA-MURILLO E-mail address:	pertinent details, and c. For Multiple Condition of Condi	DLE PROBLEMS. CHEVRON PLA G TO CONFIRM TUBING IS GOO CE 5 RODS ABOVE AND BELOV ERFORM A TEARDOWN AND REVERIFIED. e and belief. DATE 07/02/201	of ANS TO D. POOH V &R.