#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Operator

FORM APPROVED OMB NO. 1004-0137 pires: January 31, 2018

)ľ		Expires
	5.	Lease Serial No.

	5. Lease	٥
NDRY NOTICES AND REPORTS ON WELLS	NML	.C
use this form for proposals to drill or to re-enter an		

SUI 028784C Do not u 6. If Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8 Well Name and No GRAYBURG DEEP 25 FED 5 . ☑ Oil Well ☐ Gas Well ☐ Other Name of Operator **GREG BRYANT** Contact: API Well No. CONOCÓPHILLIPS COMPANY E-Mail: GREG.BRYANT@BASICENERGYSERVICES.COM 30-015-03083-00-S1 3b. Phone No. (include area code)
Ph: 432-563-3364
Fx: 432-563-3364

10. Field and Pool or Exploratory Are UNDESIGNATED

11. County or Parish, State
EDDY COUNTY, NM

TO INDICATE TO TURE OF NOTICE, REPORT, OR OTHER DATA 3a. Address 10. Field and Pool or Exploratory Area HOUSTON, TX 77252 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 25 T17\$ R29E NENE 330FNL 660FEL 12. CHECK THE APPROPRIATE BOX(ES) TO INDIC OF'ACTION TYPE OF SUBMISSION ☐ Acidize □ Deepen □ Production (Start/Resume) ■ Water Shut-Off ■ Notice of Intent ■ Alter Casing ■ Well Integrity ☐ Hydraulic Fracturing □ Reclamation ☐ Subsequent Report □ Casing Repair ■ New Construction □ Recomplete □ Other ☐ Final Abandonment Notice □ Change Plans Plug and Abandon ☐ Temporarily Abandon □ Convert to Injection Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. SFF ATTACHED FOR POOH & LD Prod equipment RIH WL - Set 5-1/2 CIBP @ 6555'. Circ hole w/ MLF. Cap BP w/ 25sx cmt to 6455' CONDITIONS OF APPROVAL Spot 25sx cmt @ 5547' - 5427' 150' Ala SX from 4030-3880. WOCTA (DVT) Spot 25sx cmt @ 4178' - 4058' Perf & Sqz 55sx cmt @ 2868' - 2647'. WOC-Tag Perf & Sqz 40sx cmt @ 2102' - 2002'. WOC-Tag Perf & Sqz 50sx cmt @ 1454' - 1354'. WOC-Tag 825. Perf @ 475, SQZ ent to 375. woc Tag 8) Perf & Sqz 505x cmt @ 1705 - 955'. WOC-Tag 9 2 5 6 10) Perf & Circ 40sx cmt @ 60' - 3' 11) Verify cmt @ surface. RDMO. Clean location, cut off WH & anchors. Install P&A marker. 14. I hereby certify that the foregoing is true and correct. Electronic Submission #461997 verified by the BLM Well Information System For CONOCOPHILLIPS COMPANY, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 04/18/2019 (19PP1729SE) Name (Printed/Typed) GREG BRYANT Title **AGENT** Signature (Electronic Submission) Date 04/17/2019 THIS SPACE FOR FEDERAL OR STATE OFFICE USE 526-19 \_Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)
\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*
FOR RECORD ONLY + NMOCD 7-11-19

## WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Surface   State   St	RKB @ 3615' DF @ 3615' GL @ 3504'	Subarea Hotals (West) Lease 5 Wet No Grayburg Deep 25 Federal Unit # 005
Sept Tubing & Rods Table: string cetals	6-5/9" 32#/n to 1404*	Field Bear Grass ABO Date Spudded 5/26/1960 API Number 30-015-03083  Operator Number Lease ID
### PBID @ 6535  TO @ 1725  ### PABOISHY Bear Grass Draw.  ### Perfaction 6579/  #### PBID @ 6535  TO @ 1725  SA 2747 W	5-112" 17#th to 6838" J. 5 4 mg, E. Chard w/ 650 SX J. 5 4 mg, E. TOC - 3980' By Unknown	275 5 × 7 12 Stage
375 SX /St Stage  7002  T-Salt 425  B-Salt 875  Ou 2012 2107  SA 2747 N		
	Perta 6055 0679	7-501 425 B-51 875 On 2012 2107 SA 2747 M GL 4178 -

# WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

P/S 40 sx 60'-3' Surface  8-5/8' 328/ft, to 1404' Cmt d w/525 SX TOC - 102' By Unknown  P/S 40 sx 1055'-955' Tag  P/S 50 sx 1454'-1354' Tag  Production  5-1/2', 178/ft to 6838' Cmt'd w/ 650 SX TOC - 3980' By Unknown  P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Gross Draw)  Perf d 6655' - 6679'  Perf d 6655' - 6679'	RKB	@ 3619	<del></del> _
P/S 40 sx 60'-3' Surface 8-5/8' 328//II, to 1404' Cmtd w/525 SX TOC - 102' By Unknown P/S 40 sx 1055'-955' Tag P/S 50 sx 1454'-1354' Tag Production 5-1/2', 178//II to 6838' Cmt'd w/ 650 SX TOC - 3980' Fly Unknown P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Grass Draw) Perfd 8695' - 6679'	DF GI	@ 3619	<del></del>
Surface 8-5/8* 32#/ft, to 1404* Cmt d w/525 SX TOC - 102* By Unknown  P/S 40 sx 1055*-955* Tag  P/S 50 sx 1454*-1354* Tag  Production 5-1/2*, 17#/ft to 6838* Cmt'd w/ 650 SX TOC - 3980* Ry Unknown P/S 40 sx 2102*-2002* Tag  P/S 55 sx 2868*-2647* Tag  25 sx 4178*-4058*  25 sx 4178*-4058*  25 sx 6555*-6455* Set CIBP @ 6555* ABO/SH* (Bear Gross Draw)  Perf d 8655* - 6675*	-	<u> </u>	<del></del>
8-5/8" 328/ft, to 1404' Cmt d w/525 SX TOC - 102' By Unknown  P/S 40 sx 1055'-955' Tag  Production 5-1/2", 178/ft to 6838' Cmt'd w/ 650 SX TOC - 3980' By Unknown  P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Gross Grow)  Perf d 6655' - 6679'			P/5 40 sx 60'-3'
Cmtd w/525 SX TOC - 102' By Unknown  P/S 40 sx 1055'-955' Tag  P/S 50 sx 1454'-1354' Tag  Production 5-1/2', 17#/It to 6838' Cmt'd w/ 650 SX TOC - 3980' By Unknown P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Gross Grow)  Perfd 6655' - 6679'			7 <del>-4</del>
P/S 40 sx 1055'-955' Tag  P/S 40 sx 1055'-955' Tag  P/S 50 sx 1454'-1354' Tag  Production  5-1/2', 17#/It to 6838'  Cmt'd w/ 650 SX  TOC - 3980' By Unknown  P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455'  Set CIBP @ 6555'  ABO/SH* (Bear Gross Oraw)  Perfd 6655' - 6675'	-11	1 1	
P/S 40 sx 1055'-955' Tag  P/S 50 sx 1434'-1354' Tag  Production 5-1/2', 17#/It to 6838' Cmt'd w/ 650 SX TOC - 3980' Fly Unknown P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Grass Draw)  Perfd 6655' - 6675'	11		
Production 5-1/2*, 17#/It to 6838* Cmt'd w/ 650 SX TOC - 3980* By Unknown PrS 40 sx 2102*-2002* Tag  PrS 55 sx 2868*-2647* Tag  25 sx 4178*-4058*  25 sx 6555*-6455* Set CIBP @ 6555* ABO/SH* (Bear Gross Draw)  Perfd 6655*-6679*			1 100 - 102 By Onthown
Production 5-1/2*, 178/ft to 6838* Cmt'd w/ 650 SX TOC - 3980* Fly Unknown P/S 40 sx 2102*-2002* Tag  P/S 55 sx 2868*-2647* Tag  25 sx 4178*-4058*  25 sx 6555*-6455* Set CIBP @ 6555* ABO/SH* (Bear Grass Draw)  Perfd 6655*-6675*			P/S 40 sx 1055'-955' Tag
5-1/2", 17#/It to 6838' Cmt'd w/ 650 SX TOC - 3980' Fly Unknown P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Gross Draw)  Perf d 6655' - 6679'			P/S 50 sx 1454'-1354' Tag
5-1/2", 17#/It to 6838' Cmt'd w/ 650 SX TOC - 3980' Fly Unknown P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Gross Draw)  Perf d 6655' - 6679'			Production
Cmt'd w/ 650 SX TOC - 3980' Fly Unknown P/S 40 sx 2102'-2002' Tag  P/S 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Grass Draw)  Perfd 6655' - 6679'		1 1	1
P(\$ 40 sx 2102'-2002' Tag  P(\$ 55 sx 2868'-2647' Tag  25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Grass Draw)  Perfd 8655' - 6675'			•
PBTD @ 6838*	- 1		TOC - 3980' By Unknown
25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Grass Draw)  Perfd 6655' - 6675'	- 1		
25 sx 4178'-4058'  25 sx 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Grass Draw)  Perfd 6655' - 6675'			
25 6x 5547-5427  25 6x 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Grass Draw) Perfd 8655' - 6675'			P/S 55 sx 2868'-2647' Tag
25 s x 6555'-6455' Set CIBP @ 6555' ABO/SH' (Bear Grass Draw) Perf d 8655' - 6675'			25 sx 4178'-4058'
Set CIBP @ 6555' ABO/S+1' (Bear Grass Draw) Perfd 8655' - 6679'  PerfD @ 6838'			25 6x 5547-5427
Set CIBP @ 6555' ABO/S+1' (Bear Grass Draw) Perfd 8655' - 6679'  PerfD @ 6838'	ĺ	1 1	
ABO/SH (Bear Grass Graw)  Perfd 8655 - 6679'  Perp @ 6838'	- 1		25 s x 6555'-6455'
Perf d 6655' - 6675'			
PETD @ 6835	$\equiv$	Ξ	ABO/SH" (Bear Grass Draw)
PETD @ 6835	=	= =	
	77	- -	Pend 6633 - 6679
1D (© 1225	1	<b>LEADTING</b>	TO @ 7225

Subarea	Hobbs (	West)			
Lease & Well No		Grayburg Deep 25 Federal Unit # 005			_
Legal Description	ภ	SEC:25A, T-17	5 R-29E N	E NE	
County	Eddy		State	New Mexico	
Fiela	Bear Grass ABO		<del>_</del>		
Date Spudded		5/26/1960			
API Number	30-015-	03083			

Operator Number: Lease ID: Field Number.

Date 2/20/2019

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted