

Office Submit I Copy To Appropriate District	State of Nev	v Mexico		Form C-103				
<u>District I</u> – (575) 393-6161	Energy, Minerals and	Natural Resources		Revised August 1, 2011				
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.					
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVAT	ION DIVISION	30-025-33633					
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lea					
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, Ni	M 87505	STATE X 6. State Oil & Gas Lea	FEE				
1220 S. St. Francis Dr. Santa Fe. NM	•		0. State Off & Gas Lea	se No.				
87505	ICES AND REPORTS ON WI	CD						
SUNDRY NOT	CES AND REPORTS ON WI	ABBACK TO A	7. Lease Name or Unit	Agreement Name				
DIFFERENT RESERVOIR. USE "APPLIA	CATION FOR PERMIT" (FORM O	OI) FOR SUCH OIL	THE COLUC CTATE					
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well X	`	11 1N 20 LOIS	TRES EQUIS STATE 8. Well Number					
1. Type of Well: Oil Well X	Gas Well Other	RECEIVED	001					
2. Name of Operator		SECENTE	9. OGRID Number					
CIMAREX ENERGY CO. OF CO	LORADO	KEY	162683					
3. Address of Operator		•	10. Pool name or Wild	cat				
600 N. MARIENFELD, SUITE 60	0, MIDLAND, TEXAS 79701		TRIPLE X					
4. Well Location								
Unit Letter J: 1980 feet from the SOUTH line and 1980 feet from the EAST line								
Section 06	Township 24S	Range 33E	NMPM	County LEA				
	11. Elevation (Show whether							
	3,633' -	GR						
	18	h.						
12. Check A	Appropriate Box to Indica	te Nature of Notice.	Report or Other Data	1				
12. 0	appropriate Bon to Blanca		report of ourer Dun	•				
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPOR	RT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON X			ERING CASING 🗌				
TEMPORARILY ABANDON								
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	「JOB □					
DOWNHOLE COMMINGLE			•					
OTHER:		OTHER:						
13. Describe proposed or comp	leted operations (Clearly state		d give pertinent dates inc	·luding estimated date				
	ork). SEE RULE 19.15.7.14 N							
proposed completion or rec		Marc. To: Manipie Co.	inproductions. Tricator world	10 Glagiani 01				
1) SET 5-1/2" CIBP @ 10.050'; PU		-9,850'; CIRC. WELL W	// M.L.F.					
2) PUMP 25 SXS. CMT. @ 9,080'-8				-				
3) PUMP 25 SXS. CMT. @ 7,170'-								
		VOC X TAG CMT. PLU	G.	4) PUMP 25 SXS. CMT. @ 5,068'-4,865' (8-5/8" CSG.SHOE); WOC X TAG CMT. PLUG.				
	5) CUT X PULL 5-1/2" CSG. @ +/-3,750'.							
6) PUMP 35 SXS. CMT. @ 3,815'-3,685' (5-1/2" CSG.CUT, B/SALT); WOC X TAG CMT. PLUG.								
7) DUMD 70 CVC CMT 1 2221 1 1.								
7) PUMP 70 SXS. CMT. 1,332'-1,148) PLIMP 35 SXS. CMT. @ 585'-48	46' (T/SALT, T/ANHY.); WO	C X TAG CMT. PLUG.						
8) PUMP 35 SXS. CMT. @ 585'-48	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO	C X TAG CMT. PLUG. C X TAG CMT. PLUG.						
	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO .ING ALL ANNULI, 40 SXS.	C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'.		EEL PLATE TO				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLH	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO .ING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM	C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. C. TO SURF. ON ALL A	ANNULI; WELD ON ST					
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO JING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. BELOW Grown	C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A	INNULI; WELD ON STI	e covering				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO JING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. BELOW Grown PLAN TO USE THE CLOSEI	C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A	INNULI; WELD ON STI	e covering				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO JING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. BELOW Grown PLAN TO USE THE CLOSEI	C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A	INNULI; WELD ON STI d picture Befor	e covering				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLH CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO ING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. BELOW Grown PLAN TO USE THE CLOSEI DCD RULE 19.15.17.	C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A	INNULI; WELD ON STI d picture Befor	e covering				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO JING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. BELOW Grown PLAN TO USE THE CLOSEI	C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A	ANNULI; WELD ON STI	e Covering AUL CONTENTS				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date:	46' (T/SALT, T/ANHY.); WO 15' (11-3/4" CSG.SHOE); WO 16' (11-3/4" CSG.SHOE)	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac	e Covering AUL CONTENTS hed				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date:	46' (T/SALT, T/ANHY.); WO 15' (11-3/4" CSG.SHOE); WO 16' (11-3/4" CSG.SHOE)	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac	e Covering AUL CONTENTS hed				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date:	46' (T/SALT, T/ANHY.); WO 15' (11-3/4" CSG.SHOE); WO 16' (11-3/4" CSG.SHOE)	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac	e Covering AUL CONTENTS hed				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLH CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C	46' (T/SALT, T/ANHY.); WO 15' (11-3/4" CSG.SHOE); WO 16' (11-3/4" CSG.SHOE)	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac	e Covering AUL CONTENTS hed				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date:	46' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO 5' (11-3/4" CSG.SHOE); WO ING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. Below grown PLAN TO USE THE CLOSED CCD RULE 19.15.17. Rig Relean above is true and complete to the	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac	e covering AUL CONTENTS hed Approval				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date:	46' (T/SALT, T/ANHY.); WO 15' (11-3/4" CSG.SHOE); WO 16' (11-3/4" CSG.SHOE)	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac	e Covering AUL CONTENTS hed				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date: I hereby certify that the information	A6' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO 5' (11-3/4" CSG.SHOE); WO ING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. Below grown PLAN TO USE THE CLOSED DCD RULE 19.15.17. Rig Release above is true and complete to the	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac	e covering AUL CONTENTS hed Approval				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date:	A6' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO 5' (11-3/4" CSG.SHOE); WO ING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. Below grown PLAN TO USE THE CLOSED DCD RULE 19.15.17. Rig Release above is true and complete to the	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac	e Covering AUL CONTENTS hed Approval				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date: I hereby certify that the information SIGNATURE Type or print name: DAVID A. EY	A6' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO ING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. Below grown PLAN TO USE THE CLOSED CCD RULE 19.15.17. Rig Release TITLE: A	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date: the best of my knowledge AGENT dress: deyler@milagro-	See Attac Conditions of And Delease and Delease Phone:	AUL CONTENTS hed Approval 06/17/19 432.687.3033				
8) PUMP 35 SXS. CMT. @ 585'-48 9) PERF. X CIRC. TO SURF., FILL 10)DIG OUT X CUT OFF WELLHI CSGS. X INSTALL DRY HOLE M DURING THIS PROCEDURE WE TO REQUIRED DISPOSAL, PER C Spud Date: I hereby certify that the information SIGNATURE Type or print name: DAVID A. EY	A6' (T/SALT, T/ANHY.); WO 5' (11-3/4" CSG.SHOE); WO ING ALL ANNULI, 40 SXS. EAD 3' B.G.L.; VERIFY CM ARKER. Below grown PLAN TO USE THE CLOSED CCD RULE 19.15.17. Rig Release TITLE: A	C X TAG CMT. PLUG. C X TAG CMT. PLUG. C X TAG CMT. PLUG. CMT. @ 63'-3'. T. TO SURF. ON ALL A MACKER SEN D-LOOP SYSTEM W/ A se Date:	See Attac Conditions of And Delease and Delease Phone:	e Covering AUL CONTENTS hed Approval				



CIMAREX

T/ANHY. ~ 1,196' T/SALT. ~ 1, 282' B/SALT. ~ 3,750' T/OLWR.~ 5,018' T/BNSG. ~ 8,990'



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.