Office	State of New Mexic		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-025-38236	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DI	VISION 5 Indicate Type of	f Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis	Dr. STATE	FEE 🛛
District IV - (505) 476-3460	Santa Fe, NM 87503	6. State Oil & Gas	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		ACK TO A Lou Wortham 11	Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SU	CH 8. Well Number: 3	3
1. Type of Well: Oil Well	Gas Well 🔲 Other 🔲		
2. Name of Operator		9. OGRID Number	г
Chevron USA, Inc.		4323	
3. Address of Operator	1 mil =0=04	10. Pool name or V	
6301 Deauville Blvd., Midland	d, TX 79706	Eunice, San Andre	es, South
4. Well Location			
	om the North line and 1547 feet from the	East line	
Section 11 Township 2	2S Range 37E, NMPM, County Lea		
	11. Elevation (Show whether DR, RK	3, RT, GR, etc.)	
	3346' GL		· · · · · · · · · · · · · · · · · · ·
			Vo
12. Check	Appropriate Box to Indicate Natur	e of Notice, Report or Other D	Data T
NOTICE OF I	NTENTION TO:	SUBSEQUENT REP	OPT OF:
PERFORM REMEDIAL WORK			ALTERING CASING
TEMPORARILY ABANDON		_	PAND A
PULL OR ALTER CASING		SING/CEMENT JOB	AND A
DOWNHOLE COMMINGLE		omerozimizity dob	
	· ·		
OTHER:		HER: TEMPORARILY	
13. Describe proposed or com	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F	ent details, and give pertinent dates	, including estimated date
13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F	ent details, and give pertinent dates or Multiple Completions: Attach we	, including estimated date
13. Describe proposed or com of starting any proposed w proposed completion or re	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned t	nent details, and give pertinent dates or Multiple Completions: Attach we nis well as follows:	, including estimated date
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515	pleted operations. (Clearly state all pertions). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to Completion.	nent details, and give pertinent dates or Multiple Completions: Attach we nis well as follows: @ 3500'-2364'.	, including estimated date Illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to Chevron USA IN	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036	pleted operations. (Clearly state all pertions). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to Completion.	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to Chevron USA IN	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to Chevron USA IN	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23	, including estimated date illbore diagram of
 13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF 	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to Chevron USA IN	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
 13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF 	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of t	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
 13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF 	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of t	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
 13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF 	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of t	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of t	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of t	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF I hereby certify that the information SIGNATURE Ricky Villanueva	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of the complete of the complet	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of the complete of the complet	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF I hereby certify that the information SIGNATURE Ricky Villanueva	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of the complete of the complet	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF I hereby certify that the information SIGNATURE Ricky Villanueva Well P&A Manag	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion and the completion of the complete of the complet	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet Tmy knowledge and belief.	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF I hereby certify that the information SIGNATURE Ricky Villanueva Well P&A Manag	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion. Cut tbg @ 3500'. Pump 120 sacks cmt'. Test csg 1000 psi pass. Pump 70 sacks. Pump 120 sacks cmt @ 1174'-surf. Tope above is true and complete to the best of the complete to th	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet Tmy knowledge and belief.	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF I hereby certify that the information SIGNATURE Ricky Villanueva Well P&A Manag	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion. Cut tbg @ 3500'. Pump 120 sacks cmt'. Test csg 1000 psi pass. Pump 70 sacks. Pump 120 sacks cmt @ 1174'-surf. Tope above is true and complete to the best of the complete to th	nent details, and give pertinent dates or Multiple Completions: Attach we his well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet Tmy knowledge and belief.	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed we proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF I hereby certify that the information SIGNATURE Ricky Villanueva Well P&A Manag E-mail address: ryqg@chevron.com	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion Chevron USA INC abandoned to the completion complete to the graph of the complete to the best of the complete comple	nent details, and give pertinent dates or Multiple Completions: Attach we have mis well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet Tmy knowledge and belief.	, including estimated date illbore diagram of
13. Describe proposed or com of starting any proposed we proposed completion or re 1. 07/27/19 Set CIBP @ 3515 2. 07/29/19 Tag TOC @ 3036 3. 07/30/19 Pump 30 bbl MLF I hereby certify that the information SIGNATURE Ricky Villanueva Well P&A Manag E-mail address: ryqg@chevron.com	pleted operations. (Clearly state all pertiork). SEE RULE 19.15.7.14 NMAC. F completion Chevron USA INC abandoned to the completion. Cut tbg @ 3500'. Pump 120 sacks cmt'. Test csg 1000 psi pass. Pump 70 sacks. Pump 120 sacks cmt @ 1174'-surf. Tope above is true and complete to the best of the complete to th	nent details, and give pertinent dates or Multiple Completions: Attach we have mis well as follows: @ 3500'-2364'. cmt @ 3036'-2351'. Tag TOC @ 23 off w/cmt. Rig down P&A complet Tmy knowledge and belief.	, including estimated date illbore diagram of