Reberle I. Come To Annopolista District		F C 102
Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103 Revised July 18, 2013
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
$\frac{\text{District II}}{\text{District II}} = (575) 748 - 1283$		30-025-32741
811 S. First St., Artesia, NM 88210 OTE CONSERVATION DIVISION District III - (505) 334-6178 1220 South St. Francis CD		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460	Santa POBR7305	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		014036
87505 SUNDRY NOTICES AN	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK-TONA		Kaiser State
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C.IOL) CENED PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well 🛛 Gas Well 🗋 Other		44
2. Name of Operator Mesquite SWD Inc.		9. OGRID Number 161968
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 1479 Carlsbad, NM 88221		Wilson Yates-7 Rvrs
4. Well Location		
Unit Letter F :2310 feet from theNorth line and2310 feet from theWest line		
Section 13 Township 21-S Range 34-E NMPM County Lea		
II. Ele	evation (Show whether DR, RKB, RT, GR, 6 / 3649' GR	elc.)
12. Check Appropr	iate Box to Indicate Nature of Notic	e, Report or Other Data
		JBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUE		
		DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
CLOSED-LOOP SYSTEM		П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
MIRU. ND WH, NU BOP. POOH w/ Prod. Equipment		
RIH WL – Set CIBP @ 3,700'. Circ hole w/ MLF. Pressure test casing Spot 25sx cmt @ 3,700' – 3,600'. WOC-Tag		
Spot 25sx cmt ($(0, 2, 200)^2 - 2, 100^2$).		
Spot 55sx cmt @ 450' - 200'. WOC-Tag PerFd 9queeZe		
Spot-15sx cmt @ 60'=3' PerF J Saueeze 200' TO SU/F POOH. Fill wellbore. Verify cmt @ surface in all annuli		
INSTALL 4"dia 4' tall above ground Marker		
1 FILL / GILL 9 FALL CLOODE FILLING MAINER		
** A closed-loop system will be use	d for all fluids from this wellbore and dispos	ed of required by OCD Rule 19.15.17**
Spud Date: 12/13/94	Rig Release Date:	12/24/94
	I L	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE		
Type or print name Greg Bryant	E-mail address:	PHONE: 432-563-3355
For State Use Only		
APPROVED BY: Key Jut TITLE C.O. A DATE 8-14-19		
Conditions of Approval (if any)		

and the second second



