Submit One Copy To Appropriate District	State of New Mexico	Form C-103				
Office Energy	gy, Minerals and Natural Resources	Revised November 3, 2011				
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.				
811 S. First St., Artesia, NM 88210 OIL	CONSERVATION DIVISION	30-025-37887 5. Indicate Type of Lease				
District III 1000 Rio Brazos Rd., Aztec, NM 87410	District III 1220 South St. Francis Dr.					
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM						
87505 SUNDRY NOTICES AND	PEPOPTS ON WELLS	7. Lease Name or Unit Agreement Name				
		CH WEIR B				
DIFFERENT RESERVOIR. USE "APPLICATION FOR	PERMIT" (FORM C-101) FOR SUCH	8. Well Number				
1 Type of Well' MOil Well Gas Well		13				
2. Name of Operator	HOBDO	9. OGRID Number				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRI DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.) 1. Type of Well: Oil Well Gas Well 2. Name of Operator CHEVRON USA, INC. 3. Address of Operator	a 4 2019					
3. Address of Operator	SEP	10. Pool name or Wildcat				
6301 Deauville Blvd., Midland, TX 79706	TIVED	MONUMENT; BLINEBERRY				
4. Well Location:	the SOUTH line and 2310 f					
Unit Letter_O_:_990feet from	the SOUTH line and 2310 f	eet from the <u>EAST</u> line				
Section 11 Township 20-5	<u>S Range <u>37-E</u> NMPM County</u>	LEA				
	tion (Show whether DR, RKB, RT, GR, et					
3574' GL						
12. Check Appropriate Box to Indicate	Nature of Notice, Report or Other	Data				
NOTICE OF INTENTIO	N TO: SU ND ABANDON C REMEDIAL WO	BSEQUENT REPORT OF:				
—	E PLANS COMMENCE DI COMMENCE DI LE COMPL CASING/CEME					
OTHER:	🔲 🛛 🖾 Location is	ready for OCD inspection after P&A				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.						
		perator's pit permit and closure plan.				
Rat hole and cellar have been filled and lev	eled. Cathodic protection holes have bee	perator's pit permit and closure plan. n properly abandoned.				
	eled. Cathodic protection holes have bee	perator's pit permit and closure plan. n properly abandoned.				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a 	veled. Cathodic protection holes have bee t least 4' above ground level has been set	perator's pit permit and closure plan. n properly abandoned. in concrete. It shows the				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI 	veled. Cathodic protection holes have bee t least 4' above ground level has been set	perator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI 	veled. Cathodic protection holes have been t least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT	perator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T 	veled. Cathodic protection holes have been tt least 4' above ground level has been set E, WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT HE MARKER'S SURFACE.	perator's pit permit and closure plan. n properly abandoned. in concrete. It shows the <u>DUARTER/QUARTER LOCATION OR</u> ION HAS BEEN WELDED OR				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p 	veled. Cathodic protection holes have been tt least 4' above ground level has been set E, WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT HE MARKER'S SURFACE.	perator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. 	veled. Cathodic protection holes have been at least 4' above ground level has been set E, WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT HE MARKER'S SURFACE.	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers has 	veled. Cathodic protection holes have been at least 4' above ground level has been set E, WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT THE MARKER'S SURFACE. possible to original ground contour and ha	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bound level.				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining s 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT THE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below growell on lease, the battery and pit location	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bound level. (s) have been remediated in compliance with				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining s 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT THE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below growell on lease, the battery and pit location	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bound level.				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit pe from lease and well location. All metal bolts and other materials have bee 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and have ave been cut off at least two feet below growell on lease, the battery and pit location ermit and closure plan. All flow lines, pro-	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bound level. (s) have been remediated in compliance with				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit pe from lease and well location. All metal bolts and other materials have bee to be removed.) 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT HE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below growell on lease, the battery and pit location ermit and closure plan. All flow lines, pro- ermit and closure plan. All flow lines, pro-	perator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bund level. (s) have been remediated in compliance with boduction equipment and junk have been removed				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit pe from lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below growell on lease, the battery and pit location ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem in addressed as per OCD rules.	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bund level. (s) have been remediated in compliance with boduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit pe from lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below growell on lease, the battery and pit location ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem in addressed as per OCD rules.	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bund level. (s) have been remediated in compliance with boduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit per from lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom retrieved flow lines and pipelines. 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and ha ave been cut off at least two feet below gro well on lease, the battery and pit location ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem an addressed as per OCD rules. ned in accordance with 19.15.35.10 NMA	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bund level. (s) have been remediated in compliance with bduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non-				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit pe from lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom retrieved flow lines and pipelines. If this is a one-well lease or last remaining 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and ha ave been cut off at least two feet below gro well on lease, the battery and pit location(ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem addressed as per OCD rules. ned in accordance with 19.15.35.10 NMA well on lease: all electrical service poles a	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bund level. (s) have been remediated in compliance with boduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit per from lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom retrieved flow lines and pipelines. 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and ha ave been cut off at least two feet below gro well on lease, the battery and pit location(ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem addressed as per OCD rules. ned in accordance with 19.15.35.10 NMA well on lease: all electrical service poles a	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bund level. (s) have been remediated in compliance with bduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non-				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as pother production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit perform lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom retrieved flow lines and pipelines. If this is a one-well lease or last remaining location, except for utility's distribution infrastructure. 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT THE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below gro- well on lease, the battery and pit location ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem an addressed as per OCD rules. ned in accordance with 19.15.35.10 NMA well on lease: all electrical service poles a ucture.	 berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bound level. (s) have been remediated in compliance with bouction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- and lines have been removed from lease and well 				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit pe from lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom retrieved flow lines and pipelines. If this is a one-well lease or last remaining 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT THE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below gro- well on lease, the battery and pit location ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem an addressed as per OCD rules. ned in accordance with 19.15.35.10 NMA well on lease: all electrical service poles a ucture.	 berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bound level. (s) have been remediated in compliance with bouction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- and lines have been removed from lease and well 				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit per from lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom retrieved flow lines and pipelines. If this is a one-well lease or last remaining location, except for utility's distribution infrastrue 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below growell on lease, the battery and pit location (ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem in addressed as per OCD rules. ned in accordance with 19.15.35.10 NMA well on lease: all electrical service poles a ucture.	 berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bound level. (s) have been remediated in compliance with boduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- und lines have been removed from lease and well chedule an inspection. 				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as pother production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit perform lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom retrieved flow lines and pipelines. If this is a one-well lease or last remaining location, except for utility's distribution infrastructure. 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and have been cut off at least two feet below growell on lease, the battery and pit location (ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem in addressed as per OCD rules. ned in accordance with 19.15.35.10 NMA well on lease: all electrical service poles a ucture.	 berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bound level. (s) have been remediated in compliance with boduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- und lines have been removed from lease and well chedule an inspection. 				
 Rat hole and cellar have been filled and lev A steel marker at least 4" in diameter and a OPERATOR NAME, LEASE NAMI UNIT LETTER, SECTION, TOWNS PERMANENTLY STAMPED ON T The location has been leveled as nearly as p other production equipment. Anchors, dead men, tie downs and risers ha If this is a one-well lease or last remaining OCD rules and the terms of the Operator's pit per from lease and well location. All metal bolts and other materials have bee to be removed.) All other environmental concerns have bee Pipelines and flow lines have been abandom retrieved flow lines and pipelines. If this is a one-well lease or last remaining location, except for utility's distribution infrastrue 	veled. Cathodic protection holes have been at least 4' above ground level has been set E. WELL NUMBER, API NUMBER, C SHIP, AND RANGE. All INFORMAT 'HE MARKER'S SURFACE. possible to original ground contour and have ave been cut off at least two feet below grown well on lease, the battery and pit location(ermit and closure plan. All flow lines, pro- en removed. Portable bases have been rem addressed as per OCD rules. the d in accordance with 19.15.35.10 NMA well on lease: all electrical service poles a ucture. Form to the appropriate District office to set Corm to the appropriate District office to set Corm . TITLEDecommissioning	berator's pit permit and closure plan. n properly abandoned. in concrete. It shows the DUARTER/QUARTER LOCATION OR ION HAS BEEN WELDED OR as been cleared of all junk, trash, flow lines and bund level. (s) have been remediated in compliance with boluction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- und lines have been removed from lease and well chedule an inspection. g Project ManagerDATE8.30.19				

APPROVED BY:	Kenny	Jake-	title C	0	A	DATE 9-13-19
	- F				. 5	/