Submit 1 Copy To Appropriate District	State of New Me	exico		Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-403	
District III - (505) 334-6178	1220 South St. Ener	acis Dr.	5. Indicate STAT	Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 8	BRC	6 State Oil	& Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	OIL CONSERVATION 1220 South St. Fran Santa Fe, NM 85	CD ⁰ CD	V-2199	a Gas Lease NO.
87505 SUNDRY NOTIO	CES AND PEDOPTS ON WELLS	7 7 20.		me or Unit Agreement Name
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ALS TO DRILL OR TO DEEPEN CR.PL	JG BACK TO A	Gem 8705	
DIFFERENT RESERVOIR. USE "APPLIC	ATION FOR PERMIT" (FORM C-1041)	REACH	8. Well Nur	
1. Type of Well: Oil Well	Gas Well 🔲 Other	- VED	#010	
2. Name of Operator BTA Oil Producers, LLC			9. OGRID 1 260297	Number
3. Address of Operator				me or Wildcat
104 S. Pecos, Midland, TX 797	01			ware 96797
4. Well Location				
Unit Letter D ::	feet from the	line and3	<u>30</u> fee	t from the <u>West</u> line
Section 2		ange 33E	NMPM	County Lea
	11. Elevation (Show whether DR,			
L	3584' G	ĸ		
12. Check A	ppropriate Box to Indicate N	ature of Notice,	Report or O	ther Data
NOTICE OF IN	TENTION TO	SUB9	SEQUENT	REPORT OF:
		REMEDIAL WORK	•	
	CHANGE PLANS	COMMENCE DRI		
PULL OR ALTER CASING		CASING/CEMENT	JOB	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM	_			_
OTHER:		OTHER:		
	eted operations. (Clearly state all provide the state all provide the state all provide the state of the state all provide the state of			
proposed completion or reco		. For Multiple Con	npietions: Au	ach wendore diagram of
	-			
Following the August 28, 2013 I		and complete the	e Brushy Ca	anyon (attached), the
accompanying procedure was o	ecuted to provide:			
Open Perfs: Brushy (Canyon: 6556' – 6575' (2 JSPF)		
	ring: 9338' – 9366'			
PBID @ 9260. (CIBP @ 930	0' with 40' of cement dump ba	lied on top of Cil	BP.)	
This work was performed Septe	mber 9. 2013 through Septen	nber 18. 2013. A	summary o	f the daily work is on the
attached page of this C-103. A				
attempted P&A operations on 9	/12/2019.			
		[
Spud Date:	Rig Release Da	ite:		
			· · · · ·	
I hereby certify that the information a	bove is true and complete to the be	est of my knowledge	and belief.	
	-			
20.1 AA				. DATE 9/13/2019
SIGNATURE Solifall	TITLE Envir	onmental Manage	er	UAIE
Type or print name Bob Hall	E-mail add	ress: <u>bhall@btao</u>	<u>il.com</u> .	PHONE: (432) 682-3753
For State Use Only				
	Forthe TITLE C. 1	() <u>1</u>		DATE 9-24-19
APPROVED BY: <u><u><u><u></u></u><u><u><u></u></u><u><u></u><u><u></u></u><u><u></u><u></u><u>APPROVED BY</u>: <u><u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u></u></u></u></u></u></u></u>	JUNCE TITLE , I			_DAIE_(- ' / /
Conditions of Approval (if any)		•		

1

Conditions of Approval	(if an
------------------------	--------

Gem 8705 JV-P #10 (API #30-025-40315)

Summary of Daily Report to plugback well and complete Brushy Canyon perforations

9/9/13 Pull well. RIH with casing scraper and bit.

9/10/13 Finish TIH w/ scraper. POOH. PU & RIH w/ tbg to set CIBP @ 9300'. Load hole. Pressure test CIBP to 1000 psi. OK. Circ hole w/ 2% KCI water. POOH w/ tbg to 6575'.

9/11/13 RU pump truck. Spot 200-gal 10% acetic acid. POOH. RU WL. Perf: 6556' – 6575' (2 JSPF). Make two runs with dump bailer. Cap CIBP w/ 40' cement. ROH and RD WL.

9/12/13 RU tbg tester. PU & RIH w/ packer. Set packer @ 6440'. Test backside to 1000 psi. OK. Pump 1,000-gallon acid and flush. SWI. RU and swab well.

9/13/13 Frac well.

9/14/13 Swab well.

9/16/13 Swab well. On last run, pulled swab line apart. Lost about 900' sandline, sinker bar, swab mandrel, and no go. RD swab. Release pkr & POOH. Did not find cable or tools in SN. PU & RIH with impression block.


9/17/13 Finish RIH with impression block to 7000'. Did not hit anything. POOH. RIH with production BHA on tubing.

9/18/13 RIH with pump and rods. Hang well on. Load hole. Good pump action. RDMO pulling unit.

As part of commencement of P&A operations on the subject well:

9/12/19 RU WL & RIH with gauge ring. Tag obstruction @ 7700'. ROH and RD WL.

Conduct research to determine cause of tagging high in wellbore. Discover records of plugback of wellbore and completion of Brush Canyon perfs.



, • •														
District 1 1625 M. French Dr., Hobba, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. Forst St., Artesia, NM 88210			Eu	State of New Mexico Energy Minerals and Natural Resources			urces	HOBBS OCD Revised July 18, 2013						
Phone: (575) 748-1283 Fac: (575) 748-9720 <u>District: III</u> 1000 Rio Brazon Rond, Aztoo, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170 <u>District IV</u> 1220 S. St. Francis Dr., Santa Pe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462				Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 8750 5				AUG 2 7 CANNENDED REPORT						
APPLICA	ATION F		crator Name		ILL, RE-EN	TER, DE	EPEN, P		, OR A		ZONE			
	B	TA OIL 04 PEC	PRODUC	ERS,	LLC.				297	/				
	M		, TEXAS	5 7970	1			30-025-4	40315					
305201	Code									" Well No				
					⁷ . Surface Loc	cation								
UL-Let Se D	ection Tow 2 20	restrip)S	Range 33E	Lot li	990'	NOP	S Line RTH	Feet From 330	E/W Line WEST					
UL-Lot Se	oction Tow	nship	Range	Lot 6	to Foct from		ation SLine	Fost From	E/W Line	•	County			
					* De al V-C				i 					
				<u></u>	* Pool Inform Pool Name	1900					Pool Code			
780	25	Der	awd				. <u> </u>	<u>.</u>		0	6791			
^{11.} Work Ty			Well Type	Ad	ditional Well In ^{U.} Cable/Ro			case Type		Ground Le	vel Elevation			
P			0		WELL SERVI	ICE UNIT S 3584'								
¹⁶ Multipl NO		17. Proposed Depth 14. Forms 6580 BRUSHY CAN			BRUSHY CAN					M Spue	d Date OVED			
Depth to Ground water Distance from nearest fresh water 90' 1 mile				earest fresh water w	vell		Distance to nearest surface water NA							
XWe will be us	ing a closed	-loop syst	em in lieu o	of lined pi	ţ r									
··			11.	T	ed Casing and	Cement Pr	ogram	r-=						
Туре	Hole Size		sing Size	T	ing Weight/ft	<u> </u>			s of Cement		Estimated TOC			
Surface	173"		3/8"		54.5 ₽	1387'		1100 Sx.		Surface				
Intermed.	12;		5/8"	<u> </u>	40∦	3248'		1900 S		Surface				
Prod	8 3/4	" 7	······································	the second se	29 #	9800!		900 s	×.	1800'				
, DV	-Tool A	t 3624		ng/Ceme	nt Program: A	dordonal (omments							
			n	Propos	d Blowout Pre	vention Pr	ogram							
Туре		Working Pressure		Test Pressure		re	Manufacturer							
Annular, pipe rams 3		3000		1500		Schaffer or Cameron								
^{23.} I hereby certify best of my knowle I further certify 19.15.14.9 (B) N	edge and belie that) have c	ef. omplied w	ith 19.15.14.9			Approved B		ONSERVA		VISION				
(17.13.14.7 (H) N	TIAL (, 11 8	appucable.			1			1 series	ET.					
Signature:	100	TU	<u>pan</u>	11	Ca			· _		Title: Petroleum Engineer				
	toe		san	11	<u>ca</u>	Title:	Petroleu	m Engineer	<u> </u>					
Signature: Printed name: Jo	toe	~~~	<u>1-an</u>	11	<u>c</u> ą	Title: Approved D				ite: 08	128/15			
Signature: Printed name Jo	<u>pe T. Ja</u> ermit Er	ng.			<u>e</u> ą					ite: <i>D</i> 8	128/15			

.

Procedure:

I.

MI & RU Completion Unit. Unseat pump. Hot oil rods and tubing. Pull out of hole with rods and pump. ND Wellhead and NU BOP. Release TAC and pull out of hole.

- 2. Pick up and RIH with 6" scraper on tubing.
- 3. Run in hole with CIBP for 7" 29# casing on tubing. Set CIBP at +- 9300'. Cap CIBP with 40' cement.
- 4. Load hole with 2% KCl water. Pressure test casing to 1000 psi.
- 5. Raise end of tubing to 6575'. Spot 200 gallons 10 % acetic acid at 6575'.
- 6. POH with tubing.
- Rig up Perforating truck. Run in hole correlate to Halliburton Spectral Density Dual Spaced Neutron Resistivity Log dated 6/10/2012. RIH with 3-1/8" hollow carrier casing gun with Premium Charges. Perforate at 6556 to 6575' with 2 JSPF per the attached Perf Sheet.
- RIH with tubing and packer for 7" 29# casing. Pressure testing tubing to 6000 psi. Set packer at +/- 6440'. Pressure test packer to 1000 psi.
- 9. Breakdown perfs with pressure and displace acid.
- 10. Swab back load to evaluate.
- RU to acidize with 1000 gallons 7-1/2% HCl NEFE acid containing 47 (7/8" 1.3 S.G.) ball sealers. Pump at 6-8 BPM. Maximum pressure 6000 psi with 1000 psi on backside.
- 12. Flow and swab back load to evaluate. Depending on results prepare to frac well.


13. Prepare to frac down tubing as follows:

Frac well down frac tubing using with 66700 gallons of Cross-linked (25#) gel carrying 100,000 pounds 20/40 brown sand as follows:

- a) Pump 16500 gallons 25# cross-link gel pad
- b) Pump 7000 gallons 25# cross-link gel with sand from 0.5 PPG
- c) Pump 13300 gallons 25# cross-link gel with sand from 1 PPG
- d) Pump 13200 gallons 25# cross-link gel with sand from 2 PPG
- e) Pump 10000 gallons 25# cross-link gel with sand from 3 PPG
- f) Pump 6700 gallons 25# cross-link gel with sand from 4 PPG
- g) Flush with to top perforation with linear gel (Approximately 1747 gallons).

Pump at 20 - 23 BPM. Maximum pressure 6000 psi with 1000 psi on casing.

- 14. Shut well in for gel to break overnight.
- 15. Flow back load to evaluate.







Perfs 6556-6575

CIBP @ 9300'±/40'cement cap

9540 9700 a se

distant.

:/

Strate in the second

:

Perfs Base Spring 9338 - 9366

Revised	I	Producing Well	I Orawn (TJW	
İ	LEASE: 87	105 JV-P GBM	#10	1	6/12/2012
	FTELD:	Teas (Bone Spri	ing)		
	LUCATION: 990	FNL 330' FWL Sec.	2 T20S R33E	Approved	
	COLDITY:	Les state	New Mexico	ļ	
	PRODUCING FORMATION	Bone Se	oriz	Dage	
	-			1	

|.

1 m P