Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERCIAL STATES OMB NO. 1004-0137 BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLOCD Hobbs 5. Lease Serial No. NMNM84652 Do not use this form for proposals to drill or to re-entings. 6. Is Indian Allone or Triba Name 7. Is Indian Allone or Triba Name 8. Is Indian Allone or Triba Name 8. Is Indian Allone or Triba Name 8. Is Indian Allone or Triba Name 9. Is Indian Allone or Triba Name 1. Is Indian Allone or Triba

abandoned we	II. Use form 3160-3 (APD) fo	or such proposale BB	S OCA 6. If Indian, Allottee	or Tribe Name	
SUBMITIN	7. If Unit or CA/Agre	eement, Name and/or No.			
Type of Well		RECEI		8. Well Name and No. HAMON FED COM 01	
Name of Operator LEGACY RESERVES OPERA	Contact: JOH			9. API Well No. 30-025-30848-00-S1	
3a. Address	3b.	Phone No. (include area code		10. Field and Pool or Exploratory Area	
MIDLAND, TX 79702		n: 432-689-5200	QUAIL RIDGE	QUAIL RIDGE	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish,	11. County or Parish, State	
Sec 7 T20S R34E NWNE 660	FNL 1980FEL		LEA COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES) TO	INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☑ Production (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	□ Change Plans	□ Plug and Abandon	□ Temporarily Abandon		
	☐ Convert to Injection	□ Plug Back	■ Water Disposal		
Pick up work string, 8 drill coll. Tag for fill. Top of fill left at 80 Clean out to top of packer. Retrieve packer at 8070'. Trip in with CIBP and set at 8' Modify well head if needed for location and remove work stril Cap well with packer fluid/oxy wrapped liner. Repair the glas MIRU cement company. Estal bbl (350 sx) light with LCM an	44'. 120' and dump bail 10' cemen renew casing, if needed set shing. Prepare to run liner. gen scavenger/biocide. Pick us wrap at every tong and pick blish rate with packer fluid/oxy	allow RBP for well controup and run 8110' of 4" L-8 up mark and joints.	30 FJ glass Pump cement lead 82		
14. I hereby certify that the foregoing is	Electronic Submission #4841	VES OPE R ATING LP, sent	to the Hobbs		
Name (Printed/Typed) JOHN SAENZ		Title OPERA	ATIONS ENGINEER		
	<u></u>				
Signature (Electronic S		Date 09/19/2		, , , , , , , , , , , , , , , , , , , 	
	THIS SPACE FOR I	FEDERAL OR STATE	OFFICE USE		
Approved By		Ac	cepted for Record	SEP 1 9 2019	
onditions of approval, if any, are attached. Approval of this notice does not warrant or criffy that the applicant holds legal or equitable title to those rights in the subject lease hich would entitle the applicant to conduct operations thereon.			Jonathon Shepard Carlsbad Field Office		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crim	e for any person knowingly and	d willfully to make to any department of	r agency of the United	

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #484119 that would not fit on the form

32. Additional remarks, continued

Wait on cement and install well head and cut off liner. Install BOP. Run CBL from PBTD to surface. Pick up work string and 3-1/4" bit and drill pipe. Clean out well to 8250'. Trip out lay down collars and bit. Pick up 4" injection packer. Set injection packer at 8100'. Lay down work string. Pick up and hydro test 2-3/8" FJ IPC injection tubing. Circulate packer fluid, latch injection tubing to packer. Rig down BOP, perform MIT 500#. Call BLM/OCD to witness test tomorrow. Rig down pulling unit. Perform MIT with witness. Return to injection, pump 2 drums acid down well.

