Do not use this form for propo abandoned well. Use form 316	THE INTERIOR MANAGEMENT REPORTS ON WELLS Desails to drill or to re-free and Hobbs 0-3 (APD) for such proceeds Hobbs	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 FRANCEScrial No. NMINM0315712 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - O	ther instructions on part OBBS OCD	 If Unit or CA/Agreement, Name and/or No. NMNM134687
1. Type of Well S Oil Well Gas Well Other	OCT 0 2 2019	8. Well Name and No. SNEED 9 FEDERAL COM 2H
	Contact: DANA KING king@concho.com	9. API Well No. 30-025-41409-00-S1
3a. Address ONE CONCHO CENTER 600 W ILLINOIS AV MIDLAND, TX 79701-4287	/ENUE 3b. Phone No. (include area code) ED Ph: 432-818-2267	10. Field and Pool or Exploratory Area MALJAMAR-YESO, WEST
4. Location of Well (Footage, Sec., T., R., M., or Survey D	escription)	11. County or Parish, State
Sec 9 T17S R32E NWNW 990FNL 150FWL		LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent	Acidize	🗖 Deepen	Production (Start/Resume)	U Water Shut-Off	
Subsequent Report	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity	
	Casing Repair	New Construction	Recomplete	🛛 Other	
Final Abandonment Notice	Change Plans	ans I i Piug and Abandon I i i emporarity Abandon		Venting and/or Flari ng	
	Convert to Injection	Plug Back	Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

SNEED 9 FEDERAL #2H BATTERY

Permit approval: Electronic Submission #448178

Actual gas flared for this battery for 12/18/2018 TO 3/18/2019 is as follows:

Dec 2018 Total for Battery = 78 MCF

Jan 2019 Total for Battery = 8704 MCF

14. I hereby certify that the	e foregoing is true and correct. Electronic Submission #484873 verifie For COG OPERATING	LLC, se	nt to the Hobbs					
Name (Printed/Typed)	Committed to AFMSS for processing by PRI DANA KING	SCILLA Title	SUBMITTING CONTACT					
Signature	(Electronic Submission)	Date	09/24/2019					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By		Title	Accepted for Record	SEP	26	2019		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Jonathon Shepard Garlsbad Field Office					
Title 18 U.S.C. Section 100 States any false, fictitious	1 and Title 43 U.S.C. Section 1212, make it a crime for any pe or fraudulent statements or representations as to any matter w	erson kno rithin its j	wingly and willfully to make to any department or urisdiction.	agency of the	Jnited			
(Instructions on page 2)	BI M REVISED ** BI M REVISED ** BI M RI	EVISEI) ** BI M REVISED ** BI M REVISE					

Additional data for EC transaction #484873 that would not fit on the form

32. Additional remarks, continued

Feb 2019 Total for Battery = 1899 MCF

Mar Total for Battery = 0 MCF

۶.

٠

NUMBER OF WELLS TO FLARE: 5

SNEED 9 FEDERAL COM # 2H 30-025-41409-00-SNEED 9 FEDERAL COM #11H 30-025-43284-00-SNEED 9 FEDERAL COM #13H 30-025-43285-00-SNEED 9 FEDERAL COM #21H 30-025-41489-00-SNEED 9 FEDERAL COM #23H 30-025-41410-00-

REASON: UNPLANNED MIDSTREAM CURTAILMENT DUE TO PLANT MAINTENANCE OR HIGH LINE PRESSURE.