

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOCD

HOBBS OGD

FORM APPROVED
OMB No. 1004-0135
Expires: January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS 2019

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

RECEIVED

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator Manzano, LLC

3a. Address
P.O. Box 2107, Roswell, NM 88202-2107

3b. Phone No. (include area code)
575-623-1996

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

5. Lease Serial No.
NM-111966

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

Nmom - 116279

8. Well Name and No.
Brennan Federal Com #2

9. API Well No.
30-041-90222 20922

10. Field and Pool, or Exploratory Area
Chaveroo N. Lower Penn

11. County or Parish, State
Roosevelt, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

see attached

Approved as to plunging of the well bore. Liability under bond is retained until surface restoration is completed.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

John B. Thompson

Title V.P. Production

Signature

John B. Thompson

Digitally signed by John B. Thompson
Date: 2019.10.10 14:25:38 -06'00'

Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

ACCEPTED FOR RECORD

OCT 01 2019
Date

BUREAU OF LAND MANAGEMENT
ROSWELL FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

27 NM/OCB 10-11-19

FOR RECORD ONLY

Plugging Report
Brennan Federal Com #2
Lat: 33.7529858886 Lon: -103.559196236

2/27/2019 Started blowing down the well to the battery. Cleared location and rigged up.

2/28/2019 Blew down well and killed casing and tubing. Installed BOP. Well started blowing again. Killed the well again and released anchor. POOH with 275 jts 2 7/8" tubing, a seating nipple, and an anchor. Set CIBP at 8700'. Started back in the hole with the tubing. SION

3/1/2019 Finished RIH with tubing and tagged CIBP at 8700'. Circulated MLF and teased casing to 500#. Casing good. Spotted 25 sx Class H cement on top of CIBP. WOC and tagged cement at 8469'. POOH to 7778' and spotted 25 sx Class H cement. POOH to 6920' and spotted 25 sx Class C cement. POOH to 5502' and spotted 25 sx cement. POOH to 3792' and spotted 25 sx cement. POOH and SION.

3/4/2019 Tagged cement at 3553'. POOH to 2223' and spotted 60 sx with CaCl to combine the Yates and the top of the salt plugs. WOC and tagged cement at 1661'. POOH to 444' and circulated cement to surface with 45 sx. POOH and removed BOP. SION

3/5/2019 Rigged down. Dug out cellar and cut off wellhead. Filled up 5 1/2" casing and 8 5/8" casing with 30 sx cement. Installed marker and cut off anchors. Cleaned the steel pit, cleared the location and moved out equipment.