, CD	
Submit One Copy To Appropriate District State of New Merit 2019	Farm C 102
Office	Form C-103 Revised November 3, 2011
District I Energy, Winerais and Watural Resources	WELL API NO.
District II 811 S. First St., Artesia, NM 88210 OIL CONSERVA RESEVISION	30-025-27652
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	B-2148 7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.) 1. Type of Well: XOil Well Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
CONCOCOPHILLIPS COMPANY	217817
3. Address of Operator P. O. BOX 2197	10. Pool name or Wildcat
HOUSTON, TX 77252	MALJAMAR;GB-SA
4. Well Location	
Unit Letter <u>H</u> : <u>1980</u> feet from the <u>N</u> line and <u>660</u> feet from the _	
Section <u>24</u> Township <u>17S</u> Range <u>35E</u> NMPM County L	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other D	Data er
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK DILUG AND ABANDON REMEDIAL WORK DILUG ALTERING CASING DI	
	— — —
PULL OR ALTER CASING	
OTHER: In the compliance with OCD rules and the terms of the Operator's pit permit and closure plan	
X All nits have been remediated in compliance with OCD rules and the terms of the One	
\boxed{X} All pits have been remediated in compliance with OCD rules and the terms of the Ope \boxed{X} Rat hole and cellar have been filled and leveled. Cathodic protection holes have been	rator's pit permit and closure plan.
 All pits have been remediated in compliance with OCD rules and the terms of the Ope Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in 	rator's pit permit and closure plan. properly abandoned.
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUI	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the JARTER/QUARTER LOCATION OR
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, ON UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIC PERMANENTLY STAMPED ON THE MARKER'S SURFACE. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u>
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u>
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>UARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production of the operator's pit permit and closure plan. All flow lines, production of the operator's pit permit and closure plan. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production of the operator's pit permit and closure plan. All flow lines, production of the operator's pit permit and closure plan. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in <u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OPERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u> The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grou If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. 	rator's pit permit and closure plan. properly abandoned. In concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grou If this is a one-well lease or last remaining well on lease, the battery and pit location(s OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC 	rator's pit permit and closure plan. properly abandoned. In concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grouts of the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grouter of the operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles are service poles. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>JARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles ar location, except for utility's distribution infrastructure. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>UARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ad lines have been removed from lease and well
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grouter of the operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles are service poles. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>UARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ad lines have been removed from lease and well
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles ar location, except for utility's distribution infrastructure. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>UARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ad lines have been removed from lease and well
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles ar location, except for utility's distribution infrastructure. 	rator's pit permit and closure plan. properly abandoned. In concrete. It shows the <u>UARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ad lines have been removed from lease and well medule an inspection.
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group of the production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below group of the coperator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remote to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMACC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles ar location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to sel SIGNATURE 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>UARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ad lines have been removed from lease and well hedule an inspection. <u>DATE 10/29/2019</u>
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, ON UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grouts of the operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remote to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles ar location, except for utility's distribution infrastructure. 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>UARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ad lines have been removed from lease and well hedule an inspection. <u>DATE 10/29/2019</u>
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OF UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grouts of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. Mall metal bolts and pipelines. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMACC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles ar location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to sel SIGNATURE Manda Rogers E-MAIL: _rogerrs@conocopiperfor State Use Only 	rator's pit permit and closure plan. properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed boved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ad lines have been removed from lease and well hedule an inspection. inatorDATE10/29/2019 PHONE:832-486-2737 A
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been A steel marker at least 4" in diameter and at least 4' above ground level has been set in OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OI UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grouter in the state of the Operator's pit permit and closure plan. All flow lines, proof from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMACC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles ar location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to sel SIGNATURE Men all work has been completed, return this form to the appropriate District office to sel SIGNATURE 	rator's pit permit and closure plan. properly abandoned. n concrete. It shows the <u>UARTER/QUARTER LOCATION OR</u> <u>ON HAS BEEN WELDED OR</u> been cleared of all junk, trash, flow lines and und level.) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- ad lines have been removed from lease and well hedule an inspection. <u>DATE 10/29/2019</u>









