

Office		f New Me		•	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals	s and Natu	ral Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240				WELL A	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-31707	
District III – (505) 334-6178	1220 Sout	th St. Fran	ncis Dr.		te Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505				ATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa I	C, INIVI O	7505	6. State C	Oil & Gas Lease No.
87505					
SUNDRY NO	TICES AND REPORTS C	N WELLS	ı	7. Lease	Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO DE	EPEN OR PLA	JG BACK TO A	}	5
DIFFERENT RESERVOIR. USE "APP	LICATION FOR PERMIT" (FOI	RM C-101) F	CACH	Vacuum	Glorieta West Unit
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well  Other IN	JIE GN	) -	8. Well N	lumber 78H
2. Name of Operator	Oas well Other It	ATE BOY	-10	O OCPU	) Number
Chevron USA INC	HC	, .	5012	4323	Number
3. Address of Operator		NOV SE	10		name or Wildcat
6301 Deauville BLVD, Midland	TX 79706	Mo.	WED	Vacuum (	
·				V deddiii (	
4. Well Location	2401			107	33/224
Unit Letter E	:2491feet from the	North	line and		feet from the West line
Section 36	Township	17S Ra	inge 34E	NMPM	County Lea
	11. Elevation (Show w	vhether DR,	RKB, RT, GR, etc.	)	
ı ♣ 12 Check	Appropriate Box to I	ndicate N	ature of Notice	Report or	Other Data
12. Check	. Appropriate Box to I	ildicate iv	atare or rectice,	Report of	Other Buta
NOTICE OF	INTENTION TO:		l sub	SEQUEN	IT REPORT OF:
PERFORM REMEDIAL WORK		N 🛛	REMEDIAL WOR	k I	AMPACABLE PING CASING T
	CHANGE PLANS		REMEDIAL WOR	ILLI <b>SSE</b> P	S.I. BANDFOVAI
	MULTIPLE COMPL	ī	CASING/CEMEN	T JORNA	US Of Whh.
		<del></del>	C	Ollaino	US of Approval
——————————————————————————————————————	<b>-</b>		_	, •	
OTHER:	_	П	OTHER:		П
	npleted operations. (Clear	ly state all		d give pertir	nent dates, including estimated da
					Attach wellbore diagram of
proposed completion of r	ecompletion.8-5/8" @ 153	<b>15 TOC Sur</b>	iace, 3-1/2 (w, 093	2 100 100	0, CIDI (a) 3024
proposed completion of i	recompletion.8-5/8" @ 153	35 TOC Sur	iace, 5-1/2 @ 093	5 100 100	0, CIBI (@ 3024
proposed completion of f	ecompletion.8-5/8" @ 153	35 TOC Sur	iace, 5-1/2 (@ 693	5 100 100	0, CIDI (@ 3024
CI	nevron USA INC respectf	fully reques			
CI		fully reques			
Ch 1. Call and notify NMOCD	nevron USA INC respectf 24 hrs before operations b	f <b>ully reque</b> s egin.	st to abandon this	well as follo	
Ct 1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to a	nevron USA INC respects 24 hrs before operations b pump truck, pressure test c determine which plugs liste	fully requesting to mage to mage dependent to mage dependent to mage dependent with the second secon	st to abandon this ximum anticipated ill be spots or P&S	well as follo squeeze pre and the asso	ssure and perform CBL, share ociated cement volumes. Check
Ct 1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to a	nevron USA INC respects 24 hrs before operations b pump truck, pressure test c determine which plugs liste	fully requesting to mage to mage dependent to mage dependent to mage dependent with the second secon	st to abandon this ximum anticipated ill be spots or P&S	well as follo squeeze pre and the asso	ows: ssure and perform CBL, share
1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform by plugged to a certain point	nevron USA INC respects 24 hrs before operations be pump truck, pressure test condetermine which plugs listed bubble test on surface casing tagreed upon by the NMO	fully requesting to maged below was annulus,	st to abandon this ximum anticipated ill be spots or P&S if bubble test fails (	well as follo squeeze pre and the asso	ssure and perform CBL, share ociated cement volumes. Check
1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point 3. MIRU CTU, TIH and tag	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test c determine which plugs liste bubble test on surface casing t agreed upon by the NMO g CIBP at 5624'.	fully requesting in the segin, assing to maded below with the segment of the segm	st to abandon this ximum anticipated ill be spots or P&S if bubble test fails of evron.	well as follows squeeze preand the associated control interesting the second control in	essure and perform CBL, share ociated cement volumes. Check ands to Zonite the well after it is
Coll and notify NMOCD  Call and notify NMOCD  MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point MIRU CTU, TIH and tag  Spot 205 sx CL "C" cmt	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed bubble test on surface casing t agreed upon by the NMO of CIBP at 5624'.	fully requesting in the property of the proper	st to abandon this ximum anticipated ill be spots or P&S if bubble test fails evron.	well as follows squeeze preand the associated control interesting the second control in	ssure and perform CBL, share ociated cement volumes. Check
Coll and notify NMOCD  Call and notify NMOCD  MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point  MIRU CTU, TIH and tag  Spot 205 sx CL "C" cmt  Spot 120 sx of Class C C	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed pubble test on surface casing to agreed upon by the NMO (3 CIBP at 5624'. If 5624't/ 3891', do not WAMT f/ 3168' t/ 2151' (Sev	fully requesting to make defended below was annulus, occ and characters for the control occ and control occ an	st to abandon this ximum anticipated ill be spots or P&S if bubble test fails evron.	well as follows squeeze preand the associated control interesting the second control in	essure and perform CBL, share ociated cement volumes. Check ands to Zonite the well after it is
Coll and notify NMOCD  Call and notify NMOCD  MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point  MIRU CTU, TIH and tag  Spot 205 sx CL "C" cmt  Spot 120 sx of Class C C  P&S or Spot 55 sx f/ 158	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed pubble test on surface casing to agreed upon by the NMO (3 CIBP at 5624'. If 5624't/ 3891', do not WAMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe)	fully requesting to make defended below was annulus, occ and characters for the control occ and control occ an	st to abandon this ximum anticipated ill be spots or P&S if bubble test fails evron.	well as follows squeeze preand the associated control interesting the second control in	essure and perform CBL, share ociated cement volumes. Check ands to Zonite the well after it is
Coll and notify NMOCD  Call and notify NMOCD  MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point  MIRU CTU, TIH and tag  Spot 205 sx CL "C" cmt  Spot 120 sx of Class C C  P&S or Spot 55 sx f/ 156  P&S or Spot 105 sx f/ 35	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test conditional determine which plugs listed pubble test on surface casing the agreed upon by the NMO (3 CIBP at 5624'. If 5624't/3891', do not WMT f/3168' t/2151' (Sev 35't/1398' (Rustler, Shoe).	fully requesting to make deferment with the second control of the	et to abandon this aximum anticipated ill be spots or P&S if bubble test fails evron.  If casing passed a payates, Tansil).	well as follo squeeze pre and the asso Chevron inte	essure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)
CH 1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 158 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchorse	nevron USA INC respects 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to the public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  15/ 5624't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398') (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398') (Rustler, Shoe).	fully requesting to make deferment with the second control of the	et to abandon this aximum anticipated ill be spots or P&S if bubble test fails evron.  If casing passed a payates, Tansil).	well as follo squeeze pre and the asso Chevron inte	essure and perform CBL, share ociated cement volumes. Check ands to Zonite the well after it is
Coll and notify NMOCD  Call and notify NMOCD  MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point  MIRU CTU, TIH and tag  Spot 205 sx CL "C" cmt  Spot 120 sx of Class C C  P&S or Spot 55 sx f/ 156  P&S or Spot 105 sx f/ 35	nevron USA INC respects 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to the public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  15/ 5624't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398') (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398') (Rustler, Shoe).	fully requesting to make deferment with the second control of the	et to abandon this aximum anticipated ill be spots or P&S if bubble test fails evron.  If casing passed a payates, Tansil).	well as follo squeeze pre and the asso Chevron inte	essure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)
CH 1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 158 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchorse	nevron USA INC respects 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to the public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  15/ 5624't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398') (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398') (Rustler, Shoe).	fully requesting to make deferment with the second control of the	et to abandon this aximum anticipated ill be spots or P&S if bubble test fails evron.  If casing passed a payates, Tansil).	well as follo squeeze pre and the asso Chevron inte	essure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)
CH 1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 158 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchorse	nevron USA INC respects 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to the public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  15/ 5624't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398') (Rustler, Shoe).  15/ 5024't/ 3891', do not WMMT f/ 3168' t/ 2151' (Sev 35't/ 1398') (Rustler, Shoe).	fully requesting to make deferment with the second control of the	et to abandon this aximum anticipated ill be spots or P&S if bubble test fails evron.  If casing passed a payates, Tansil).	well as follo squeeze pre and the asso Chevron inte	essure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)
Coll and notify NMOCD  Call and notify NMOCD  MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point  MIRU CTU, TIH and tag  Spot 205 sx CL "C" cmt  Spot 120 sx of Class C C  P&S or Spot 55 sx f/ 150  P&S or Spot 105 sx f/ 35  Cut all casings & anchors requirements. Clean loca	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed by the test on surface casing the agreed upon by the NMO of CIBP at 5624'. If 5624't 3891', do not WMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe) of the test of the	fully requesting to make deference was annulus, of the CD and Cheron Rivers, where the CD were the control of the CD were the control of the CD were t	st to abandon this  ximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a pr Yates, Tansil).  ment to surface & v	well as following squeeze present and the associated control interessure test (	essure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)
CH 1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 158 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchorse	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed by the test on surface casing the agreed upon by the NMO of CIBP at 5624'. If 5624't 3891', do not WMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe) of the test of the	fully requesting to make deference was annulus, of the CD and Cheron Rivers, where the CD were the control of the CD were the control of the CD were t	st to abandon this  ximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a pr Yates, Tansil).  ment to surface & v	well as following squeeze present and the associated control interessure test (	essure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)
Coll and notify NMOCD  Call and notify NMOCD  MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point  MIRU CTU, TIH and tag  Spot 205 sx CL "C" cmt  Spot 120 sx of Class C C  P&S or Spot 55 sx f/ 150  P&S or Spot 105 sx f/ 35  Cut all casings & anchors requirements. Clean loca	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to be public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  If 5624't/ 3891', do not WMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe) of t/ Surface' (WB) of the agreed with the agreed to	fully requesting to make dealow was annulus, occurrent of the control occurrence. Verify center to the best occurrence of the control occurrence occurrenc	st to abandon this  ximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a pr Yates, Tansil).  ment to surface & v est of my knowledge	well as following squeeze present the associated continuation of the second sec	essure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)
Comparison of the control of the con	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to be public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  If 5624't/ 3891', do not WMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe) of t/ Surface' (WB) of the agreed with the agreed to	fully requesting to make deference of the following annulus, of the following annulus annulu	st to abandon this  ximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a pr Yates, Tansil).  ment to surface & v	well as following squeeze present the associated continuation of the second sec	essure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)
Coll and notify NMOCD  Call and notify NMOCD  MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point  MIRU CTU, TIH and tag  Spot 205 sx CL "C" cmt  Spot 120 sx of Class C C  P&S or Spot 55 sx f/ 150  P&S or Spot 105 sx f/ 35  Cut all casings & anchors requirements. Clean loca	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to be public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  If 5624't/ 3891', do not WMT f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe) of t/ Surface' (WB) of the agreed with the agreed to	fully requesting to make dealow was annulus, occurrent of the control occurrence. Verify center to the best occurrence of the control occurrence occurrenc	est to abandon this eximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a property ates, Tansil).  ment to surface & very sest of my knowledge ell P&A Project M	well as folions squeeze present the associated continues the same test (weld on dry because and belief anager	essure and perform CBL, share ociated cement volumes. Check ands to Zonite the well after it is perfs, Grayburg, San Andres) thole marker as per, NMOCD
1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 158 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchors requirements. Clean local	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to be the test on surface casing the agreed upon by the NMO of CIBP at 5624'.  15/ 5624't/ 3891', do not Wom f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 1398' (Rustler, Shoe).  15/ 1398' (Rustler, Shoe).  15/ 1398' (Bustler, Shoe).  15/ 1398' (Bustler, Shoe).  15/ 1398' (Bustler, Shoe).  16/ 1398' (Bustler, Shoe).  17/ 17/ 17/ 17/ 17/ 17/ 17/ 17/  17/ 17/ 17/ 17/ 17/ 17/ 17/  17/ 17/ 17/ 17/ 17/ 17/ 17/  17/ 17/ 17/ 17/ 17/ 17/ 17/ 17/ 17/ 17/	fully requesting to make delow was annulus, of the control of the	exit to abandon this eximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a property ates, Tansil).  ment to surface & very sest of my knowledge ell P&A Project M	well as followed and the associated continued	essure and perform CBL, share ociated cement volumes. Check ands to Zonite the well after it is perfs, Grayburg, San Andres) thole marker as per, NMOCD
1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform by plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 158 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchors requirements. Clean loca  I hereby certify that the information  SIGNATURE  Type or print name Ricky Villent Results (1) R	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to be the test on surface casing the agreed upon by the NMO of CIBP at 5624'.  15/ 5624't/ 3891', do not Wom f/ 3168' t/ 2151' (Sev 35't/ 1398' (Rustler, Shoe).  15/ 1398' (Rustler, Shoe).  15/ 1398' (Rustler, Shoe).  15/ 1398' (Bustler, Shoe).  15/ 1398' (Bustler, Shoe).  15/ 1398' (Bustler, Shoe).  16/ 1398' (Bustler, Shoe).  17/ 17/ 17/ 17/ 17/ 17/ 17/ 17/  17/ 17/ 17/ 17/ 17/ 17/ 17/  17/ 17/ 17/ 17/ 17/ 17/ 17/  17/ 17/ 17/ 17/ 17/ 17/ 17/ 17/ 17/ 17/	fully requesting to make dealow was annulus, occurrent of the control occurrence. Verify center to the best occurrence of the control occurrence occurrenc	exit to abandon this eximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a property ates, Tansil).  ment to surface & very sest of my knowledge ell P&A Project M	well as followed and the associated continued	ssure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)  hole marker as per, NMOCD  DATE 11/22/2019
1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform by plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 158 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchors requirements. Clean located the company of t	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to be public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  If 5624't 3891', do not Wom MT f 3168' t 2151' (Sev 35't 1398' (Rustler, Shoe) of Volume Surface' (WB) of the agreed with the agreed to the agreed	fully requesting to make delow was annulus, och and chook tag it wen Rivers, where the to the best of	et to abandon this eximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a property ates, Tansil).  ment to surface & veron to surfa	well as followed and the associated continued	ssure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)  hole marker as per, NMOCD  DATE 11/22/2019  PHONE: 432-687-7786
1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform be plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 150 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchors requirements. Clean loca  I hereby certify that the information  SIGNATURE  Type or print name Ricky Ville For State Use Only  APPROVED BY:	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to be public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  If 5624't 3891', do not Wom MT f 3168' t 2151' (Sev 35't 1398' (Rustler, Shoe) of Volume Surface' (WB) of the agreed with the agreed to the agreed	fully requesting to make delow was annulus, och and chook tag it wen Rivers, where the to the best of	et to abandon this eximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a property ates, Tansil).  ment to surface & veron to surfa	well as followed and the associated continued	ssure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)  hole marker as per, NMOCD  DATE 11/22/2019
1. Call and notify NMOCD 2. MIRU wireline unit and presults with NMOCD to well pressures, perform by plugged to a certain point 3. MIRU CTU, TIH and tag 4. Spot 205 sx CL "C" cmt 5. Spot 120 sx of Class C C 6. P&S or Spot 55 sx f/ 158 7. P&S or Spot 105 sx f/ 35 8. Cut all casings & anchors requirements. Clean located the company of t	nevron USA INC respectf 24 hrs before operations be pump truck, pressure test condetermine which plugs listed to be public test on surface casing the agreed upon by the NMO of CIBP at 5624'.  If 5624't 3891', do not Wom MT f 3168' t 2151' (Sev 35't 1398' (Rustler, Shoe) of Volume Surface' (WB) of the agreed with the agreed to the agreed	fully requesting to make delow was annulus, of the control of the	et to abandon this eximum anticipated ill be spots or P&S if bubble test fails of evron.  f casing passed a property ates, Tansil).  ment to surface & veron to surfa	well as followed and the associated continued	ssure and perform CBL, share ociated cement volumes. Check ends to Zonite the well after it is perfs, Grayburg, San Andres)  hole marker as per, NMOCD  DATE 11/22/2019  PHONE: 432-687-7786





## **GENERAL CONDITIONS OF APPROVAL:**

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.