Form 3160-5 (June 2015)

Carisbad Field Office

UNITED STATES DEPARTMENT OF THE INTERIOR OCD Hobbs

FORM APPROVED OMB NO. 1004-0137

BUREAU OF LAND MANAGEMENT	Expires. January 51, 2
SUNDRY NOTICES AND REPORTS ON MEDIS DO NOT USE this form for proposals to drill or to re-enter and abandoned well. Use form 3160-3 (APD) for such proposals.	5. Lease Serial No. NMNM57285
abandoned well. Use form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Nam
SUBMIT IN TRIPLICATE - Other instructions on page 2 2 2019	7. If Unit or CA/Agreement, Nam
D	J

SUBMIT IN TRIPLICATE - 0	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other	RECEIVED	8. Well Name and No. STIVASON FEDERAL 5
Name of Operator Contact: KYLE ZIMMERMANN VANGUARD OPERATING LLC E-Mail: kzimmerman@vnrenergy.com		9. API Well No. 30-025-30725-00-S1
3a. Address 5847 SAN FELIPE, SUITE 3000 HOUSTON, TX 77057	3b. Phone No. (include area code) Ph: 432-202-0145	10. Field and Pool or Exploratory Area PEARL
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)	11. County or Parish, State
Sec 27 T19S R34E SWSW 660FSL 550FWL		LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent □ Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete	□ Water Shut-Off □ Well Integrity □ Other
☐ Final Abandonment Notice	Change Plans Convert to Injection	☐ Plug and Abandon ☐ Plug Back	☑ Temporarily Abandon ☐ Water Disposal	3 •

Vanguard Operating, LLC is requesting to temporarily abandon (TA) this well to evaluate any future uphole recompletion opportunities. TA procedure is as follows:

- 1. MIRU WS. LD production equipment.
- 2. RU WL. Set 5-1/2? CIBP @ 4,468? (Top perf @ 4,518?). Cap w/ 35? of cement via bailer.


 3. Contact BLM prior to running MIT test. Fill casing with treated water and pressure test to 500 psig for at least 30 minutes. Record pressure chart.
- . 4. KD WS & WL.
- 5. File subsequent 3160-5 and MIT chart.


14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #494368 verifie For VANGUARD OPERATI Committed to AFMSS for processing by PRI	IG ĹLC.	sent to the Hobbs	
Name (Printed/Typed)	KYLE ZIMMERMANN	Title	OPERATIONS ENGINEER	
Signature	(Electronic Submission) THIS SPACE FOR FEDERA	Date	12/03/2019 STATE OFFICE USE	=1x1x
Approved By /s/	Jonathon Shepard	Title	PE	ወ ፎር 0 5 2019
Conditions of approval, if as certify that the applicant hol	ny, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease licant to conduct operations thereon.	Office	CFO	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED RECORD. (Instructions on page 2) 7 NMOCD 12-18-19

^{13.} Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.





BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Note: TA status "will be effective for a period up to 1 year from the date of NOI approval and can be renewed annually thereafter" per IM NM-2016-017.

- A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 2. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 3. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 4. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 5. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 6. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.