UNITED STATES DEPARTMENT OF THE INTERIOR Shaderield Officerau of LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


SUNDRY	UREAU OF LAND MANA NOTICES AND REPO	RTS ON W	DEBH	appe eia O	I. 16 O Serial No. NMNM53380	andary 51, 2016
Do not use th abandoned we	is form for proposals to II. Use form 3160-3 (AP	drill or to re D) for such p	-onter en 🥆 🖎	obbs	6. If Indian, Allottee	or Tribe Name
SUBMIT IN	TRIPLICATE - Other ins	tructions o	ege 2	4	7. If Unit or CA/Agre	ement, Name and/or No.
1. Type of Well				,	8. Well Name and No. CAVINESS 10 FED 01	
	Contact:	TAMMY RL	INK		9. API Well No.	
MATADOR PRODUCTION C	OMPANYE-Mail: tlink@mata				30-025-29849-0	
3a. Address			. (include area code 7-2465)	10. Field and Pool or Exploratory Area MESCALERO ESCARP	
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description) .			11. County or Parish,	State
Sec 10 T18S R33E NESE 16	50FSL 330FEL	-			LEA COUNTY,	NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTI	ER DATA
TYPE OF SUBMISSION			TYPE O	F ACTION		
Notice of Letters	☐ Acidize	☐ Dee	pen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off
Notice of Intent	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	tion	☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomp	lete	Other
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon		arily Abandon	
	☐ Convert to Injection	☐ Plug	Back	☐ Water Disposal		
Objective:Temporary Abandor 1. Provide 24 hour notice to di 2. Safety meeting, MIRU, Kill v 3. Set CIBP at 8550' (60' abov 4. Dump bail 35' cement on to 5. Perform MIT to 500 psi. Sut minutes. 6. RDMO.	strict office. well, ND WH, NU BOP's, e top perforation). p of CIBP. omit pressure chart showi	unseat tubing	packer and TO			
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #- For MATADOR P mitted to AFMSS for proce	492571 verified RODUCTION	by the BLM Wel	II Information to the Hobbs	System	
Name (Printed/Typed) TAMMY R LINK		ssaling by FRIS		JCTION ANA		
Signature (Electronic S			Date 11/15/20			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	5E	
Approved By /s/ Jone	athon Shepard		Title PE			NOVate 1 9 2019
onditions of approval, if any, are attached crify that the applicant holds legal or equ hich would entitle the applicant to condu	itable title to those rights in the		Office CFO			·
itle 18 U.S.C. Section 1001 and Title 43 UStates any false, fictitious or fraudulent s						
nstructions on page 2) ** BLM REVI	SED ** BLM REVISED) ** BLM RE	VISED ** BLM	F(REVISED	RRECO	RD ONLY

77 NMOCD 12-20-19

Additional data for EC transaction #492571 that would not fit on the form

32. Additional remarks, continued

See attached Wellbore Schematic



Lea County, NM API: 3002529849 WELLBORE SCHEMATIC Spud: 3/1/1987

3,150

9,587



1 1/2" sinker bars

Pump

Tubing	String
KB-GL	
2 3/8" 4.7# 8RD tbg	281
2 3/8" 35K TAC	set @ 8470
2 3/8" 4.7# 8RD tbg	10
SN (ID 1.875")	set @ 8781
Sand Screen (24' length)	8782 to 8806
Bull Plug	8806
Rod Design: Weatherfo	ord D rods (RTS order)
1 1/2" Polish Rod	26'
Pony Rod	2'
7/8" rods	108
3/A" mds	230

Previous Workovers			
2/1/2016	HIT		
12/24/2016	HIT		
2/16/2017	Parted Rods		
8/30/2017	Pull rod pump		
12/5/2017	Parted Rods		

Weight lb/ft

54.5

24 & 32

17

Joints

Depth Set

415

3,150

9,587

Date Run

3/4/1987 3/8/1987

3/27/1987

Note: Rods recovered from Fed 30-1 were elongated 62 from Fed 30, 46 new 164 from Fed 30, 66 new

2"x1.25"x20x24 RHBC pump Andrew Pump


		C	asing Informati
	Hole Size	Casing Size	Туре
Surface	17 1/2	13 3/8	ST&C
Intermediate	12 1/4	8 5/8	J55 ST&C
Production	7 7/8	5 1/2	LT&C J-55
Marker Joint		Geologica	l Markers
DV Tool	7900	Rustler	1,568
Float Collar		Yates	3,045
Cementing Record		7 Rivers	
Surface	450 sx Bowers		3,960
Intermediate	1350 sx	Queen	4,226
Production	1950 sx	Penrose	4,480
		Grayburg	4,782
		BFSA	5,180
		Delaware Sd	5,690
		Bone Spring	6,530

10

Perf'd 8610-8698 2 spf and acidized w 1000 gals 15% MSR and reacidized w 6250 gal of 20% SRA & ball sealers

EOT Buil Plug @ 8806 PBTD

TAC 8470



35' Bailed Cement

9,587

As of 12/6/2017

L	Tubing String	
KB-GL		14
Rod Design	: Weatherford D rods (F	(TS order)
.00		
L		

Previous Workovers			
2/1/2016	HIT		
12/24/2016	HIT		
2/16/2017	Parted Rods		
8/30/2017	Pull rod pump		
12/5/2017	Parted Rods		

Weight lb/ft

54.5

24 & 32

17

Joints

		C	asing information	
	Hole Size	Casing Size	Туре	
Surface	17 1/2	13 3/8	ST&C	
Intermediate	12 1/4	8 5/8	JSS ST&C	
Production	7 7/8	5 1/2	LT&C J-55	
Marker Joint		Geologica	l Markers	
DV Tool	7900	Rustler	1,568	
Float Collar		Yates	3,045	
ementing Record		7 Rivers		
Surface	450 sx	Bowers	3,960	
Intermediate	1350 sx	Queen	4,226	
Production	1950 sx	Penrose	4,480	
		Grayburg	4,782	
		BFSA	5,180	
		Delaware Sd	5,690	
		Bone Spring	6,530	

Perf'd 8610-8698 2 spf and acidized w 1000 gals 15% MSR and reacidized w 6250 gal of 20% SRA & ball sealers

EOT Bull Plug @ 8806

PBTD

Killatador

Depth Set

415

3,150

9,587

Date Run

3/4/1987

3/8/1987

3/27/1987

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Note: TA status "will be effective for a period up to 1 year from the date of NOI approval and can be renewed annually thereafter" per IM NM-2016-017.

- A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 2. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 3. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 4. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 5. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 6. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.