

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-35975
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Royal Stimulator
8. Well Number 2
9. OGRID Number 5898
10. Pool name or Wildcat Wildcat S153631F;Miss (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM 10) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
DAVID H. ARRINGTON OIL AND GAS,

3. Address of Operator
P.O. BOX 2071
MIDLAND, TX 79702

4. Well Location
Unit Letter 2 : 1900 ²²³⁵ feet from the S line and 1300 ³³⁰ feet from the W line
Section 31 Township 15S Range 36E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
GL 3927'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9-10-19 Tag existing CIBP @ 11880'. 9-11,12-19 circ w/ 450 bbls salt gel brine. spot 25 sx cmt from 11120-10880'. POOH w/ 32 stds tbg. 9-13-19 found cmt inside tbg. 9-16-19 Tag CIBP @ 11880', spot 25 sks H cmt from 11130-10840'. POOH w/ 30 stds tbg pulling wet. 9-17-19 RIH did not tag cmt plug. Call NMOC - Kerry Fortner instructed to set 7" CIBP 50' above 4 1/2" liner and spot 50 sks cmt. - POOH. 9-18-19 RIH w/ 7" CIBP set @ 10750'. POOH RD WL. RIH w/ tbg & tag CIBP @ 10748', circ hole w/ 400 bbls MLF. 9-19-19 load w/ 20 bbls brine, circ well. prs to 500 psi 10 mins OK. Mix & pump 50 sks H cmt @ 10740' displace w/ 40 bbls brine wtr. POOH to 8427'. 9-20-19 RIH tag TOC @ 10333', prs test to 500 psi 10 mins OK. Spot 35 sks H cmt plug from 8403-8230'. POOH w/ tbg. RU WL & perf 7" csg @ 6400'. RIH w/ prk set @ 60', est inj rate into perfs. 9-22-19 RIH set prk @ 6042' Sqz 7" perfs w/ 50 sks C cmt, displace w/ 33.24 bbls. release & re set prk @ 4483. RU WL & perf @ 4830'. sqz perfs w/ 50 sks C cmt, displace w/ 26.78 bbls brine. 9-23-19 Tag TOC @ 4648'. reset prk @ 2703' RIH & perf @ 3050' & sqz w/ 50 sks C cmt, displace to 2950'. WOC. Reset prk @ 1685', RIH & perf @ 2050' & sqz w/ 50 sks C cmt, displace to 1285'. 9-25-19 Reset prk @ 159' RIH & perf @ 528'. Sqz 7" csg perfs w/ 50 sks C Cmt, displace to 428'. WOC & tag TOC @ 377'. POOH LD tbg. RIH & perf @ 250'. Pump 130 sks C cmt w/ returns out 9 5/8" csg @ surface.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Regulatory Specialist

DATE 11/13/2019

Type or print name DEBBIE WHITING

E-mail address: DEBBIE.WHITING@ARRINGTONPHONE.COM 682-6685

For State Use Only

APPROVED BY:

TITLE C O

DATE 12-20-19

Conditions of Approval (if any):