

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

| |
|---|
| WELL API NO. 30-025-44083 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name Thistle Unit |
| 8. Well Number 162 |
| 9. OGRID Number 6137 |
| 10. Pool name or Wildcat Triple X; Bone Spring (59900) |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Devon Energy Production Co. LP

3. Address of Operator
333 W. Sheridan Ave OKC, OK 73102

4. Well Location
Unit Letter **B** : **335** feet from the **North** line and **1780** feet from the **East** line
Section **22** Township **23S** Range **33E** NMPM **Lea** County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3713'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: Conductor P&A ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Devon Energy respectfully requests the following procedure to plug and abandon set conductor:

1. Pumped cement job to completely fill conductor with cement
2. Cut off casing 55" below GL
3. Welded plate to cutoff casing. Plate includes the following information:
 - a. Company name, Well Name and Number, API Number, & Legal Description
4. Took GPS measurement of plate location
 - a. See attached picture of GPS coordinate and plate
5. Filled cellar with caliche
6. Operations completed 9/22/2018

HOBBS OCD
DEC 11 2019
RECEIVED
RECEIVED

Spud Date:

12/01/17

Rig Release Date:

12/01/17

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rebecca Deal TITLE Regulatory Analyst DATE 7/31/2018

Type or print name Rebecca Deal E-mail address: rebecca.deal@dvn.com PHONE: 405-228-8429

For State Use Only

APPROVED BY: Kerry Fortner TITLE CO A DATE 12-20-19

Conditions of Approval (if any)