Office Farmer Minagels and Natural Basesses	1 OIM C-103
District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave. Artesia NM 8821000 CODNSERVATION DIVISION	30-025-23173
District II 1301 W. Grand Ave., Artesia, No. 2008 DISTRICT III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Dia Danne Del Arter NM 8741/1	STATE TO FEE TO
District IV 1220 S. St. Francis Dr., Santa Fe, NM JAN 2 3 2020 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NO PICE AND PORTS ON WELLS	7. Lease Name or Unit Agreement Name
I (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	State I-29
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well X Other PA	#5
2. Name of Operator	9. OGRID Number
Texland Petroleum-Hobbs, LLC	113315
3. Address of Operator	10. Pool name or Wildcat
777 Main Street, Suite 3200, Fort Worth, Texas 76102	Hobbs, Upper Blinebry
	11000s, Opper Billieory
4. Well Location	
Unit Letter O : 330 feet from the South line and 22	
Section 29 Township 18S Range 38	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	.)
3646'	
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDis	stance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; C	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Penort or Other Data
12. Check Appropriate Box to indicate Nature of Notice,	Report of Ouler Data
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON XX REMEDIAL WOR	
	ILLING OPNS. P AND A
TEMPORARIET ABANDON OFFICIAL PARTY OF COMMITTION DA	
DULL OD ALTED CASING IN MULTIPLE COMPLICED IN CASING/CEMEN	T IOP (
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN	T JOB
	T JOB
OTHER:	
	d give pertinent dates, including estimated date
OTHER:  OTHER:  OTHER:  OTHER:	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  OTHER:	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug  PLS 5) Spot 50 sk plug @ 2500-2700'; tag plug  PLS 6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug  PLS 5) Spot 50 sk plug @ 2500-2700'; tag plug  PLS 6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug  PLS 5) Spot 50 sk plug @ 2500-2700'; tag plug  PLS 6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug  P+5 5) Spot 30 sk plug @ 2500-2700'; tag plug  P+5 6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole  See attached Well Bore Schematic	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Control of proposed completion  marker  de and belief. I further certify that any pit or below-
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug  P+5 5) Spot 50 sk plug @ 2500-2700'; tag plug  P+5 6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole  See attached Well Bore Schematic	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Control of proposed completion  marker  de and belief. I further certify that any pit or below-
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt  2) Circ 9.5# salt gel mud between plugs  3) Spot 100 sk plug @ 5300-5830', tag plug  4) Spot 100 sk plug @ 3478-4100', tag plug  4) Spot 100 sk plug @ 3478-4100', tag plug  6) Spot 30 sk plug @ 2500-2700'; tag plug  6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole  See attached Well Bore Schematic  I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Continue Table T
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug  P+5 5) Spot 30 sk plug @ 2500-2700'; tag plug  P+5 6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole  See attached Well Bore Schematic	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Continue Table T
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt  2) Circ 9.5# salt gel mud between plugs  3) Spot 100 sk plug @ 5300-5830', tag plug  4) Spot 100 sk plug @ 3478-4100', tag plug  4) Spot 100 sk plug @ 3478-4100', tag plug  6) Spot 30 sk plug @ 2500-2700'; tag plug  6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole  See attached Well Bore Schematic  I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Continue Table T
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt  2) Circ 9.5# salt gel mud between plugs  3) Spot 100 sk plug @ 5300-5830', tag plug  4) Spot 100 sk plug @ 3478-4100', tag plug  \$\text{P\$\text{5}}\$ \$\text{Spot}\$ \$\text{50}\$ skp plug @ 2500-2700'; tag plug  \$\text{\$\text{6}}\$ \$\text{Spot}\$ \$\text{50}\$ sk plug @ 410-surface; circ to surface, install dry hole  See attached Well Bore Schematic  I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines \$\mathred{\text{n}}\$, a general permit \$\mathred{\text{CISS}}\$  SIGNATURE	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Continues and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  StDATE1/23/2020
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug 945 5) Spot 50 sk plug @ 2500-2700'; tag plug 945 6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole See attached Well Bore Schematic  I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines  , a general permit    SIGNATURE	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Continues and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  StDATE1/23/2020
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug  1) Spot 100 sk plug @ 2500-2700'; tag plug  1) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole  See attached Well Bore Schematic  I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines    SIGNATURE TITLE Regulatory Analy  Type or print name Vickie Smith E-mail address: vsmith@texpetro	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Continue Research  marker  e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  stDATE1/23/2020  c.com Telephone No. 575-433-8395
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  Texland Petroleum-Hobbs proposes to plug and abandon as follows:  1) Existing CIBP set @ 5865'w/5 sks cmt 2) Circ 9.5# salt gel mud between plugs 3) Spot 100 sk plug @ 5300-5830', tag plug 4) Spot 100 sk plug @ 3478-4100', tag plug 945 5) Spot 50 sk plug @ 2500-2700'; tag plug 945 6) Spot 100 sk plug @ 410-surface; circ to surface, install dry hole See attached Well Bore Schematic  I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines  , a general permit    SIGNATURE	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion  Continues and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  StDATE1/23/2020