

۴B				ator	OMB NO		
Do not use this form for proposals to drill or to re-enter and to BBS Of Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals to BBS Of Indian, Allottee or Tribe Name							
					1		
SUBMIT IN TRIPLICATE - Other instructions on page 2 MAR 1 2020 <sup>7.</sup> If Unit or CA/Agreement, Name and/or No.							
1. Type of Well         Oil Well       Other         RECEIVED         8. Well Name and No.         B. Oil Well         O Oil Well         O Other							
2. Name of Operator Contact: ABIGAIL ANDERSON COG OPERATING LLC E-Mail: abbym@bcmandassociates.com					9. API Well No. 30-025-30872-00-S1		
3a. Address       3b. Phone No. (include area code)         ONE CONCHO CENTER 600 W ILLINOIS AVENUE       Ph: 432-580-7161         MIDLAND, TX 79701-4287       Ph: 432-580-7161					10. Field and Pool or Exploratory Area JOHNSON RANCH		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 4 T25S R33E SWNE 1975FNL 1980FEL 32.161398 N Lat, 103.575182 W Lon					LEA COUNTY, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	<ul> <li>Acidize</li> <li>Alter Casing</li> </ul>	Deepen	Fracturing	Product Reclam	tion (Start/Resume) ation	<ul> <li>Water Shut-Off</li> <li>Well Integrity</li> </ul>	
Subsequent Report	Casing Repair	New Const				Other	
Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	🛛 Plug and A 🗖 Plug Back	bandon	Tempol Water I	rarily Abandon Disposal		
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for funal inspection. 1. Tag existing 4 1/2" CIBP @ 14,170 w/ 35' cmt on top. 2. Set 4 1/2" CIBP @ 13,115'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx class H cmt @ 13,115-13,015'. WOC & Tag (7" Shoe) 3. Spot 25 sx cmt @ 12,818'-12,748' (4 1/2" Liner Top) / 2.59 8. Add from 12260 - 12040 (T/wc). 4. Perf & Sqz 50 sx cmt @ 9270-9178'. (T/Bone Spring) 9080. woc Tag. 5. Perf & Sqz 50 sx cmt @ 6600-6500' (Spacer) woc Tag. 6430 6. Perf & Sqz 140 sx cmt @ 5300-4900'. WOC & Tag (B/Sait & 9 5/8" Shoe) 7. Perf & Sqz 50 sx cmt @ 1400-1250'. WOC & Tag (T/Sait) 9. Perf & Sqz 50 sx cmt @ 1400-1250'. WOC & Tag (13 3/8" Shoe) 10. Perf & Sqz 50 sx cmt @ 100' to Surface. 11. Cut off well head, verify cmt to surface, weld on Below Ground Dry Hole Marker. Action of the set of the se							
Electronic Submission #494583 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Hobbs Committed to AFMSS for processing by DEBORAH MCKINNEY on 12/05/2019 (20DLM0120SE) Name (Printed/Typed) ABIGAIL ANDERSON Title AGENT							
Numer, Anicaryped ADIGALL		11110	AGENT	· ·	··	<u> </u>	
Signature (Electronic Submission) Date 12/04/2019							
	THIS SPACE FO	R FEDERAL OR	STATE		SE		
_Approved ByAnne	es les am	🗲	SA	<u>67</u>		12-8-19 Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the	not warrant or subject lease Offic	e CF	$\mathcal{O}$			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** FOR RECORD ONL J NMOC)							



32.1614037

-103.5751495



## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be req ired to verify depth. Based on depth, a tag of the cement may be deemed necessary. Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8 <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Tinting Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u> From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3 00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted