HOBBS OCD

State of New Mexico Submit One Copy To Appropriate District Form C-103 Office Energy, Minerals and Natural Resources Revised November 3, 2011 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-38144 District II OIL CONSERVATION THIS ION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE X FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM V-2522 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A FOX A STATE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 7 1. Type of Well: XOil Well Gas Well Other 9. OGRID Number 37115 2. Name of Operator ROCKCLIFF OPERATING NEW MEXICO LLC 3. Address of Operator 10. Pool name or Wildcat 1301 MCKINNEY; STE 1300; HOUSTON TX 77010 **ALLISON SAN ANDRES** 4. Well Location feet from the NORTH ine and 430 feet from the EAST line Unit Letter Township 9S County LEA Section Range 36 E NMPM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4049' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: • PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. P AND A **MULTIPLE COMPL PULL OR ALTER CASING CASING/CEMENT JOB** OTHER: □ Location is ready for OCD inspection after P&A
□ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection. **SIGNATURE** TYPE OR PRINT NAME _____ For State Use Only APPROVED BY: Xluy Jul TITLE CO DATE 3-13-20



EMNRD - DISTRIC 1 1625 N FRENCH DRIVE HOBBS NM 88240 575-393-6161

PLUG & ABANDON - SITE OK TO RELEASE

OPERATOR NAME	Kockej: ff				
API	30-025-38144				
PROPERTY NAME	Fox A STATE #7				

WELL LOCATION	UL- LOT	SECTION	TOWNSHIP	RANGE	COUNTY
	A	Z	95	36E	LEA

DATE: 3-6-20P\ A'D OK TO RELASE \sqrt{ES}

TITLE: Constant Office