

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other Instructions on page 2**

**HOBBS OGD**  
**MAR 16 2020**  
**RECEIVED**

5. Lease Serial No.  
NMNM119759

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.  
NMNM136936

8. Well Name and No.  
Multiple-See Attached

9. API Well No.  
Multiple-See Attached

10. Field and Pool or Exploratory Area  
WC025G08S203506D-BONE SPRING

11. County or Parish, State  
LEA COUNTY, NM

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
COG OPERATING LLC  
Contact: ALICE BUCK  
E-Mail: ABUCK@CONCHO.COM

3a. Address  
ONE CONCHO CENTER 600 W ILLINOIS AVENUE  
MIDLAND, TX 79701-4287

3b. Phone No. (include area code)  
Ph: 575-689-3074

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Multiple-See Attached

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Venting and/or Flaring
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

COG OPERATING LLC RESPECTFULLY REQUESTS TO FLARE AT THE BLUE JAY FED 1H BATTERY.

FROM 3/26/2020 TO 6/24/2020

# OF WELLS TO FLARE: 2  
BLUE JAY FEDERAL COM 2H; 30-025-43533  
BLUE JAY FEDERAL COM 1H; 30-025-42338

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #505440 verified by the BLM Well Information System**  
**For COG OPERATING LLC, sent to the Hobbs**  
**Committed to AFMSS for processing by PRISCILLA PEREZ on 03/04/2020 (20PP1524SE)**

Name (Printed/Typed) ALICE BUCK Title OPERATING ENGINEERING TECH

Signature (Electronic Submission) Date 03/04/2020

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By JONATHON SHEPARD Title PETROELUM ENGINEER Date 03/12/2020

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Hobbs

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***

## Revisions to Operator-Submitted EC Data for Sundry Notice #505440

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	FLARE NOI	FLARE NOI
Lease:	NMNM119759	NMNM119759
Agreement:	NMNM136936	NMNM136936 (NMNM136936)
Operator:	CONCHO OPERATING LLC ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701-4287 Ph: 432-685-4342	COG OPERATING LLC ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701-4287 Ph: 432.685.4342
Admin Contact:	ALICE BUCK OPERATING ENGINEERING TECH E-Mail: ABUCK@CONCHO.COM  Ph: 575-689-3074	ALICE BUCK OPERATING ENGINEERING TECH E-Mail: ABUCK@CONCHO.COM  Ph: 575-689-3074
Tech Contact:	ALICE BUCK OPERATING ENGINEERING TECH E-Mail: ABUCK@CONCHO.COM  Ph: 575-689-3074	ALICE BUCK OPERATING ENGINEERING TECH E-Mail: ABUCK@CONCHO.COM  Ph: 575-689-3074
Location:		
State:	NM	NM
County:	LEA COUNTY	LEA
Field/Pool:	WC025G08S203506D-BONE SPR	WC025G08S203506D-BONE SPRING
Well/Facility:	BLUE JAY FEDERAL COM 1H Sec 18 T20S R35E 190FSL 2310FEL 32.566610 N Lat, 103.494850 W Lon	BLUE JAY FEDERAL COM 2H Sec 18 T20S R35E SESE 210FSL 660FEL 32.566491 N Lat, 103.490171 W Lon BLUE JAY FEDERAL 1H Sec 18 T20S R35E SWSE 190FSL 2310FEL 32.566295 N Lat, 103.495039 W Lon

**Additional data for EC transaction #505440 that would not fit on the form**

**Wells/Facilities, continued**

<b>Agreement</b>	<b>Lease</b>	<b>Well/Fac Name, Number</b>	<b>API Number</b>	<b>Location</b>
NMNM136936	NMNM119759	BLUE JAY FEDERAL COM 2H	30-025-43533-00-S1	Sec 18 T20S R35E SESE 210FSL 660FEL 32.566491 N Lat, 103.490171 W Lon
NMNM119759	NMNM119759	BLUE JAY FEDERAL 1H	30-025-42338-00-S1	Sec 18 T20S R35E SWSE 190FSL 2310FEL 32.566295 N Lat, 103.495039 W Lon

**32. Additional remarks, continued**

BBLS OIL/DAY: 180  
MDF/DAY: 580

REASON: NO PIPELINE CONNECTION, UNPLANNED MIDSTREAM CURTAILMENT AND/OR BREAKOUT GAS.