Office State of New Mexico	Form C-103
District I - (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-04016
District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE
District IV - (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLIS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DETAIN) PLUG BACK TO A	Northwest Eumont Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCHOO	Northwest Edition One
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPART LUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 20 PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 112
1. Type of Well: Oil Well X Gas Well Other JUN	
2. Name of Operator Rhombus Operating Co., Ltd, 3. Address of Operator P.O. Box 627, Littleton CO 80160-0627 4. Well Leasting	9. OGRID Number 19111
3. Address of Operator P.O. Box 627, Littleton CO 80160-0627	10. Pool name or Wildcat
	Eumont Yates, 7 Rivers, Queen
4. Well Location	-
Unit Letter L : 1987 feet from the South line and	660 feet from the West line
Section 14 Township 19S Range 36E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, e	(c.)
	<u> </u>
12. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
	•
NOTICE OF INTENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WO	DRK
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE [PRILLING OPNS. P AND A
·· · · · · · · · · · · · · · · · · · ·	
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEME	ENT JOB \square
	ENT JOB
DOWNHOLE COMMINGLE	ENT JOB
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	_
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM COTHER: COTHER: Requ	uest TA Extension X
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM COTHER: OTHER: OTHER: Requirements of the complete of the complete operations. (Clearly state all pertinent details,	uest TA Extension X and give pertinent dates, including estimated date
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: OTHER: Requirement details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple 0	uest TA Extension X and give pertinent dates, including estimated date
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM COTHER: OTHER: OTHER: Requirements of the complete of the complete operations. (Clearly state all pertinent details,	uest TA Extension X and give pertinent dates, including estimated date
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: OTHER: Requirement details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple 0	uest TA Extension X and give pertinent dates, including estimated date
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion.	uest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD FINAL TA STATUS	pest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: Requirement of Starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Processor up to 500 pair Hold.	pest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Approval of TA EXPIRES:	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: Required proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Proposed Completion or Recompletion. FINAL TA STATUS Approval of TA EXPIRES: Well needs to be PLUGGE	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple oproposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension FINAL TA STATU: Approval of TA EXPIRES: Well needs to be PLUGGE	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1// 2-1 D OR RETURNED
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple oproposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension FINAL TA STATU: Approval of TA EXPIRES: Well needs to be PLUGGE	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1// 2-1 D OR RETURNED
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: Required proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Proposed Completion or Recompletion. FINAL TA STATUS Approval of TA EXPIRES: Well needs to be PLUGGE	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1// 2-1 D OR RETURNED
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension FINAL TA STATUS Approval of TA EXPIRES: Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1// 2-1 D OR RETURNED
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple oproposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension FINAL TA STATU: Approval of TA EXPIRES: Well needs to be PLUGGE	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1// 2-1 D OR RETURNED
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension FINAL TA STATUS Approval of TA EXPIRES: Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1// 2-1 D OR RETURNED
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension FINAL TA STATUS Approval of TA EXPIRES: Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1// 2-1 D OR RETURNED
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple oproposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB Spud Date: Rig Release Date:	sest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1///2 D OR RETURNED OVE: X
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension FINAL TA STATUS Approval of TA EXPIRES: Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB	sest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1///2 D OR RETURNED OVE: XX
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of S-EXTENSION 1// 2 D OR RETURNED OVE: OVE: dge and belief.
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of S-EXTENSION 1// 2 D OR RETURNED OVE: OVE: dge and belief.
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple oproposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB Spud Date: Rig Release Date:	and give pertinent dates, including estimated date completions: Attach wellbore diagram of S-EXTENSION 1// 2 D OR RETURNED OVE: OVE: dge and belief.
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM DITHER: OTHER: OTHER: OTHER: OTHER: Proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD FINAL TA STATUS Approval of TA EXPIRES: Approval of TA EXPIRES: Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED ABOUT THE DATE STATED AB	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1/1/2 D OR RETURNED OVE:
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled. SIGNATURE TITLE_Office Manager Type or print name Cindy Grogg E-mail address: rhombusenergy@gmail.com	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1/1/2 D OR RETURNED OVE:
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE_Office Manager Type or print name Cindy Grogg E-mail address: rhombusenergy@gmail.com For State Use Only	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1/1/2 D OR RETURNED OVE:
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE_Office Manager Type or print name Cindy Grogg E-mail address: rhombusenergy@gmail.com For State Use Only	Dest TA Extension X and give pertinent dates, including estimated date completions: Attach wellbore diagram of S-EXTENSION 1/1/2 D OR RETURNED OVE:
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple of proposed completion or recompletion. Notified NMOCD Pressure up to 500 psi. Held Chart attached Request TA Extension Well needs to be PLUGGE to PRODUCTION BY THE DATE STATED AB Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE Office Manager Type or print name Cindy Grogg E-mail address: rhombusenergy@gmail.com For State Use Only	Dest TA Extension X and give pertinent dates, including estimated date Completions: Attach wellbore diagram of S-EXTENSION 1/1/2 D OR RETURNED OVE:

