Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-28422
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE 🖾 FEE 🗌
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON WELLS DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name C. E. Brooks
PROPOSALS.)	Gas Well Other HOBBS	8. Well Number 1
1. Type of Well: Oil Well X	Gas Well Other	9. OGRID Number 328599
		9. OOKID Number 328399
3. Address of Operator P.O. B	ox 11350 Midland, TX 79702 RECEIVED	10. Pool name or Wildcat Knowles; Devonian, South
4. Well Location RECE		
Unit Letter L :	1980leet from theSouth the an	
Section 18	Township 17-S Range 3 11. Elevation (Show whether DR, RKB, RT, GR, etc.	9-E NMPM County Lea
3668' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	PLUG AND ABANDON 🖾 🕴 REMEDIAL WO	·
PULL OR ALTER CASING	MULTIPLE COMPL	NT JOB
DOWNHOLE COMMINGLE		
OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
2-3-2020 1.) MIRU. ND WH, NU BOP.		
2-4-2020 2.) Set CIBP @ 11,950'. Circ hole w/ MLF. Cap BP w/ 25 sx H cmt to 11,747'		
2-6-2020 3.) Spot 25 sx H cmt @ 10,762'- 10,662' 2-6-2020 4.) Spot 25 sx H cmt @ 8,344' - 8,244'		
2-6-2020 4.) Spot 25 sx H cmt @ 8,344' - 8,244' 2-6-2020 5.) Spot 25 sx C cmt @ 5,404' - 5,304'		
2-7-2020 6.) WOC- Tag @ 5,282' Spot 25 sx C cmt @ 5,066' - 4,860'		
2-7-2020 7.) Perf/Sqz 40 sx cmt @ 4,184' - 4,084' - WOC - Tng @ 4,028'		
2-7-2020 8.) Perf/Sqz 65 sx cmt @ 3,742' – 3,527' – WOC – Tag @ 3,440' 2-10-2020 9.) Perf/Sqz 50 sx cmt @ 2,450' – 2,150' – WOC – Tag @ 2,218'		
2-10-2020 10.) Perf/Sqz 120 sx cmt @ 450' to surface. RDMO		
3-6-2020 11.) Clean Location. Cut off WH & anchors. Install DH marker 4' below ground.		
(		
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Warge 7/23/2020		
Type or print nameWayne Dixon E-mail address:wdixon@ringenergy.com _ PHONE:432-556-5923 For State Use Only		
APPROVED BY: <u>Reproval (if any)</u> : TITLE <u>G</u> <u>A</u> DATE <u>7-29-20</u> Conditions of Approval (if any):		

•