

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised July 18, 2013

WELL API NO. <b>30-025-22043</b>	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. <b>K-2371</b>	
7. Lease Name or Unit Agreement Name <b>Sohio State</b>	
8. Well Number <b>1</b>	
9. OGRID Number <b>247692</b>	
10. Pool name or Wildcat <b>Bagley, Perno Penn North</b>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>4272' KB</b>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06/11/20 Set CIBP @ 10074'. Attempt to Pressure test casing. Test fail call OCD for instruction.

06/13/20 Circulate MLF. Spot 25 sx Class "H" cmt on CIBP. WOC (Per Kerry w/OCD). Pressure test casing. Perf @ 8600'. Attempt to Sqz call OCD for instruction.

06/14/20 Set balance plug @ 8650' w/ 25 sx Class "H" cmt (Per Kerry w/OCD). WOC. No Tag call OCD for instruction.

Set balance plug @ 8650' w/ 25 sx Class "H" cmt (Per Kerry w/OCD). WOC.

06/15/20 Tag plug @ 8372'. Perf @ 7320'. Attempt to Sqz call OCD for instruction. Set balance plug @ 7370' w/ 25 sx Class "H" cmt (Per Kerry w/OCD). WOC.

Tag plug @ 6965'. Perf @ 5120'. Attempt to Sqz call OCD for instruction. Set balance plug @ 5170' w/ 25 sx Class "C" cmt (Per Kerry w/OCD). WOC.

06/16/20 Tag plug @ 4976'. Perf @ 3800'. Sqz w/ 65 sx cmt. WOC. Tag plug @ 3580'. Perf 2430'. Sqz w/ 65 sx cmt. WOC. Tag plug @ 2170'.


Perf @ 1800'. Sqz w/ 65 sx cmt. WOC.


06/17/20 Tag plug @ 1568'. Perf @ 395'. Circulate cement to surface. Cut off wellhead 3' below ground level. Verify cement to surface. Install dry hole marker.

Spud Date: **06/08/2020**

Rig Release Date: **06/17/2020**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Production Analyst DATE 08/07/2020  
Type or print name Nhi Le E-mail address: nle@jaymgt.com PHONE: 713-621-6785  
**For State Use Only**

APPROVED BY:  TITLE C C A DATE 9-11-20  
Conditions of Approval (if any):