HOBBS OCD OCT 1 2020

ENED

Office			Form C-10	
District I	State of New Me Energy, Minerals and Natu	ral Resources	Revised November 3, 20 WELL API NO.	11
1625 N. French Dr., Hobbs, NM 88240 District II			30-005-00475	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 🗓		
District IV	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	\neg
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		C.L. O'brien	- 1	
PROPOSALS.)				
1. Type of Well: Oil Well X Gas Well Other		8. Well Number 1		
2. Name of Operator Primero Operating, Inc.		9. OGRID Number 018100		
3. Address of Operator PO Box 1433, Roswell, NM 88202		10. Pool name or Wildcat		
PO Box 1433, Roswell, NM 88202		Cato San Andres Gas (West)	l	
4. Well Location			781 da -	
Unit Letter A : 660	feet from the N line and 6	60 feet from the E	line	
Section 7 Township	8S Range 30E NMPM	County	<u>Ch</u> aves	ŀ
11	. Elevation (Show whether DR 4068 GR	RKB, RT, GR, etc.)		
12. Check Appropriate Box to Inc	dicate Nature of Notice, R	eport or Other Da	ata	┪
NOTICE OF INTE	NTION TO:	l Sur	SEQUENT REPORT OF:	
	LUG AND ABANDON	REMEDIAL WORK		
	HANGE PLANS	COMMENCE DRIL		_
PULL OR ALTER CASING MI	ULTIPLE COMPL	CASING/CEMENT	JOB 🔲	
OTHER:	П	M Location is re-	ady for OCD inspection after P&A	
	lianaa suith OCDlaa and ti			
All pits have been remediated in cor	mbliance with OCD rules and t	ie terms of the Obera		
All pits have been remediated in cor Rat hole and cellar have been filled	and leveled. Cathodic protecti	on holes have been p	properly abandoned.	
All pits have been remediated in cor Rat hole and cellar have been filled A steel marker at least 4" in diameter	and leveled. Cathodic protections and at least 4' above ground	ne terms of the Opera on holes have been p level has been set in	concrete. It shows the	
Rat hole and cellar have been filled A steel marker at least 4" in diameter	and leveled. Cathodic protecti er and at least 4' above ground	on holes have been p level has been set in	properly abandoned. concrete. It shows the	
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A	on holes have been plevel has been set in	concrete. It shows the ARTER/QUARTER LOCATION OR	
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, 7	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, ATOWNSHIP, AND RANGE.	on holes have been plevel has been set in API NUMBER, QU. All INFORMATIO	concrete. It shows the ARTER/QUARTER LOCATION OR	
Rat hole and cellar have been filled A steel marker at least 4" in diamete OPERATOR NAME, LEASE UNIT LETTER, SECTION, I PERMANENTLY STAMPED	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A TOWNSHIP, AND RANGE. OON THE MARKER'S SUR	on holes have been plevel has been set in API NUMBER, QUALI INFORMATION FACE.	oroperly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR	
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as near	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A TOWNSHIP, AND RANGE. OON THE MARKER'S SUR	on holes have been plevel has been set in API NUMBER, QUALI INFORMATION FACE.	concrete. It shows the ARTER/QUARTER LOCATION OR	ıd
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as near other production equipment.	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A TOWNSHIP, AND RANGE. ON THE MARKER'S SUR arly as possible to original grounds.	on holes have been plevel has been set in API NUMBER, QUALI INFORMATIO FACE. Indicate the property of the pro	oroperly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines an	ıd
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and r	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, ATOWNSHIP, AND RANGE. ON THE MARKER'S SUR arrly as possible to original ground isers have been cut off at least	on holes have been plevel has been set in API NUMBER, QU. AII INFORMATIO FACE. Indicate the contour and has been set in the contour and has been set on the contour and has been set in the c	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines an	ıd
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and r If this is a one-well lease or last rem OCD rules and the terms of the Operator	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, ATOWNSHIP, AND RANGE. ON THE MARKER'S SUR arrly as possible to original ground is sers have been cut off at least raining well on lease, the batter	on holes have been plevel has been set in API NUMBER, QU. AII INFORMATIOFACE. Indication contour and has been set in a contour and has been set below ground and pit location(s)	oroperly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines an	
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, TO PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and rought fit is a one-well lease or last remocon rough lease and well location.	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A TOWNSHIP, AND RANGE. ON THE MARKER'S SUR arly as possible to original ground itsers have been cut off at least leaining well on lease, the battery's pit permit and closure plan.	on holes have been plevel has been set in API NUMBER, QU. All INFORMATIO FACE. Ind contour and has been set in a contour and has been set below grour and pit location(s) All flow lines, production	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines an and level. have been remediated in compliance with action equipment and junk have been remove	ved
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, TO PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and roll fithis is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials have	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A TOWNSHIP, AND RANGE. ON THE MARKER'S SUR arly as possible to original ground itsers have been cut off at least leaining well on lease, the battery's pit permit and closure plan.	on holes have been plevel has been set in API NUMBER, QU. All INFORMATIO FACE. Ind contour and has been set in a contour and has been set below grour and pit location(s) All flow lines, production	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines an and level. have been remediated in compliance with	ved
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, TO PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and roll fithis is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials have be removed.)	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A TOWNSHIP, AND RANGE. ON THE MARKER'S SUR arly as possible to original ground isers have been cut off at least leaining well on lease, the battery's pit permit and closure plan. ave been removed. Portable battery	on holes have been plevel has been set in API NUMBER, QU. All INFORMATIO FACE. Ind contour and has been set below grour y and pit location(s) All flow lines, produces have been removed.	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines an and level. have been remediated in compliance with action equipment and junk have been remove	ved
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, TO PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and roll fithis is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials have be removed.) All other environmental concerns have	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A TOWNSHIP, AND RANGE. ON THE MARKER'S SUR arly as possible to original ground itsers have been cut off at least raining well on lease, the battery's pit permit and closure plan. ave been removed. Portable batter ave been addressed as per OCD	on holes have been plevel has been set in API NUMBER, QU. All INFORMATIOFACE. Ind contour and has been set below grour y and pit location(s) All flow lines, produces have been removerules.	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. Thave been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have	ved
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, TO PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and roll fithis is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials have be removed.) All other environmental concerns have	and leveled. Cathodic protection and at least 4' above ground NAME, WELL NUMBER, A TOWNSHIP, AND RANGE. ON THE MARKER'S SUR arly as possible to original ground itsers have been cut off at least raining well on lease, the battery's pit permit and closure plan. ave been removed. Portable batter ave been addressed as per OCD	on holes have been plevel has been set in API NUMBER, QU. All INFORMATIOFACE. Ind contour and has been set below grour y and pit location(s) All flow lines, produces have been removerules.	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines an and level. have been remediated in compliance with action equipment and junk have been remove	ved
Rat hole and cellar have been filled A steel marker at least 4" in diamete OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as nea other production equipment. Anchors, dead men, tie downs and r If this is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials had to be removed.) All other environmental concerns had Pipelines and flow lines have been a retrieved flow lines and pipelines. If this is a one-well lease or last rem	and leveled. Cathodic protection and at least 4' above ground at least 4' alining well on lease, the batter at least 6' and 6' above been addressed as per OCD abandoned in accordance with 1' alining well on lease: all electrications and closure plan.	on holes have been plevel has been set in API NUMBER, QUALI INFORMATION FACE. Indication contour and has been set below grourly and pit location(s) All flow lines, produces have been removed rules. 9.15.35.10 NMAC.	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. Thave been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have	ved ave
Rat hole and cellar have been filled A steel marker at least 4" in diamete OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and r If this is a one-well lease or last remocd rules and the terms of the Operator from lease and well location. All metal bolts and other materials had to be removed.) All other environmental concerns had Pipelines and flow lines have been a retrieved flow lines and pipelines.	and leveled. Cathodic protection and at least 4' above ground at least 4' alining well on lease, the batter at least 6' and 6' above been addressed as per OCD abandoned in accordance with 1' alining well on lease: all electrications and closure plan.	on holes have been plevel has been set in API NUMBER, QUALI INFORMATION FACE. Indication contour and has been set below grourly and pit location(s) All flow lines, produces have been removed rules. 9.15.35.10 NMAC.	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. That been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have been removed.)	ved ave
Rat hole and cellar have been filled A steel marker at least 4" in diamete OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as nea other production equipment. Anchors, dead men, tie downs and r If this is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials had be removed.) All other environmental concerns had pipelines and flow lines have been a retrieved flow lines and pipelines. If this is a one-well lease or last rem location, except for utility's distribution in	and leveled. Cathodic protection and at least 4' above ground at least 4' along the least 4' along the least 4' along the least 6' alon	on holes have been plevel has been set in API NUMBER, QUALI INFORMATIOFACE. Ind contour and has been set below groundy and pit location(s) All flow lines, produces have been removed rules. 9.15.35.10 NMAC. cal service poles and	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have been removed from non-lines have been removed from lease and wellines have been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the s	ved ave
Rat hole and cellar have been filled A steel marker at least 4" in diamete OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as nea other production equipment. Anchors, dead men, tie downs and r If this is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials had to be removed.) All other environmental concerns had Pipelines and flow lines have been a retrieved flow lines and pipelines. If this is a one-well lease or last rem	and leveled. Cathodic protection and at least 4' above ground at least 4' along the least 4' along the least 4' along the least 6' alon	on holes have been plevel has been set in API NUMBER, QUALI INFORMATIOFACE. Ind contour and has been set below groundy and pit location(s) All flow lines, produces have been removed rules. 9.15.35.10 NMAC. cal service poles and	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have been removed from non-lines have been removed from lease and wellines have been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the s	ved ave
Rat hole and cellar have been filled A steel marker at least 4" in diamete OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as nea other production equipment. Anchors, dead men, tie downs and r If this is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials had be removed.) All other environmental concerns had pipelines and flow lines have been a retrieved flow lines and pipelines. If this is a one-well lease or last rem location, except for utility's distribution in	and leveled. Cathodic protection and at least 4' above ground at least 4' along the least 4' along the least 4' along the least 6' alon	on holes have been plevel has been set in API NUMBER, QUALI INFORMATIOFACE. Ind contour and has been set below groundy and pit location(s) All flow lines, produces have been removed rules. 9.15.35.10 NMAC. cal service poles and	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. have been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have been removed from non-lines have been removed from lease and wellines have been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the share been removed from lease and well in the s	ved ave
Rat hole and cellar have been filled A steel marker at least 4" in diamete OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as nea other production equipment. Anchors, dead men, tie downs and r If this is a one-well lease or last rem OCD rules and the terms of the Operator from lease and well location. All metal bolts and other materials had be removed.) All other environmental concerns had pipelines and flow lines have been a retrieved flow lines and pipelines. If this is a one-well lease or last rem location, except for utility's distribution in When all work has been completed, return	and leveled. Cathodic protection and at least 4' above ground	API NUMBER, QU. AII INFORMATIO FACE. Ind contour and has been set in a contour and pit location(s). All flow lines, product in a contour and prod	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. Thave been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have been removed from non-lines have been removed from lease and we dedule an inspection. DATE 9/30/2020	ved ave
Rat hole and cellar have been filled A steel marker at least 4" in diameter OPERATOR NAME, LEASE UNIT LETTER, SECTION, TO PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and rough of the compact of the operator from lease and the terms of the Operator from lease and well location. All metal bolts and other materials have been an aretrieved flow lines and pipelines. If this is a one-well lease or last rem location, except for utility's distribution in the work has been completed, return SIGNATURE	and leveled. Cathodic protection and at least 4' above ground at least 6' action at least 6	API NUMBER, QU. All INFORMATIO FACE. Ind contour and has been set in the set	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. Thave been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have been removed from non-lines have been removed from lease and we dedule an inspection. DATE 9/30/2020	ved ave
Rat hole and cellar have been filled A steel marker at least 4" in diamete OPERATOR NAME, LEASE UNIT LETTER, SECTION, T PERMANENTLY STAMPED The location has been leveled as near other production equipment. Anchors, dead men, tie downs and r If this is a one-well lease or last remocal occurrence	and leveled. Cathodic protection and at least 4' above ground	API NUMBER, QU. All INFORMATIO FACE. Ind contour and has been set in the set	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and level. Thave been remediated in compliance with action equipment and junk have been removed. (Poured onsite concrete bases do not have been removed from non-lines have been removed from lease and we dedule an inspection. DATE 9/30/2020	ved ave

PRIMERO OPERATING, INC.

PO Box 1433, Roswell, NM 88202-1433 575 622 1001

HOBBS OCD

OCT 1 2020

9/30/2020

RECEIVED

Targa/Versado Gas Processers, LLC 811 Louisiana St. Suite 2100 Houston, Tx 77002

Re:

Your Meter #1150, asset #146

Primero Operating, Inc.

C.L. O'Brien #1

Section 7, T8S, R28E; 660' FN & EL

Chaves County, NM

Gentlemen:

Primero Operating, Inc. has plugged and abandoned the subject well. We hereby request that you remove your meter #1150 at your earliest convenience. If you have any questions please give me a call at 575 626 7660.

Thank You

Phelps White

President