

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised March 25, 1999

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240
DISTRICT II
811 South First, Artesia NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410
DISTRICT IV
2040 South Pacheco, Sante Fe, NM 87505

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02093
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 8015

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other INJECTOR	7. Lease Name or Unit Agreement Name Bridges State
2. Name of Operator Mobil Producing TX. & N.M. Inc.	8. Well No. 47
3. Address of Operator P.O. Box 4358 Houston TX 77210-4358	9. Pool name or Wildcat Vacuum; Grayburg-San Andres
4. Well Location Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line Section 24 Township 17S Range 34E NMPH Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Temporary abandon <input checked="" type="checkbox"/>


12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion)

10/21/02 Road rig to location, hold safety meeting. RU well service unit, NU BOP. SION

10/22/02 Held 5 minute safety meeting. Inspect rig, test H2S monitor. Circulate well, pull tubing slowly. Lay down packer. RU Wireline, run gauge ring, lay down gauge ring. PU CIBP, set at 4010'. Drop 2 bags cement on top of plug. RD Wireline, RIH with tubing. SION

10/23/02 Held 5 minute safety meeting. Inspect rig, check H2S monitor. Finish RIH with tubing. RU pump truck, L & T plug to 500 PSI OK. Circulate well, ND BOP. RD pulling unit. Moved off.

08/05/03 Ran MIT chart for Temporary abandonment status. Test witnessed by NMOCD representative John Robinson.



This Approval of Temporary Abandonment Expires 8/12/08

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tiffany A. Stebbins TITLE Staff Office Assistant DATE 08/11/2003


TYPE OR PRINT NAME Tiffany A. Stebbins TELEPHONE NO. (281) 654-1936

(This space for State Use)

APPROVED BY Lance W. Ward TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE AUG 12 2003

CONDITIONS OF APPROVAL IF ANY:

Permits
AUG 11 2003



AUG 2003
RECEIVED
Hobbs
OCD

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31